

22/03/2003

ASS. REC. BY:

REF: CS/CT219018806/ Eyf3⁵²

Special Instruction:

samuel. auburn

Auto

y mail.

com

Surveyor

ASSIGNMENT (Office)

From (Person):

Elaine Chung

of

CT1

Date/Time: 23.10.19 15.19 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6504D

Insured:

YP 2037B

Tel:

97875558

at Workshop m/s

Auburn Auto

of

176 Sin Ming Drive #104-1g

Policy No:

DMCVSN/16338518000

Claim No:

SM191204950C02

Sum Insured:

Excess:

D.O.A. 16.10.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 23.10.19 3.32p.m

Person Contacted:

Sam

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 6504D X
	YP 2037B - CI / TPD 18010474 ZC DOA - 11/10/2019
29/10/19	Pending Estimate


Surveyor *Steve*

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



Veh No: *SLJ 65040* Yr Regn: *20/12/16*
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Mazda 3* c.c. *1496*
 Colour: *Blue* A/C: Insured / Std / NI / NA
 Sp. Reading: *206338* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 CiNo: *JM 6BN 22A8H 0124529*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *205/60R16*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <i>5</i>	mm	R/Bal. <i>5</i>	mm
L/Bal. <i>5</i>	mm	L/Bal. <i>5</i>	mm
D.O.A. <i>16/10/19</i>		D.O.I. <i>24/10/19</i>	

Survey held at *Ayburn*
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR. Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

9/12/19 MV-61K
L/S \$3400/- (Red \$21,177-00, 86%)

RECEIVED 13 DEC 2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

)

TOTAL

Date/Time, File Return to?

12/12/19 Typist

Report Format :

Lump Sum / I.B.I. (\$) *\$3400/-*

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019		23 Oct 2019 15:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: ONESTO LEASING PTE LTD, Co. Reg. No.: 201814843R									
Vehicle Reg. No.:		SLJ6504D	Date of Loss:	16/10/2019 19:00 - :59					
Claim Type:		TP / SNM19D204950C02	Policy/Cover Note No.:	DMCVSN18338518000					
Vehicle Reg. No. (Insured):		YP2037B	Policy No. (Claimant):	5101550542 (CLASSIC)					
			Excess:	S\$1,500.00					
Repairer: Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, December 12, 2019 6:21 PM
To: Sam Ng
Cc: SUR
Subject: RE: VEHICLE NO: SLT6504D DOA: 16/10/2019

Hi Sam

Confirm L/S \$3400.00 @ 5 repair days.

Kindly send final invoice and all supporting documents directly to CHINA TAIPING INSURANCE.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Ng [mailto:samuel.auburnauto@gmail.com]
Sent: Tuesday, December 10, 2019 10:10 AM
To: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: VEHICLE NO: SLT6504D DOA: 16/10/2019

Hi Yvonne,

The company decided to proceed with the settlement. Kindly revert to the relevant personal.

with regards
Sam
Auburn Auto Pte Ltd
+65 9787 5558

On Mon, 9 Dec 2019 at 10:24, Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com> wrote:

Morning Samuel

Please confirm L/S \$3400.00 @ 5 days repairs.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/10/2019 14:22
Date Of Accident	16/10/2019 19:30
Exact Location Of Accident	EXIT SLE AT WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ6504D
Insured/Policyholder	
Name Of Registered Owner	ONESTO LEASING PTE LTD
Co Reg No	201814843R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97875558
Alternative Phone No	OFFICE-97875558

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101550542 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	KESHIA ANTOINETTE YOW
NRIC No	S9015463Z
Date Of Birth	08/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2016
Driving Experience	2 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92231265
Fax Number	
Contact Number	
EMail Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1


Name	KESHIA ANTOINETTE YOW
Approximate Age	29
Injuries Sustain	NECK AND BACK INJURY
Injured person in which vehicle?	SLJ6504D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 99 OLD AIRPORT ROAD #04-187
Postcode	390099

Sketch Plan #2 Pg. 1

A - SL765040

B - YF 20378

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/10/2019 at 19:30, I was driving along SLE trying to exit Woodland Ave 12 Exit. Car B Bang into my rear while I was trying to exit the express way. We came down & exchange contact & I felt my neck hurts & I went to see a doctor after that Car B also wrote a acknowledgement stating he was at fault.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



GIAR No: Sketch Plan 001, 1/2

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

NG WING KIN JAMES

admin.vac@vicom.com.sg

17 OCT 2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	843R
Vehicle Details	
Vehicle No.:	SLJ6504D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520407995
Chassis No.:	JM6BN22A8H0124529
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,037.00
Original Registration Date:	20 Dec 2016
First Registration Date:	20 Dec 2016
Transfer Count:	2
Actual ARF Paid:	\$12,037.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2026
PARF Rebate Amount:	\$9,027.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$36,833.00
Total Rebate Amount:	\$45,860.00

The information contained herein is correct as at 24 Oct 2019

OK

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SLJ6504D

Model: MAZDA3

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear Tailgate X <i>NN</i>	\$ 1,210.00
1	Rear Taillamp (<i>RH</i>) ? / <i>BR</i>	\$ 1,200.00 <i>849 /</i>
1	Rear Tailgate Lamp X <i>NN</i>	\$ 420.00
1	Rear Tailgate Locking Mechanism X <i>NN</i>	\$ 620.00
1	Rear Bumper / <i>CRH</i>	\$ 1,530.00 <i>1075 /</i>
1	Rear Bumper Side Retainers (<i>RH</i>) / <i>BR</i>	\$ 650.00 <i>92 /</i>
1	Bumper Sensor X <i>NN</i>	\$ 320.00
1	Rear Bumper Reflectors (<i>RH</i>) <i>2</i> / <i>BR</i>	\$ 220.00 <i>51 /</i>
1	Rear Bumper Top Step Garnish X <i>NN</i>	\$ 320.00
1	Rear End Panel X <i>NN</i>	\$ 2,200.00
1	Rear End Panel Inner Garnish X <i>NN</i>	\$ 580.00
1	Rear Boot Garnish X <i>NN</i>	\$ 780.00
1	Hydraulic Hinge X <i>NN</i>	\$ 350.00
2	Rubber Moulding X <i>NN</i>	\$ 120.00
1	Number Plate & Car plate Holder X <i>NN</i>	\$ 220.00
1	Rear Exhaust X <i>NN</i>	\$ 1,800.00
1	Rear Reverse Camera X <i>NN</i>	\$ 320.00
1	Rear Tailgate "SKYACTIV" Emblem X <i>NN</i>	\$ 160.00
1	Private Hire Sticker & Inspection X <i>NN</i>	\$ 98.00
1	R/H Fender Inner Trim <i>2</i> / (<i>Fwd</i> / <i>int</i> / <i>trk</i>) / <i>BR</i>	\$ 972.00 <i>146 /</i>
1	L/H Fender Inner Trm <i>2</i> X <i>NN</i>	\$ 972.00
1	Tailgate Outer Garnish X <i>NN</i>	\$ 340.00
1	R/H Rear Door (<i>Repr RH fender</i>) / <i>00</i>	\$ 932.00 <i>/</i>
1	Front Right Door X <i>NN</i>	\$ 982.00
1	Rear Inner Bumper Enforcement X <i>NN</i>	\$ 668.00
1	Rear Inner Bumper Trim X <i>NN</i>	\$ 550.00
1	Rear Inner Garnish X <i>NN</i>	\$ 580.00
2	R/H Rims X <i>NN</i>	\$ 763.00
		\$ 19,877.00

c/f: \$

\$

19,877.00

Special Nett Items

AMT \$

1	Rear Windscreen Sealant	/ n/c	\$	120.00	40 /
1	Back bumper clip	/ n/c	\$	150.00	30 /
1	Rear Reverse Sensor (1 set)	X N/N	\$	620.00	
			\$	890.00	70

S/N.

Labour Charges

1	Refit rear windscreen		\$	300.00	120
2	Remove and refit rear tailgate		\$	300.00	X
3	Remove and refit rear bumper		\$	300.00	200
4	Remove and Refit Rear Panel Rear RH fender		\$	800.00	600
5	Remove, refit and replaced damage lamps and check up rear electrical wiring		\$	150.00	30
6	Remove and refit inner garnishes trim to assist repair		\$	200.00	50
7	Remove and refit rear reverse sensor		\$	240.00	50
8	To apply undercoating on replaced panel		\$	120.00	30
9	To Respray Painting.		\$	1,400.00	600

 \$ 3,810.00
GRAND TOTAL

 \$ 24,577.00

1660

p- 2516
 NI- 70
 L- 1660
 4246
 L/S- 3396.80
 = 3400

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8322 8813
(Email) _____
(Signature) _____
(Date/Time) 24/10/19, 10.30am

[Handwritten signature]
28/11/19

WHL Paul

52 dy

L/S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019		23 Oct 2019 15:19 Edit Adj Rpt	S\$3,400.00 Edit Estimates	S\$3,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured: -, Co. Reg. No.: -	
Main Claimant: ONESTO LEASING PTE LTD , Co. Reg. No.: 201814843R	
Vehicle Reg. No.: SLJ6504D	Date of Loss: 16/10/2019 19:00 - :59 [33 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / SNM19D204950C02	Policy/Cover Note No.: DMCVSN18338518000
Vehicle Reg. No. (Insured): YP2037B	Policy No. (Claimant): 5101550542 (CLASSIC)
	Excess: S\$1,500.00
Repairer: Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]	
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/11/2019]	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ6504D (SNM19D204950C02)**
[YP2037B]

TP

ONESTO LEASING PTE LTD

Oct 16 2019 7:00PM

[-]

Auburn Auto Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images

3 per page ▼ ☒

No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	17/10/19 14:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/19 18:25	General View	1	Load JPG	☒
2	12/12/19 18:25	General View	1	Load JPG	☒
3	12/12/19 18:25	General View	1	Load JPG	☒
4	12/12/19 18:25	General View	1	Load JPG	☒
5	12/12/19 18:25	General View	1	Load JPG	☒
6	12/12/19 18:25	General View	1	Load JPG	☒
7	12/12/19 18:25	General View	1	Load JPG	☒
8	12/12/19 18:25	General View	1	Load JPG	☒
9	12/12/19 18:25	General View	1	Load JPG	☒
10	12/12/19 18:25	General View	1	Load JPG	☒
11	12/12/19 18:25	General View	1	Load JPG	☒
12	12/12/19 18:25	General View	1	Load JPG	☒
13	12/12/19 18:25	General View	1	Load JPG	☒
14	12/12/19 18:25	General View	1	Load JPG	☒
15	12/12/19 18:25	General View	1	Load JPG	☒
16	12/12/19 18:25	General View	1	Load JPG	☒
17	12/12/19 18:25	General View	1	Load JPG	☒
18	12/12/19 18:25	General View	1	Load JPG	☒
19	12/12/19 18:25	General View	1	Load JPG	☒
20	12/12/19 18:25	General View	1	Load JPG	☒
21	12/12/19 18:25	General View	1	Load JPG	☒
22	12/12/19 18:25	General View	1	Load JPG	☒
23	12/12/19 18:25	General View	1	Load JPG	☒
24	12/12/19 18:25	General View	1	Load JPG	☒
25	12/12/19 18:25	General View	1	Load JPG	☒
26	12/12/19 18:25	General View	1	Load JPG	☒
27	12/12/19 18:25	General View	1	Load JPG	☒
28	12/12/19 18:25	General View	1	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
29	12/12/19 18:25	General View	 Load JPG	☒
30	12/12/19 18:25	General View	 Load JPG	☒
31	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
32	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
33	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
34	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
35	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
36	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
37	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
38	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
39	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
40	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
41	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
42	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
43	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
44	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
45	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
46	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
47	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
48	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
49	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
50	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
51	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
52	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
53	12/12/19 18:26	Reinspection Photo	 Load JPG	☒
54	12/12/19 18:26	Reinspection Photo	 Load JPG	☒

Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/19 15:20	PRS - SLJ6504D	 Load PDF	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	17/10/19 14:33	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	17/10/19 14:33	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	17/10/19 14:33	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	17/10/19 14:33	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	
5	17/10/19 14:33	Sketch Plan #5 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	06/12/19 19:05	Accident Statement	 Load HTM	
2	06/12/19 19:06	Accident Statement	 Load HTM	
3	06/12/19 19:08	Accident Statement	 Load HTM	
4	06/12/19 19:10	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	17/10/19 14:32	Accident Photo	 Load JPG	☒
2	17/10/19 14:32	Accident Photo	 Load JPG	☒
3	17/10/19 14:32	Accident Photo	 Load JPG	☒
4	17/10/19 14:32	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page ▾	✓
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
5	17/10/19 14:32	Accident Photo	 Load JPG	✓
6	17/10/19 14:32	Accident Photo	 Load JPG	✓
7	17/10/19 14:32	Accident Photo	 Load JPG	✓
8	17/10/19 14:32	Accident Photo	 Load JPG	✓
9	17/10/19 14:32	Accident Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	17/10/19 14:33	Sketch Plan	 Load TIF	
2	17/10/19 14:33	Sketch Plan #2	 Load TIF	
3	17/10/19 14:33	Sketch Plan #3	 Load TIF	
4	17/10/19 14:33	Sketch Plan #4	 Load TIF	
5	17/10/19 14:33	Sketch Plan #5	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018806/EYF3S2

Date: 06/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN18338518000

Claimant Vehicle No: SLJ6504D Insured Vehicle No: YP2037B

Date of Loss: 16/10/2019 Nature of Claim: TP Claim No: SNM19D204950C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ6504D

Make & Model: MAZDA 3, 1.5 SEDAN L SP (A) Engine No: P520407995

Reg. Date: 20/12/2016 (Man. Year: 2016) Chassis No: JM6BN22A8H0124529

Colour: Blue Odometer: 206338 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,767.00	2,586.00	18,181.00	87.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,680.00	2,130.00	55.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,577.00	4,266.00	20,311.00	82.64
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	24,577.00	3,400.00	21,177.00	86.17

INSPECTION

Date of Assignment: 23/10/2019

Date Inspected: 24/10/2019 Inspected At:

Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2020)
Parts:	143	MAZDA 3 1.5 SEDAN L SP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ6504D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	1,210.00 F	*- FL
2	1		*REAR TAILLAMP (RH)	Broken	1,200.00 F	*849.00 FL
3	1		*REAR TAILGATE LAMP	Not Necessary	420.00 F	*- FL
4	1		*REAR TAILGATE LOCKING MECHANISM	Not Necessary	620.00 F	*- FL
5	1		*REAR BUMPER	Crushed	1,530.00 F	*1,075.00 FL
6	1		*REAR BUMPER SIDE RETAINER (RH)	Broken	650.00 F	*92.00 FL
7	1		*BUMPER SENSOR	Not Necessary	320.00 F	*- FL
8	1		*REAR BUMPER REFLECTORS (RH)	Broken	220.00 F	*51.00 FL
9	1		*REAR BUMPER TOP STEP GARNISH	Not Necessary	320.00 F	*- FL
10	1		*REAR END PANEL	Not Necessary	2,200.00 F	*- FL
11	1		*REAR END PANEL INNER GARNISH	Not Necessary	580.00 F	*- FL
12	1		*REAR BOOT GARNISH	Not Necessary	780.00 F	*- FL
13	1		*HYDRAULIC HINGE	Not Necessary	350.00 F	*- FL
14	2		*RUBBER MOULDING	Not Necessary	120.00 F	*- FL
15	1		*NUMBER PLATE & CAR PLATE HOLDER	Not Necessary	220.00 F	*- FL
16	1		*REAR EXHAUST	Not Necessary	1,800.00 F	*- FL
17	1		*REAR REVERSE CAMERA	Not Necessary	320.00 F	*- FL
18	1		*REAR TAILGATE SKYACTIV EMBLEM	Not Necessary	160.00 F	*- FL
19	1		*PRIVATE HIRE STICKER & INSPECTION	Not Necessary	98.00 F	*- FL
20	1		*R/H FENDER INNER TRIM	Broken	972.00 F	*146.00 FL
21	1		*L/H FENDER INNER TRIM	Not Necessary	972.00 F	*- FL
22	1		*TAILGATE OUTER GARNISH	Not Necessary	340.00 F	*- FL
23	1		*R/H REAR DOOR (REAR RH FENDER)	Dented	932.00 F	*932.00 FL
24	1		*FRONT RIGHT DOOR	Not Necessary	982.00 F	*- FL
25	1		*REAR INNER BUMPER ENFORCEMENT	Not Necessary	668.00 F	*- FL
26	1		*REAR INNER BUMPER TRIM	Not Necessary	550.00 F	*- FL
27	1		*REAR INNER GARNISH	Not Necessary	580.00 F	*- FL
28	2		*R/H RIMS	Not Necessary	763.00 F	*- FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
30	1		*BACK BUMPER CLIP	Necessary	150.00 FS	*30.00 FS
31	1		*SET EAR REVERSE SENSOR	Not Necessary	620.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	20,767.00	3,215.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	629.00
Total Parts (\$\$)	20,767.00	2,586.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REFIT REAR WINDSCREEN.	New	300.00	120.00
2	REMOVE AND REFIT REAR TAILGATE.	New	300.00	0.00
3	REMOVE AND REFIT REAR BUMPER.	New	300.00	200.00
4	REMOVE AND REFIT REAR RH FENDER.	New	800.00	600.00
5	REMOVE, REFIT AND REPLACED DAMAGE LAMPS AND CHECK UP ELECTRICAL WIRING.	New	150.00	30.00
6	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR.	New	200.00	50.00
7	REMOVE AND REFIT REAR REVERSE SENSOR.	New	240.00	50.00
8	TO APPLY UNDERCOATING ON REPLACED PANEL.	New	120.00	30.00
9	TO RESPRAY PAINTING.	New	1,400.00	600.00
Gross Labour Cost (\$\$)			3,810.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >