

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC3387D

DATE: 22. Oct. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 21. Oct. 2019

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$553.00
10	Rear Bumper Clips ✓		\$2.20	\$22.00
1	Rear Bumper Sponge ?			\$103.50
1	Rear Bumper Reinforcement ?			\$428.40
1	Rear Bumper Undercover x			\$228.00
1	Rear Panel x repair			\$592.30
1	Rear panel Garnish x			\$57.70
1	Rear panel Lower Garnish x repair			\$495.50
1	Boot Lid ✓			\$2,174.90
1	Boot Lid i40 emblem ✓			\$27.90
1	Boot Lid CRDI emblem ✓			\$27.90
1	Boot Lid H emblem ✓			\$28.70
1	Boot Lid Lower Garnish x repair			\$227.90
SUB TOTAL				\$4,967.70
LESS 20%				\$993.54
DISCOUNTED TOTAL				\$3,974.16
1	ComfortDelgro Sticker ✓			\$15.00
1	Comfort Tel No. ✓			\$15.00
1	Rear Bumper Rubber Mat ✓			\$50.00
1	Reverse Sensor ✓			\$135.70
Labour Charge				\$215.70
1	Panel Beating			\$840.00
1	Spray Painting Charge			\$600.00
1	Tuff Kote			\$80.00
1	Wiring Charge			\$60.00
1	Remove/refix Reverse Sensor			\$120.00
TOTAL LABOUR				\$1,700.00
ESTIMATE TOTAL				\$5,889.86
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *Kahin 1/10/19*

Date: *24/10/19*

3 Days

U/S

After Repair p/Lt

Nett

Nett

Nett

Nett

Larry Ng