

22/03/2002

ASS. REC. BY

REF:

CS/SPF/9018816/Qy d3eb

Special Instruction:

Surveyor:

Sun Pin

ASSIGNMENT (Office)

From (Person):

Hafizul Furhan

of

SPF

Date/Time:

23/10/19 2:20pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SYM 3027S

Insured:

QX 565J

at Workshop m/s

Hua Peng Auto

Tel:

9688 5655

of

70 woodlands Ind. park Eg

Fax 6365 6101

Policy No:

Claim No:

AEMB/105/1009/2019/103

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:18pm 23/10/19

Person Contacted:

Mr. Eric

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

Do Not Finalise

ASS. REG. BY: Sun PmREF: SPF

ASSIGNMENT

From:

Date:

24/10/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJM 30275

at Workshop m/s

Hua Peng Auto

of

70 woodlands Ind. Park E9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJM 30275

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C.

1498

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

142424

T/Radio:

Insured / Std / NI / NA

Eng/No:

-

C/No:

MR053HY9305094222Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

195/55 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodyear

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

24/10/2019

Survey held at

Hua PengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV:

L / S \$1650 (Red \$3360-43, 67%)13/11/2019

RECEIVED 15 NOV 2019

Upper Rung \$1,650 - \$2,000From 24/oct/2019, R/D 2days, have one weekend.

Do Not Finalise

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

14/11/19 Typist

Days Of Repair:

2 + 1 weekends

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L&B: (\$

\$1650/-)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Wednesday, 23 October 2019 2:20 PM
To: Admin-D (LKKAuto); SUR; assignments
Cc: Frankie THAY (SPF); Cui Fen ENG (SPF)
Subject: Pre-repair Survey of SJM 3027S (vs QX565J on 26/6/2019)

Our ref: AEMD/105/009/2019/103

Hi,

Kindly conduct pre-repair survey of **SJM 3027S (vs QX565J, DOA on 26/6/2019)**

Hua Peng Auto
70 Woodlands Industrial Park E9
Singapore 757836
Contact person: Mr Eng, HP: 96885655 / 68531773

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

Vimalarani D/O Marimuthu
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SJM3027S
Make And Model : Toyota Vios E
Date of Accident : 26 June 2019

S/No	Parts	QTY	Unit Price	List Price
1	Front door (R/H) $\times R$	1	\$	899.20 $\times$
2	Front door lock (R/H) $\times SVC$	1	\$	235.50 $\times$
3	Front door protector (R/H) $\times / SCR$	1	\$	100.70 $\times$
4	Front door protector chrome moulding (R/H) $\times / SCR$	1	\$	40.70 $\times$
5	Front door frame black sticker (R/H) $\times SVC$	1	\$	41.20 $\times$
6	Rear door (R/H) $\times / DD$	1	\$	862.90 $\times$
7	Rear door protector (R/H) $\times / SCR$	1	\$	100.70 $\times$
8	Rear door protector chrome moulding (R/H) $\times / SCR$	1	\$	40.70 $\times$
9	Rear door frame black sticker (R/H) $\times SVC$	1	\$	41.20 $\times$
10	Rocker panel garnish (R/H) $\times SVC$	1	\$	321.90 $\times$
11	Wing mirror assy (R/H) $\times SVC$	1	\$	1,089.20 $\times$
				\$ 3,773.90
Less 25%				\$ 943.48
Total				\$ 2,830.43

Special Nett Item

12	Door inner trimboard clips	2 sets 1 set net	\$	120.00 $\times 35$
13	Rocker panel garnish clips RH $\times NN$		\$	60.00 $\times$
Total				\$ 180.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts.	\$	800.00 $\times 500$
To spray paint on affected areas.	\$	800.00 $\times 550$
To apply anti-rust on affected areas.	\$	100.00 $\times$
To remove/refit front & rear door mechanism.	\$	200.00 $\times 80$
To check wiring for rear portion. (door)	\$	100.00 $\times 30$
Total		\$ 2,000.00

LKK Auto Consultants hence notify the Repairer of the following:
Grand Total : \$ 5,010.43

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sun Pin.

TP without Prejudice.

24/10/2019

Lump-Sum Repair

After spray photo.

Repair day - 3 days

L/S = 1650



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19018816/Qyd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN : HAFIZUL FARHAN			Date : 27-11-2019	
			Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 565J	Veh. Inspected	SJM 3027S	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/103	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	23/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1498	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR053HY9305094222	Colour	WHITE	
Odometer	142424	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	GOODYEAR	5 mm	
L/H Front Tyre	195/55 R15	GOODYEAR	5 mm	
R/H Rear Tyre	195/55 R15	GOODYEAR	5 mm	
L/H Rear Tyre	195/55 R15	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2019	Inspection Date	24/10/2019	
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 3027S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR (R/H)	TO REPAIR SEE LABOUR	899.20	-
1	FRONT DOOR LOCK (R/H)	SERVICEABLE	235.50	-
1	FRONT DOOR PROTECTOR (R/H)	SCRATCHED	100.70	100.70
1	FRONT DOOR PROTECTOR CHROME MOULDING (R/H)	SCRATCHED	40.70	40.70
1	FRONT DOOR FRAME BLACK STICKER (R/H)	SERVICEABLE	41.20	-
1	REAR DOOR (R/H)	DENTED	862.90	862.90
1	REAR DOOR PROTECTOR (R/H)	SCRATCHED	100.70	100.70
1	REAR DOOR PROTECTOR CHROME MOULDING (R/H)	SCRATCHED	40.70	40.70
1	REAR DOOR FRAME BLACK STICKER (R/H)	SERVICEABLE	41.20	-
1	ROCKER PANEL GARNISH (R/H)	SERVICEABLE	321.90	-
1	WING MIRROR ASSY (R/H)	SERVICEABLE	1,089.20	-
	LESS 25% DISCOUNT		-943.48	-286.43
			2,830.42	859.27
SPECIAL NETT ITEMS				
2	SETS DOOR INNER TRIMBOARD CLIPS (SN)	NECESSARY (1 SET ONLY)	120.00	35.00
1	ROCKER PANEL GARNISH CLIPS RH (SN)	NOT NECESSARY	60.00	-
			180.00	35.00
LABOUR				
	TO DISMANTLE, REPLACE & PANEL BEATING AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR (R/H).		800.00	500.00
	TO SPRAY PAINT ON AFFECTED AREAS.		800.00	550.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REMOVE / REFIT FRONT & REAR DOOR MECHANISM.		200.00	80.00
	TO CHECK WIRING FOR REAR PORTION. (DOOR)		100.00	30.00
			2,000.00	1,160.00
GRAND TOTAL			5,010.42	2,054.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/SPF19018816/Qyd3e2



Report Ref No. CS/SPF19018816/Qyd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,650-\$2,000

RECOMMENDED REPAIR DAYS : 2

WEEKEND : 1

TOTAL DAYS : 3

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.