

ASS. REC. BY:

REF:

C</MSG#018322/AGrf3

Special Instructions:

Surveyor Adrian

ASSIGNMENT (Office)

From (Person): Pauline Tham

of MSG

Date/Time: 23.10.19 16.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGM 1028m

Insured: SGR 6720m

at Workshop no: Liang Hu motor

Tel: 6747 4416

of 1 lanki Bukit Ar 6 401 62

Policy No: 1000906989

Claim No: 232462

Sum Insured:

Excess:

Make of Vely:

D.O.A 19.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

Date/Time: 23.10.19 4.36pm

Person Contacted: David

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGM 1028m - N/A A/G 12024523/52 D.O.A - 20/12/2012
	SGR 6720m - X
24/10/19	Informed Pauline pending workshop est by merimen
14/1/2020	Adrian confirmed LS \$5500 (Red 8050.70, 5910)
14/1/20	Send preli revised via merimen

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2019 16:21		23 Oct 2019 16:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	NG KUAN SIANG, ID: S7935193H, Tel: +6597339021								
Main Claimant:	SNG BEE CHOO, ID: S1414659H								
Vehicle Reg. No.:	SGM1028M	Date of Loss:	19/10/2019 09:00 - :59 [61 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 232462	Policy/Cover Note No.:	1000906989 (Comprehensive) Coverage: 13/02/2019 - 12/02/2020						
Vehicle Reg. No. (Insured):	SGR6720M	Policy No. (Claimant):	MP310840						
		Excess:	S\$0.00						
Repairer:	Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2019]								
Driver/Custodian (Insured):	NG KUAN SIANG (39 / Male), NRIC: S7935193H, Tel: +6597339021 Email:								
Adj Asg. Remarks:	on WP. Liab: clear, Agree on SJE. Assign: Adrian Ling from LKK Auto Consultants Pte Ltd, Contact: David @ 9752 7252 / 6747 4416.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone: (65) 6536 9339, Fax: (65) 6536 5368

Email: claims@juseq.com.sg

web site: www.juseq.com.sg

Our Ref: JEQ/191098/1019/ LHEE

Your Ref: **SGR6720M**

22 October 2019

NG KUAN SIANG
35 PUNGGOL FIELD #12-27
SINGAPORE 828818

By Post Only

MSIG Insurance (Singapore) Pte Ltd
Singapore

By Fax: 6225 7402 &
motorsurvey@sg.msig-asia.com

Dear Sir

ACCIDENT INVOLVING SGM1028M & SGR6720M ON 19-10-2019

We act for the owner of vehicle no. SGM1028M.

We hereby notify you of a road traffic accident on **19 October 2019** at about **1040 hrs**, at CTE exit involving our client's vehicle and vehicle registration no. **SGR6720M** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Pauline Tham	Date:	14 Jan 2020
<u>Preliminary Advice</u>			

Insured Vehicle No	: SGR6720M	Accident Date	: 19/10/2019
TP Vehicle No	: SGM1028M	Assignment Date	: 23/10/2019
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 6
Date of Inspection	: 23/10/2019		
Inspection At	: LIANG HEE MOTOR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,550.70
Revised Amount	:S\$	5,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,500.00
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐	The vehicle is economical/not economical for repair.
☒	The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SGM1028M (232462)**
[SGR6720M]

TP
SNG BEE CHOO
Oct 19 2019 9:00AM
[NG KUAN SIANG]
Liang Hee Motor Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **24/10/2019 10:11 AM**,
To SGSGPAUT
Subject TP SURVEY SGM 1028M

Dear Pauline,

Please be informed that we have inspected the vehicle SGM 1028M on 23/10/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	659H
Vehicle Information	
Vehicle No.:	SGM1028M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	2ARU160139
Chassis No.:	MR053AK5004008133
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$27,861.00
Original Registration Date:	19 Sep 2014
First Registration Date:	19 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$31,006.00
PARF Eligibility Information	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2024
PARF Rebate Amount:	\$21,704.00
COE Information	
COE Expiry Date:	18 Sep 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,990.00
COE Rebate Amount:	\$35,290.00
Total Rebate Amount:	\$56,994.00

The information contained herein is correct as at 24 Oct 2019

OK



Republic Auto | CERTIFIED PRE-OWNED
MERCEDES BENZ



VIEW OUR CARS

20 results/page

[View All](#)

20 results/page

NSME1210250 / SNE Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 21/10/2019 18:15
SUBMITTED BY: Che Pw Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Data Of Report	21/10/2019 16:15
Date Of Accident	19/10/2019 10:40
Exact Location Of Accident	GTE EXIT 10 BEFORE LORONG CHUAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM1028M
Insured/Policyholder	
Name Of Registered Owner	SNG BEE CHOO
NRIC No	S1414650H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97243228
Alternative Phone No	OFFICE-97243228

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Particulars

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP310840
Cover Note Number	

Driver

Name of Driver	JIMMY NG PENG SENG
NRIC No	S1132103H
Date Of Birth	07/05/1955
Occupation	INDOOR
Date Of Driving Pass	18/06/1976
Driving Experience	43 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98274488
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 776 YISHUN AVE 2 #10-1598
 Postcode 2776
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: SNG BEE CHOO
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of the Accident

ON 19/10/2019, I WAS TRAVELLING ALONG CTE TOWARDS PIE AROUND 10.30AM. SOMEWHERE NEAR EXIT 10, THE CAR IN FRONT OF ME STOPPED AND I FOLLOWED AND STOPPED TOO. SUDDENLY, THERE WAS A LOUD BANG BEHIND MY CAR. THE IMPACT WAS SO GREAT, I GOT A SHOCK AND CAME OUT TO INVESTIGATE. I SAW THE BACK OF MY CAR WAS BADLY DAMAGED BY VEHICLE (SGR6720M). THE DRIVER WHO CAME OUT AND HE ACKNOWLEDGE HIS FAULT. WE EXCHANGED PARTICULARS AND TOOK PICTURE OF THE DAMAGED VEHICLE. THE DRIVER OF (SGE6720M) ASKED ME TO PROCEED WITH THE CLAIM AGAINST HIS INSURANCE. ABOUT NOON, I FELT MY NECK AND BACK PAIN. I WENT TO THE NEARBY CLINIC AT MY PLACE FOR CONSULTATION AND WAS GIVEN 2 DAYS MC AND MEDICATION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGR6720M
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver NG KUAN SIANG
 NRIC/Passport Number
 Contact Number 97339021
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

JIMMY NG PENG SENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGM1028M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Record Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information as collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIH No.:

CLARK HBB

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19 Oct 2019, I was travelling along CTE towards PIE around 10:30 am. Somewhere near Exit 10, the car in front of me stopped and I followed and stopped too. However, the vehicle behind suddenly, there was a loud bang behind my car. The impact was very great. I got a shock and came out to investigate. I saw the back of my car was badly damaged by Vehicle No. SGR 6720 M. The driver who came out and he acknowledged his fault. We exchanged particulars and took pictures of the damaged vehicles. The driver of Vehicle No. SGR 6720 M asked me to provide with the claim against his insurance. About now, I felt my neck and back pain. I went to the nearby clinic at my place for consultation and was given 2 days rest & medication.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time:

[Signature]
Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/PPN No.:

LIANGHEEMOTOR 55

TPMS19

Veron

SGM1028M

Toyota Camry

2484

MROS3AK5004008133

Rear Bumper Distorted

Rear Bumper Clips new

Rear Bumper Side Holder x 02 new

Rear Bumper Reflector x 02 new

Rear Bumper Reinforcement Best

Reverse Sensor x 04. 2 pieces damaged

Rear End Panel Distorted

Rear End Panel Top Garnish Rebound

Rear End Panel Sealant. new

Trunk x 02 crushed

Trunk Panel x 02 Repairs

Bootlid Buckled.

Bootlid Lock Damaged

Bootlid Lock Antenna. crushed.

Bootlid Weatherstripe. lit

Bootlid Lamp x 02 new

Bootlid Chrome Moulding. new

Bootlid Hinge x 02 Not Nec

Spore Tyre Panel Top Board new

LKK Auto Consultants hereby notify the Repairer of the following:

- To repairer, who is not solely causing
- To repairer, who is not solely causing
- Parts and work subject to no warranty
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be received and is subject to final approval by Insurance Company

Acknowledged by Repairer

Signature:

Date:

289.60

30

35.2 x 2 = 70.40 ✓

69.2 x 2 = 138.40 x

391.80 ✓

225 x 4 = 900. 450

587.20 ✓

295.40 ✓

60 (SW) ✓

447.7 x 2 = 895.40 ✓

281.10 x 2 = 562.20 x

927.90 ✓

355.10 ✓

89.40 ✓

285.70 ✓

354.2 x 2 = 708.40 x

374.50 x

182.1 x 2 = 364.20 x

374.50 x

86M1028M

Spare Tyre Panel Undercover	Deband	368.90	—
Spare Tyre Panel Undercover Clips	in	30	—
Spare Tyre Panel Centre Sponge	Grubd	386.30	✓
Spare Tyre Panel Side Sponge x 02	Grubd	200.9 x 2 = 401.80	—
Rear Exhaust Pipe	Not in	876.70	+
Rear Exhaust Mounting	Not in	45.20	+
Toyota Logo	Not in	80.40	+
Carry wording	} in	65.40	—
2 S wording		45.90	—
Panel Beating		1200	1000
Spray Painting		1200	800
Wiring		50	30
To underseal		150	60
To remove reverse sensor		100	60
To remove upholstery		150	60
To transfer bootlid fittings		150	80
To remove exhaust pipe		150	+
To remove rear camera		100	50

13,550.70

list 6266.50

less 25% 4699.87

SN 60

Labour 2140

total: 6899.87

L/S SSK 06 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2019 16:21		23 Oct 2019 16:20 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG KUAN SIANG , ID: S7935193H, Tel: +6597339021									
Main Claimant: SNG BEE CHOO , ID: S1414659H									
Vehicle Reg. No.: SGM1028M		Date of Loss: 19/10/2019 09:00 - :59 [61 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / 232462		Policy/Cover Note No.: 1000906989 (Comprehensive) Coverage: 13/02/2019 - 12/02/2020							
Vehicle Reg. No. (Insured): SGR6720M		Policy No. (Claimant): MP310840							
		Excess: S\$0.00							
Repairer: Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 67474416									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Claimant's Insurer: HL Assurance Pte Ltd (HQ) - Tel: 69226030									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/11/2019]									
Driver/Custodian (Insured): NG KUAN SIANG (39 / Male) , NRIC: S7935193H, Tel: +6597339021 Email:									
Adj Asg. Remarks: on WP, Liab: clear. Agree on SJE. Assign: Adrian Ling from LKK Auto Consultants Pte Ltd. Contact: David @ 9752 7252 / 6747 4416.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGM1028M (232462)
[SGR6720M]
TP
SNG BEE CHOO
Oct 19 2019 9:00AM
[NG KUAN SIANG]
Liang Hee Motor Workshop

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	14/01/20 16:56	Adjuster Immediate Advice							 Load HTM			
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	14/01/20 16:22	General View							 Load JPG		☒	
2	14/01/20 16:22	General View							 Load JPG		☒	
3	14/01/20 16:22	General View							 Load JPG		☒	
4	14/01/20 16:22	General View							 Load JPG		☒	
5	14/01/20 16:22	General View							 Load JPG		☒	
6	14/01/20 16:22	General View							 Load JPG		☒	
7	14/01/20 16:22	General View							 Load JPG		☒	
8	14/01/20 16:22	General View							 Load JPG		☒	
9	14/01/20 16:22	General View							 Load JPG		☒	
10	14/01/20 16:22	General View							 Load JPG		☒	
11	14/01/20 16:22	General View							 Load JPG		☒	
12	14/01/20 16:22	General View							 Load JPG		☒	
13	14/01/20 16:22	General View							 Load JPG		☒	
14	14/01/20 16:22	General View							 Load JPG		☒	
15	14/01/20 16:22	General View							 Load JPG		☒	
16	14/01/20 16:22	General View							 Load JPG		☒	
17	14/01/20 16:22	General View							 Load JPG		☒	
18	14/01/20 16:22	General View							 Load JPG		☒	
19	14/01/20 16:22	General View							 Load JPG		☒	
20	14/01/20 16:22	General View							 Load JPG		☒	
21	14/01/20 16:22	General View							 Load JPG		☒	
22	14/01/20 16:22	General View							 Load JPG		☒	
23	14/01/20 16:22	General View							 Load JPG		☒	
24	14/01/20 16:22	General View							 Load JPG		☒	
25	14/01/20 16:22	General View							 Load JPG		☒	
26	14/01/20 16:22	General View							 Load JPG		☒	
27	14/01/20 16:22	General View							 Load JPG		☒	
28	14/01/20 16:22	General View							 Load JPG		☒	
29	14/01/20 16:22	General View							 Load JPG		☒	
30	14/01/20 16:22	General View							 Load JPG		☒	
31	14/01/20 16:22	General View							 Load JPG		☒	
32	14/01/20 16:22	General View							 Load JPG		☒	
33	14/01/20 16:22	General View							 Load JPG		☒	
34	14/01/20 16:22	General View							 Load JPG		☒	
35	14/01/20 16:22	General View							 Load JPG		☒	
36	14/01/20 16:22	General View							 Load JPG		☒	
37	14/01/20 16:22	General View							 Load JPG		☒	
38	14/01/20 16:22	General View							 Load JPG		☒	
39	14/01/20 16:22	General View							 Load JPG		☒	
40	14/01/20 16:22	General View							 Load JPG			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
42	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
43	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
44	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
45	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
46	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
47	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
48	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
49	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
50	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
51	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
52	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
53	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
54	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
55	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
56	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
57	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
58	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
59	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
60	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
61	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
62	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
63	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
64	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
65	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
66	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
67	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
68	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
69	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
70	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
71	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
72	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
73	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
74	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
75	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
76	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
77	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
78	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
79	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
80	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
81	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
82	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
83	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
84	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
85	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
86	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
87	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
88	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
89	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
90	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
91	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
92	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
93	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
94	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
95	14/01/20 16:22	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
97	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
98	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
99	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
100	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
101	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
102	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
103	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
104	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
105	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
106	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
107	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
108	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
109	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
110	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
111	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
112	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
113	14/01/20 16:22	Reinspection Photo	 Load JPG	☒
114	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
115	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
116	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
117	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
118	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
119	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
120	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
121	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
122	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
123	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
124	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
125	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
126	14/01/20 16:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/10/19 16:23	PR1	 Load PDF	
2	23/10/19 09:34	Agree on SJE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/12/19 19:10	Accident Statement	 Load HTM	
2	06/12/19 19:15	Accident Statement	 Load HTM	
3	06/12/19 19:20	Accident Statement	 Load HTM	
4	06/12/19 19:20	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	21/10/19 16:25	Accident Photo	 Load JPG	☒
2	21/10/19 16:25	Accident Photo	 Load JPG	☒
3	21/10/19 16:25	Accident Photo	 Load JPG	☒
4	21/10/19 16:25	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	21/10/19 15:22	Sketch Plan Click here & type to add comment....	 Load TIF	
2	21/10/19 15:22	Sketch Plan #2	 Load TIF	

Assessment Reports				1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
3	21/10/19 15:23	Identification Card		Load TIF	
4	21/10/19 15:23	Driving License		Load TIF	
5	21/10/19 15:23	CI		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018822/AGVF3Q2

Date: 16/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000906989

Claimant

Vehicle No : SGM1028M

Insured Vehicle No : SGR6720M

Date of Loss: 19/10/2019

Nature of Claim:

TP

Claim No: 232462

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGM1028M

Make & Model: TOYOTA CAMRY, 2.5 (A)

Engine No: 2ARU160139

Reg. Date: 19/09/2014 (Man. Year: 2014)

Chassis No: MR053AK5004008133

Colour: Grey

Odometer: 120482 km

Engine Capacity: 2494 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,300.70	4,759.65	5,541.05	53.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	2,140.00	1,110.00	34.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,550.70	6,899.65	6,651.05	49.08
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	13,550.70	5,500.00	8,050.70	59.41

INSPECTION

Date of Assignment: 23/10/2019

Date Inspected: 23/10/2019 Inspected At:

Liang Hee Motor Workshop (HQ)
1 KAKI BUKIT AVE 6 #01-62,
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2020)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM1028M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	589.60 F	*589.60 FL
2	1	*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2	*REAR BUMPER SIDE HOLDER	Necessary	70.40 F	*70.40 FL
4	2	*REAR BUMPER REFLECTOR	Not Necessary	138.40 F	*- FL
5	1	*REAR BUMPER REINFORCEMENT	Bent	391.80 F	*391.80 FL
6	4	*REVERSE SENSOR	Damaged (2 PCS ONLY)	900.00 F	*450.00 FL
7	1	*REAR END PANEL	Distorted	587.20 F	*587.20 FL
8	1	*REAR END PANEL TOP GARNISH	Deformed	295.40 F	*295.40 FL
9	1	*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
10	2	*TAILLAMP	Cracked	895.40 F	*895.40 FL
11	2	*TAILLAMP PANEL	Repair	562.20 F	*- FL
12	1	*BOOTLID	Buckled	927.90 F	*927.90 FL
13	1	*BOOTLID LOCK	Damaged	355.10 F	*355.10 FL
14	1	*BOOTLID LOCK ANTENNA	Cracked	89.40 F	*89.40 FL
15	1	*BOOTLID WEATHERSTRIPE	Cut	285.70 F	*285.70 FL
16	2	*BOOTLID LAMP	Not Necessary	708.40 F	*- FL
17	1	*BOOTLID CHROME MOULDING	Not Necessary	374.50 F	*- FL
18	2	*BOOTLID HINGE	Not Necessary	364.20 F	*- FL
19	1	*SPARE TYRE PANEL TOP BOARD	Not Necessary	374.50 F	*- FL
20	1	*SPARE TYRE PANEL UNDERCOVER	Deformed	368.90 F	*368.90 FL
21	1	*SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 F	*30.00 FL
22	1	*SPARE TYRE PANEL CENTRE SPONGE	Cracked	386.30 F	*386.30 FL
23	2	*SPARE TYRE PANEL SIDE SPONGE	Cracked	401.80 F	*401.80 FL
24	1	*REAR EXHAUST PIPE	Not Necessary	876.70 F	*- FL
25	1	*REAR EXHAUST MOUNTING	Not Necessary	45.20 F	*- FL
26	1	*TOYOTA LOGO	Not Necessary	80.40 F	*- FL
27	1	*CAMRY WORDING	Necessary	65.40 F	*65.40 FL
28	1	*2.5 WORDING	Necessary	45.90 F	*45.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,300.70 6,326.20
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,566.55

Total Parts (\$\$) 10,300.70 4,759.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	1,000.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	60.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
8	TO REMOVE EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
Gross Labour Cost (S\$)			3,250.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >