

ASS. REC. BY:

REF:

CS/MSG 19018827/kyf3

Special Instruction:

SURVEYOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Jawyn Tay Mei Ling

of

MSG

Date/Time:

23.10.19 11.17p.m

Estimated Cost:

Bill to:

OD TP AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 6017K

Insured:

SMD 2331G

at Workshop m/s

Chong Hoe

Tel:

64812001

of

BIC 1019 # 01-3741382 Yishu

Policy No:

29112616mcy

Claim No:

609149

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21.10.19

CA / REV / REP. / REV 24 HRS

Date/Time:

23.10.19 4.38p.m

Person Contacted:

Dorlyn

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMN 6017K - X

SMD 2331G - X

ASSIGNMENT

From _____ Date _____
Estimated Cost _____
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐
To inspect Vehicle No. _____
at Workshop no. *Cheng Hec*
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured _____ Excess _____
(Client's Record)
Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value _____
IDAC Accident Report _____ Consistent? Yes or No _____
GIC PH Segm _____ Consistent? Yes or No _____
Est. Repairs _____ days Res. Yes or No _____
Loss Item _____ To Total Yes or No _____

CA / REV / REP. / 24 HRS

Only _____ Person Contacted _____ Vehicle IN OUT

Veh No *SMH6017K* Yr Regn *08 19*
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *Wagon*
Make *Toy* *Alpha* cc *2494*
Colour *M. P. White* A/C Insured / Std / NI / NA
Sp. Reading *5790* Traction Insured / Std / NI / NA
Eng No _____
Chassis *JTNGF3D14 908023529*
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size F: *235/50R18*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Engl _____
R/Sw *9* mm R/Cl *9* mm
L/Sw *9* mm L/Cl *9* mm
DCA *21/10/19* DRI *24/10/19*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear
The UIC / Chassis frame / Body Structure affected due to collision

25/10 Sent Preli by Merimer

13/1/20 PIP \$7049-92 (Red \$1288-94, 15%)

RECEIVED 14 JAN 2020

13/1/2020

Draw/Time: File Pass to: ☐ Preli Report ☐ Final Report

13/1/20 Typist

Days Of Repair: *6*
Resurvey No. of Trip: *3*

Add Fee: ☐ Site Insp \$5
☐ Interview \$5
☐ Trav. Exp. \$5
☐ Other \$5

Report Format _____

Lump Sum / L.R. _____

PIP \$7049-92



...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2019		23 Oct 2019 16:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H							
Main Claimant:		RUIFENG TECHNOLOGY PTE LTD, Co. Reg. No.: 201734218W							
Vehicle Reg. No.:		SMN6017K	Date of Loss:	21/10/2019 00:00 - :59 [2 Months and 1 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 609149	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019					
Vehicle Reg. No. (Insured):		SMD2331G	Policy No. (Claimant):						
		Excess:							
Repairer:		Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2019]							
Adj Asg. Remarks:		on WP. Car In. Lieb: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Dorlyn Li @ 6481 2001.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 25 Oct 2019

Preliminary Advice

Insured Vehicle No	: SMD2331G	Accident Date	: 21/10/2019
TP Vehicle No	: SMN6017K	Assignment Date	: 23/10/2019
Make	: TOYOTA ALPHARD	Est. Duration of Repair	: 6.00
Date of Inspection	: 24/10/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,917.23
Revised Amount	:S\$	7,256.18
Check Items (Estimated)	:S\$	890.24
Total	:S\$	8,146.42

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2019 14:36
Date Of Accident	21/10/2019 21:30
Exact Location Of Accident	TECK GHEE COMMUNITY CENTRE OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN6017K
Insured/Policyholder	
Name Of Registered Owner	RUIFENG TECHNOLOGY PTE LTD
Co Reg No	201734218W
Email Address	WALTER.NG@RUIFENGWEALTH.COM
Mobile Phone No	(LOCAL) +65-97480475
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALPHARD-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111799417
Cover Note Number	DRIVO PREMIUM

Driver

Name of Driver	SEAH BAO JIE
NRIC No	S8508658H
Date Of Birth	15/03/1985
Occupation	INDOOR
Date Of Driving Pass	02/09/2005
Driving Experience	14 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81000671
Fax Number	
Contact Number	
E-Mail Address	WALTER.NG@RUIFENGWEALTH.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be filed and held by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the information so collected under (d) above may be shared / disclosed:
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.

SEAH BAO JIE
22/10/2019 14:04

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

F/20191021/0164

POLICE DEPARTMENT

OFFICE NOTES

Your vehicle was hit by one
Blue sq vehicle SMD 2331 G. Please
contact the below person who is
the driver of the mentioned
vehicle.

Catherine (90905231)

AS this is a minor accident
No police report is needed. Police
advised to lodge insurance report.

Sgt Brandon Tan. TPRD.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	218W
Vehicle Details	
Vehicle No.:	SMN6017K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD ELEGANCE MR (AUTO)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	2AR2184682
Chassis No.:	JTNGF3DH908023529
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$48,189.00
Original Registration Date:	20 Aug 2019
First Registration Date:	20 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$59,465.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Aug 2029
PARF Rebate Amount:	\$44,598.00
Intended COE Rebate Details	
COE Expiry Date:	19 Aug 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$41,808.00
Total Rebate Amount:	\$86,406.00

The information contained herein is correct as at 23 Oct 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
 Claim Type: Third Party
 Accident Date: 21/10/2019
 TP Veh Reg No: SMD2331G

Estimate No: ES1992170/AMK
 Date: 24 Oct 2019
 Policy No: 5111799417 PREMIUM
 Veh Reg No: SMN6017K
 Make/Model: TOYOTA ALPHARD ELEGANCE
 Chassis No: JTNGF3DH908023529
 Engine No: 2AR2184682
 Reg. Date: 20/08/2019

Estimate Repair Cost to Vehicle No :SMN6017K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	721.90	1 PC	721.90	✓
2 REAR BUMPER RH REFLECTOR	57.60	1 PC	57.60	✓
3 REAR BUMPER RH SIDE RETAINER	89.70	1 PC	89.70	✓
4 REAR BUMPER RH CORNAL RETAINER	90.69	1 PC	90.69	✓
5 REAR BUMPER CENTRE PARKING SENSOR	411.67	2 PC	823.34	✓
6 REAR BUMPER RH OUTER PDC SENSOR	411.67	1 PC	411.67	?
7 REAR BUMPER CLIP	3.89	5 PC	19.45	✓
8 REAR RH SIDE BUMPER	279.30	1 PC	279.30	?
9 REAR TAILGATE	1,950.70	1 PC	1,950.70	✓
10 TAILGATE INNER LOCK	768.95	1 PC	768.95	✓
11 TAILGATE INNER RUBBER	367.90	1 PC	367.90	✓
12 TAILGATE EMBLEM 'ALPHARD'	66.70	1 PC	66.70	✓
13 TAILGATE INNER TRIM BOARD	824.73	1 PC	824.73	✓
14 TAILGATE DOOR CONTROL SWITCH	141.67	1 PC	141.67	?
15 TAILGATE WINDSCREEN GLASS MOULDING	141.90	1 PC	141.90	✓
16 REAR END PANEL	760.24	1 PC	760.24	✓
17 REAR END PANEL INNER TOP GARNISH	275.60	1 PC	275.60	✓
18 REAR END PANEL BUZZER SENSOR	116.40	1 PC	116.40	✓
19 REAR END PANEL ANTENNA	136.70	1 PC	136.70	✓
			8,045.14	
		Less 25%	2,011.29	6,033.86
Special Net				
20 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
21 REAR END PANEL SEALANT	40.00	1 PC	40.00	30.00
			80.00	80.00
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
23 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMPS, TAILGATE, SPOILER & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	900.00	1 LA	900.00	700.00
24 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS, SIDE BUMPERS, TAILGATE, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800.00
25 REMOVE & REFIX REAR SEATS, CARPET TO FACILITATE REPAIR	150.00	1 LA	150.00	80.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 21/10/2019

TP Veh Reg No: SMD2331G

Estimate No: ES1992170/AMK

Date: 24 Oct 2019

Policy No: 5111799417 PREMIUM

Veh Reg No: SMN6017K

Make/Model: TOYOTA ALPHARD
ELEGANCE

Chassis No: JTNGF3DH908023529

Engine No: 2AR2184682

Reg. Date: 20/08/2019

Estimate Repair Cost to Vehicle No :SMN6017K

Description	U/Price	Quantity	List Price	Amount
26 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	60.00	1 PC	60.00	SS ✓ SS
27 RUSTPROOFING	90.00	1 LA	90.00	60.00
			2,220.00	2,220.00
			Total	SS 8,333.86
			Add GST @ 7%	583.37
			Total Amount Payable	SS 8,917.23

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768751
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 21/10/2019

TP Veh Reg No: SMD2331G

Estimate No: ES1992170/AMK

Date: 24 Oct 2019

Policy No: 5111799417 PREMIUM

Veh Reg No: SMN6017K

Make/Model: TOYOTA ALPHARD
ELEGANCE

Chassis No: JTNGF3DH908023529

Engine No: 2AR2184682

Reg. Date: 20/08/2019

Estimate Repair Cost to Vehicle No :SMN6017K

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR BUMPER	721.90	1 PC	721.90	✓
2 REAR BUMPER RH REFLECTOR	57.60	1 PC	57.60	✓
3 REAR BUMPER RH SIDE RETAINER	89.70	1 PC	89.70	✓
4 REAR BUMPER RH CORNAL RETAINER	90.69	1 PC	90.69	✓
5 REAR BUMPER CENTRE PARKING SENSOR	411.67	2 PC	823.34	✓
6 REAR BUMPER RH OUTER PDC SENSOR	411.67	1 PC	411.67	✓
7 REAR BUMPER CLIP	3.89	5 PC	19.45	✓
8 REAR RH SIDE BUMPER	279.30	1 PC	279.30	✓
9 REAR TAILGATE	1,950.70	1 PC	1,950.70	✓
10 TAILGATE INNER LOCK	768.95	1 PC	768.95	✓
11 TAILGATE INNER RUBBER	367.90	1 PC	367.90	✓
12 TAILGATE EMBLEM 'ALPHARD'	66.70	1 PC	66.70	✓
13 TAILGATE INNER TRIM BOARD	824.73	1 PC	824.73	✓
14 TAILGATE DOOR CONTROL SWITCH	141.67	1 PC	141.67	✓
15 TAILGATE WINDSCREEN GLASS MOULDING	141.90	1 PC	141.90	✓
16 REAR END PANEL	760.24	1 PC	760.24	✓
17 REAR END PANEL INNER TOP GARNISH	275.60	1 PC	275.60	✓
18 REAR END PANEL BUZZER SENSOR	116.40	1 PC	116.40	✓
19 REAR END PANEL ANTENNA	136.70	1 PC	136.70	✓
6873.23				
Less 25%				1718.30
Special Net				5154.93
20 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
21 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
Labour				80.00
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
23 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAIL LAMPS, TAILGATE, SPOILER & ATTACHMENTS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	900.00	1 LA	900.00	✓
24 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS, SIDE BUMPERS, TAILGATE, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	✓
25 REMOVE & REFIX REAR SEATS, CARPET TO FACILITATE REPAIR	150.00	1 LA	150.00	✓

87044.92

6 days

NOT WITHIN

Repair By paint

5154.93

30.00

80.00 70

800

80

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 21/10/2019

TP Veh Reg No: SMD2331G

Estimate No: ES1992170/AMK

Date: 24 Oct 2019

Policy No: 5111799417 PREMIUM

Veh Reg No: SMN6017K

Make/Model: TOYOTA ALPHARD
ELEGANCE

Chassis No: JTNGF3DH908023529

Engine No: 2AR2184682

Reg. Date: 20/08/2019

Estimate Repair Cost to Vehicle No :SMN6017K

Description	U/Price	Quantity	List Price	Amount
26 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	60.00	1 PC	60.00	60.00
27 RUSTPROOFING	90.00	1 LA	90.00	90.00
			2,220.00	2,220.00
			Total	SS 8,333.86
			Add GST @ 7%	583.37
			Total Amount Payable	SS 8,917.23

• SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

PARTS: 5154.93

SS: 70

L: 1820

7044.93

P/P: 7044.93

PLS CHECK & CONFIRM

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2019		23 Oct 2019 16:17 Edit Adj Rpt	S\$7,044.92 Edit Estimates	S\$7,044.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H								
Main Claimant:	RUIFENG TECHNOLOGY PTE LTD, Co. Reg. No.: 201734218W								
Vehicle Reg. No.:	SMN6017K	Date of Loss:	21/10/2019 00:00 - :59 [2 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 609149	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SMD2331G	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/11/2019]								
Adj Asg. Remarks:	on WP, Car In. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Dorlyn Li @ 6481 2001.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMN6017K (609149)
[SMD2331G]
TP
RUIFENG TECHNOLOGY PTE LTD
Oct 21 2019 12:00AM
[BLUECAR EAST ASIA PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/10/19 16:33	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/01/20 14:12	General View	1	Load JPG	
2	13/01/20 14:12	General View	1	Load JPG	
3	13/01/20 14:12	General View	1	Load JPG	
4	13/01/20 14:12	General View	1	Load JPG	
5	13/01/20 14:12	General View	1	Load JPG	
6	13/01/20 14:12	General View	1	Load JPG	
7	13/01/20 14:12	General View	1	Load JPG	
8	13/01/20 14:12	General View	1	Load JPG	
9	13/01/20 14:12	General View	1	Load JPG	
10	13/01/20 14:12	General View	1	Load JPG	
11	13/01/20 14:12	General View	1	Load JPG	
12	13/01/20 14:12	General View	1	Load JPG	
13	13/01/20 14:12	General View	1	Load JPG	
14	13/01/20 14:12	General View	1	Load JPG	
15	13/01/20 14:12	General View	1	Load JPG	
16	13/01/20 14:12	General View	1	Load JPG	
17	13/01/20 14:12	General View	1	Load JPG	
18	13/01/20 14:12	General View	1	Load JPG	
19	13/01/20 14:12	General View	1	Load JPG	
20	13/01/20 14:12	General View	1	Load JPG	
21	13/01/20 14:12	General View	1	Load JPG	
22	13/01/20 14:12	General View	1	Load JPG	
23	13/01/20 14:50	Reinspection Photo	1	Load JPG	
24	13/01/20 14:50	Reinspection Photo	1	Load JPG	
25	13/01/20 14:50	Reinspection Photo	1	Load JPG	
26	13/01/20 14:50	Reinspection Photo	1	Load JPG	
27	13/01/20 14:50	Reinspection Photo	1	Load JPG	
28	13/01/20 14:50	Reinspection Photo	1	Load JPG	
29	13/01/20 14:50	Reinspection Photo	1	Load JPG	
30	13/01/20 14:50	Reinspection Photo	1	Load JPG	
31	13/01/20 14:50	Reinspection Photo	1	Load JPG	

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/10/19 17:23	PR1	1	Load PDF	
2	23/10/19 10:30	Agree on SJE	1	Load PDF	
3	23/10/19 12:11	E-filed GIA Report of SMN6017K	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018827/KYF3Q2

Date: 15/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29112616MCY
 Claimant: SMN6017K Insured Vehicle No: SMD2331G
 Vehicle No: SMN6017K Date of Loss: 21/10/2019 Nature of Claim: TP Claim No: 609149

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN6017K
 Make & Model: TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A) Engine No: 2AR2184682
 Reg. Date: 20/08/2019 (Man. Year: 2019) Chassis No: JTNGF3DH908023529
 Colour: Metallic Pearl White Odometer: 5790 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm
 Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,113.85	5,224.92	888.93	14.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,820.00	400.00	18.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,333.85	7,044.92	1,288.93	15.47
+ GST 7.00/7.00% (S\$)	583.37	493.14	90.23	15.47
Nett Amount (S\$)	8,917.22	7,538.06	1,379.16	15.47

INSPECTION

Date of Assignment: 23/10/2019
 Date Inspected: 24/10/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 CVT ELEGANCE S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN6017K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	721.90 FL	*721.90 FL
2	1		*REAR BUMPER RH REFLECTOR	Mtg Cracked	57.60 FL	*57.60 FL
3	1		*REAR BUMPER RH SIDE RETAINER	Distorted	89.70 FL	*89.70 FL
4	1		*REAR BUMPER RH CORNAL RETAINER	Distorted	90.69 FL	*90.69 FL
5	2		*REAR BUMPER CENTRE PARKING SENSOR	Shorted	823.34 FL	*823.34 FL
6	1		*REAR BUMPER RH OUTER PDC SENSOR	Serviceable	411.67 FL	*- FL
7	5		*REAR BUMPER CLIP	Necessary	19.45 FL	*19.45 FL
8	1		*REAR RH SIDE BUMPER	Cracked	279.30 FL	*279.30 FL
9	1		*REAR TAILGATE	Bent	1,950.70 FL	*1,950.70 FL
10	1		*TAILGATE INNER LOCK	Dented	768.95 FL	*768.95 FL
11	1		*TAILGATE INNER RUBBER	Distorted /Dented	367.90 FL	*367.90 FL
12	1		*TAILGATE EMBLEM ALPHARD	Necessary	66.70 FL	*66.70 FL
13	1		*TAILGATE INNER TRIM BOARD	Deformed	824.73 FL	*824.73 FL
14	1		*TAILGATE DOOR CONTROL SWITCH	Dented	141.67 FL	*141.67 FL
15	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	141.90 FL	*141.90 FL
16	1		*REAR END PANEL	Repair	760.24 FL	*- FL
17	1		*REAR END PANEL INNER TOP GARNISH	Buckled	275.60 FL	*275.60 FL
18	1		*REAR END PANEL BUZZER SENSOR	Cracked	116.40 FL	*116.40 FL
19	1		*REAR END PANEL ANTENNA	Cracked	136.70 FL	*136.70 FL
20	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,125.14	6,943.23
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,011.29	1,718.31
Total Parts (\$\$)	6,113.85	5,224.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,TAILLAMPS ,TAILGATE SPOILER & ATTACHMENTS TO CUT ,WELD & RENEW REAR END PANEL KNOCK & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	New	900.00	700.00
3	PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS ,SIDE BUMPERS ,TAILGATE ,REAR END PANEL ,REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	900.00	800.00
4	REMOVE & REFIX REAR SEATS ,CARPET TO FACILITATE REPAIR	New	150.00	80.00
5	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	60.00	60.00
6	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (S\$)			2,220.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >