

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT19004556	Page	1
Registration No	: SMJ1058X	Date	: 18. Oct 2019		
Chassis No	: JHMRC1890KC201042	Customer No.	: WZ1007		
Model	: ODYSSEY 2.4 EXV-S 19YM (EURO 6)	Svc Advisor	: ARY CHUA WAI NGEE		
Owner's Name	: LIANG WEITAN	Engine No	: K24W72460686		
Ins Policy No.	: 19-MS001652-R00	Date Time	: 18. Oct 2019 2:58:36 PM		
Date of Accident	: 17/10/2019	Surveyor Name	: DID : +65 6846 5673		
		Survey Date	: HP : +65 8100 6306		
		Authorisation Date	: Email : anychua@honda.com.sg		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73633) OWNER: LIANG WEITAN OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 17/10/2019@20.40PM ACC: CENTRAL BOULEVARD (L/P 35F) SURVEYED BY: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHA3815X - HYUNDAI/I40/BLUE/TAXI						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60
42700-T6A-J43	WHEEL,DISK AL 17X7JJ <i>cat</i>	1	845.30	25	633.97	44.38	678.35
44600-T0B-A00	HUB ASSYFR. <i>3</i>	1	187.20	25	140.40	9.83	150.23
44300-T6A-J51	BEARING ASSYFR.HUB <i>No new</i>	1	138.20	25	103.65	7.26	110.91
33150-T6A-Q31	LIGHT ASSY,L.HEAD <i>3</i>	1	1479.70	25	1109.77	77.68	1187.45
72470-T6A-003	GARNISHL.FR.DOOR CENTER <i>3 new</i>	1	50.50	25	37.87	2.65	40.52
72970-T6A-003	GARNISHL.SLIDE DOOR CENTER <i>3 new</i>	1	45.70	25	34.27	2.40	36.67
72450-T6A-003	MOLDING ASSYL.FR.DOOR <i>3 new</i>	1	73.90	25	55.42	3.88	59.30
72950-T6A-003	MOLDING ASSYL.RR.DOOR <i>3 new</i>	1	69.50	25	52.12	3.65	55.77
75332-T6A-N01ZC	GARNISH ASSY,L.FR.DOOR <i>3 new</i>	1	332.40	25	249.30	17.45	266.75
75333-T6A-N11ZC	GARNISH ASSY,L.SLIDE <i>3 new</i>	1	314.20	25	235.65	16.50	252.15
04645-T6A-J00ZZ	PANEL SET,L.FR.OUTSIDE <i>new</i>	1	877.70	25	658.27	46.08	704.35
04641-T6A-330ZZ	PANEL,L.SIDE SILL SIDE <i>new</i>	1	272.10	25	204.07	14.28	218.35
60260-T6A-300ZZ	FENDER COMPL.FR. <i>Painted</i>	1	548.60	25	411.45	28.80	440.25
74155-T6A-000	ENCLOSUREL.FR.FENDER <i>new</i>	1	26.30	25	19.72	1.38	21.10
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER <i>3 new</i>	1	38.40	25	28.80	2.02	30.82
67365-T6A-J01	TAPE,L.FR.DOOR SASH UPPER <i>3 new</i>	1	37.30	25	27.97	1.96	29.93

Printed on 22/10/2019 2:50:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMJ1058X

Chassis No : JHMRC1890KC201042

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : LIANG WEITAN

Ins Policy No. : 19-MS001652-R00

Date of Accident : 17/10/2019

Document No. : SQT19004556 **Page** 2

Date : 18. Oct 2019

Customer No. : WZ1007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72460686

Date | Time : 18. Oct 2019 2:58:36 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR <i>Deleted</i>	1	895.20	25	671.40	47.00	✓ 718.40
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER <i>Ren</i>	1	57.10	25	42.82	3.00	✓ 45.82
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR <i>Deleted</i>	1	1000.50	25	750.37	52.53	✓ 802.90
Sum Item					5467.29	382.73	5,850.02
BOSUN	SUNDRIES	1	60.00		20 60.00	4.20	20 64.20
BOJSE	BODY JOINT SEALANT.	1	100.00		x 100.00	7.00	x 107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		x 100.00	7.00	4 107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00		80 140.00	9.80	88 149.80
BC011R	REMOVE INSTALL & CALIBRATE LH SIDE VIEW CAMERA (N)	1	350.00		x 350.00	24.50	x 374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00		✓ 350.00	24.50	374.50
BMI03D	REMOVE & INSTALL LHF COMPARTMENT LININGS	1	450.00		x 450.00	31.50	481.50
BMI03D	REMOVE & INSTALL LHR COMPARTMENT LININGS	1	450.00		x 450.00	31.50	481.50
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	550.00		450 550.00	38.50	588.50
BKDR31R	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR.	1	650.00		500 650.00	45.50	695.50
BKFE21K	STRAIGHTEN ALIGN RR L FENDER & LH SILL PANEL	1	3360.00		1680 3360.00	235.20	3595.20
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3200.00		1350 3200.00	224.00	3424.00
Sum Labor					9760.00	683.20	10,443.20

Survey By

Date & Time

Excess

Status

Signature

Adrian Ling
31/10/19
06 Days.
Not Authorized
[Signature]

Total Amount 15,407.29 1,078.53 16,485.82

Total (Inclusive of GST) **16,485.82**

Printed on 22/10/2019 10:28:14 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.