

15/03/19

INS. CASE C

TAN Jas
6568804844

CC4/ASM19018835/Fga3

LKK:

IDAC:

143726

ASSIGNMENT

Surveyor:

RAM

DOI: 23/10/19

Date / Time: 23/10/2019

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHD5676B

Claim No. : S9M0243S

Name of Insured : TRANS-CAB SERVICES PTE LTD

Policy No. : VFX/P1680520

Insured Tel No. : HP:

Make / Model : TOYOTA PRIUS-1.8 HYBRID CVT (A)

Excess See II : S\$

D.O.A : 17/10/2019 16:15

Place of Accident : OXLEY BIZHUB DROP-OFF POINT

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age : LOO NGIAP MENG

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Driver Tel No. : +65-81328339

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

GBJ 7000C



INSRS: WSP: TORQUE 5

Tel: BIKOST

Liability: BIKOST

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:

Date/Time	GBJ 7000C - X	SHD 5676B - X	STAGE	DATE / PIC
24/12	email LOI		Non-Reporting ltr (1st):	
24/12	Rec LOR to TP (Pending LOD)		Non-Reporting ltr (2nd):	
24/12	Rec LOR return		Non-Reporting ltr (Final):	
24/12	TP call mandate		Notification ltr (if non-pickup):	
24/12	Requesting mandate approval		Call OI:	
24/12	Rec LOR 4076-45 (Pending LOR return)		After call ltr to OI:	24/12/19
24/12	Rec LOR 4076-45, DP send (Pending DV)		Documentation Check List: Handler	Typist
24/12	DV M, Rec LOR Admin to close		Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA:	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒
PRELIMINARY ADVICE Date/Time: Sent By:				
FINALIZATION Date/Time: Confirm with: Confirm by: RAM				
Repair Cost:	S\$ 3800/-	6 days) Reduction: 3800/- x 10% = 380	Email ☐	Call ☐
FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐				
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 26	If NO or B 28, Ass. Lia:	
Repair Cost:	S\$ 3800.00			
Loss of Rental (LOR):	S\$ -	days)		
Loss of Use (LOU):	S\$ 240.00	(S\$ 60 x 4 days)		
Loss of Income (LOI):	S\$ -	(S\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☒ LOR + LOI ☐	[Tick only one]			
GIA/LTA Search	S\$ 70.45			
Medical:	S\$ -			
Disbursement:	S\$ -	(e.g. Tow/ Independent)		
Legal Cost	S\$ -			
Total:	S\$ 4076.45	Global Sum S\$:		
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1:	S\$ 4076.45	Name 1:	Vijay Auto Pte Ltd	
Payee 2: (Strike if N.A.)	S\$ -	Name 2:		
Payee 3: (Strike if N.A.)	S\$ -	Name 3:		

COPY SENT
24/3/2020

X GMA

ASSIGNMENT

16 Jul 2019

Location: 2500
 Registration No: ~~GBJ7000C~~
 OO: TI / WS / TP RES / CD RES / EVA / INV / MV
 To Inspect Vehicle No: ~~GBJ7000C~~
 At Workshop: ~~8 km~~ ~~bukit 4~~ ~~#01-49~~
 Remarks:
 Vehicle No:
 Owner's No:
 Car Insurance:
 (Insured's Name):
 Make of Vehicle:

Vehicle: ~~GBJ7000C~~
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota hiace
 Colour: Silver
 Sp. Handling: 18502
 Engine:
 Chassis: JTFHT62P700249309
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Motor: Nil / SRim / STD A/Rim or
 Tyre Size: F: 195 R15
 R: -

(Proxy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / FRI / DRI: Consistent? Yes or No

Est. Repair: 6 days Res. Yes or No

Est. Sum: 20 % 3 Val. Yes or No

CA / REV / REP / 24 HRS

VIN: Person Contacted:

Vehicle: IN / OUT

Front

Rear

RUBal: 7 mm RUBal: 7 mm

LUBal: 7 mm LUBal: 7 mm

D.O.A: 17/10/2019 D.O.A: 23/10/19

Survey held at: BifrostDes. of Damages: Front / Rear / O/S / M/S / U/C / Rooftop or

Front of O/S front

The U/C / Chassis frame / Body Structure attached due to collision

Date / Time: Action / Instruction

L/S: \$3800/- confirm with Lucas chow on 25/10/19
 6 repair days

L/G \$3800/- (Red = \$8478.70 / 69.1%)

MV: \$65320.05
 PV: \$29144
 NV: \$39176.05

Survey Fee: (No Fee)

☐ : Prelim. Report

Days Of Repair:

(1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee: (No Fee)

(2)

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Tech. Insp. \$☐ Weekend \$

Report Format:

Lump Sum / I.B.I. (\$)

Survey Fee

Disbursement

TOTAL \$

(Note)

(Other)

TOTAL \$

Bifrost Auto Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, 401-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201729175W

Vehicle No: GBJ7000C
 Model: Toyota Hiace
 Chassis No: JTFHT02P700249309
 Year of manufacture: 2019

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Front bumper 400+	1	# 899.20	8540
2	Front bumper retainer RH 400	1	# 84.70	855
3	Head lamp RH 400	1	# 782.30	
4	Bonnet 400	1	# 787.40	
5	Bonnet hinge RH 400	1	# 161.70	
6	Bonnet hinge LH 400	1	# 161.70	
7	Front corner panel RH 400	1	# 132.20	
8	RH side mirror assy 400	1	# 480.00	
9	Front door RH 400	1	# 1398.10	
10	Front door window frame RH 400	1	# 122.80	
11	Front door checker 400	1	# 185.40	
12	Front door hinge top 400	1	# 121.20	
13	Front door hinge bottom 400	1	# 121.20	
14	Front door lock 400	1	# 684.70	
15	Front door outer handle 400	1	# 393.10	175
16	Front door inner trim board 400	1	# 684.70	
17	Front door regulator 400	1	# 261.30	
18	Front door P/W motor 400	1	# 467.20	
19	Front door rubber beading 400	1	# 185.40	
20	RH door center pillar 400	1	# 982.50	
21	RH sliding door 400	1	# 1972.60	
22	RH sliding door outer handle 400	1	# 382.20	

\$4535.40

11/451.60

25% = \$3401.55

-25% 2,588.70 0.00

Special Nett Items				
23	Front bumper clip set 400	1	50.00	350
24	Front door sticker 400	1	60.00	330
25	Front door inner trim board clip set 400	1	50.00	
26	Front door speaker 400	1	500.00	

\$60

660.00

Labour & Miscellaneous Charge				
27	To check wiring and lighting system	1	100.00	900
28	To conduct head lamp focus	1	100.00	330
29	To supply anti rust treatment / putty on affected areas	1	80.00	850

#12, 278.70

30	To R&R front RH door mechanism	1	350.00	350.00 \$60
31	To repair, replace & realign damaged areas	1	1200.00	1200.00 1200.00 \$500
32	To spray painting on affected areas	1	1000.00	1000.00 \$700
33	To perform water seepage test after repair	1	150.00	150.00 \$100
34	Sundries	1	50.00	50.00 \$110

 3030.00

List Items Subtotal
 Special Net Items Subtotal
 Labour Items Subtotal
 Total

Consultants hence notify
 owner of the following:
 • survey before/after spray painting
 • survey damaged part(s) during resurvey
 • prices are subject to confirmation
 • third party survey is on a "Without Prejudice" basis
 • no illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Handwritten:
 Ram (LKR)
 88622778
 Parasuram@LKR.com
 6 repair days
 23/10/19 16:50:15

LIST: \$3401.55

Net: \$60

Labour: \$1340

Total: \$4801.55

add 20% L/S: \$3800.00 *

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

742D

Vehicle Details

Vehicle No.:

GBJ7000C

Vehicle to be Exported:

No

Intended Deregistration Date:

30 Nov 2019

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE VAN TURBO 5DR MT

Primary Colour:

Silver

Manufacturing Year:

2019

Engine No.:

1KD2862666

Chassis No.:

JTFHT02P700249309

Maximum Power Output:

-

Open Market Value:

\$28,136.00

Original Registration Date:

16 Jul 2019

First Registration Date:

16 Jul 2019

Transfer Count:

0

Actual ARF Paid:

\$1,407.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

15 Jul 2029

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$25,089.00

COE Rebate Amount:

\$24,144.00

Total Rebate Amount:

\$24,144.00

The information contained herein is correct as at 18 Oct 2019

remaining: 9 years 8 months 30 days (116.9)

Depn: \$6500/yearly @ \$541.66/monthly

$116.9 \times \$541.66 = \63320.05

OK

Parasuram (LKK Auto)

From: Lucas Chow <assessment_ral@bifrostable.com>
Sent: Friday, 25 October, 2019 11:59 AM
To: Parasuram (LKK Auto)
Cc: Lucas Chow; claims@bifrostable.com; claims_ral@bifrostable.com
Subject: Re: Updated estimate of GBJ7000C

Dear Parasuram ,

We hereby confirm the finalize COR \$3800 with 6 working days .

Thank you .
Lucas Chow

On Fri, 25 Oct 2019 at 11:06, Parasuram (LKK Auto) <Parasuram@lkkauto.com> wrote:

WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi,

The file attached is the finalise estimate. Please take a look and confirm with me. So I

Can submit the documents.

Thanks

Best Regards,

Parasuram | Assistant Automotive Assessor

LKK Auto Consultants

18838.19

⏪ Service Request Details

Claim
S9M0243S

Reference
None ✎

Loss Date
October 17, 2019

Report Date
Oct 23, 2019 9:07:00 AM

Request Date
October 23, 2019

Due Date
October 23, 2020

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

P. Lucas
T: 12.10p.m
V: 1h
E: ✓

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
GBJ7000C

Model
HIACE-3.0 D TURBO (M)

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
New Message						

Summer Lee (LKK Auto)

From: Lucas Chow <assessment_ral@bifrostauto.com>
Sent: Wednesday, 23 October, 2019 11:05 AM
To: KADRI Mateen
Cc: Lucas Chow; claims@bifrostauto.com; claims_rar@bifrostauto.com
Subject: [EXTERNAL] Re: Your Ref : GBJ7000C Our Ref : S9M0243SMC/JT

Dear Kadri ,

We are agreeable LKK Auto Consultants Pte Ltd to PRS the said vehicle , kindly make the necessary arrangement .

Thank you .
Lucas Chow

On Wed, 23 Oct 2019 at 09:25, KADRI Mateen <mateen.kadri@axa.com.sg> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir,

We want to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list below to conduct the joint pre-repair survey as a Single Joint Expert.

List of our motor surveyors:
1. LKK Auto Consultants Pte Ltd
2. Infiniti Appraisal Services
3. Priority Services Pte Ltd
4. AXA in house surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert. Meanwhile, please furnish us with estimate quotation in order for our surveyor to complete the pre repair survey.

If there be any injury claims by your client, please combine it in one Letter of Demand in light of one cause of action, save as to costs and expenses.

Regards,

Mateen Kadri



From: Lucas Chow [mailto:assessment_ral@bifrostable.com]
Sent: Tuesday, October 22, 2019 4:01 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: Lucas Chow <assessment_ral@bifrostable.com>; claims@bifrostable.com; claims_rar@bifrostable.com
Subject: [EXTERNAL] Accident involving GBJ7000C & SHD5676B on 17/10/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, MCC Flying Eagle , to notify you of the aforesaid accident involving our client's vehicle GBJ 7000 C and your insured's vehicle SHD 5676 B on 17/10/2019.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SHD 5676 B for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Lucas (8131 6318)

Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 19/10/2019

PRS ARRANGEMENT (Date & Time) : 23/10/2019

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank You .

Lucas Chow

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/3/2020

Survey Details:

Date of loss	17-Oct-19
Date of appointment	23-Oct-19
Date of survey	23-Oct-19
Location of survey	BIFROST AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBJ7000C
Make and Model	TOYOTA HIACE VAN TURBO 5DR MT
Date of registration	16-Jul-19
Parf Rebate	
Market Value	\$ 63,000.00
Parf Rebate	\$ 24,144.00
Nett Loss	\$ 38,856.00

Repair details:

Initial Estimate	\$ 12,278.70
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,461.55
Check items (estimate)	\$ -
Labour	\$ 1,340.00
Total	\$ 4,801.55
Lump Sum(if applicable)	\$ 3,800.00

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	3,800.00
Loss of use	\$	400.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	36.45
Others	\$	-
Proposed Total	\$	4,236.45



<MANDATE IA> - S9M0243S {ACCIDENT INVOLVING SHD 5676B (OI) & GBJ 7000C (TP) ON 17/10/2019}

Type

Question

Message

LIABILITY: 100% BOLA S26 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$4236.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 18/03/2020

Reply

BIFROST AUTO PTE. LTD.

Co. Reg. No. : 201929175W

Invoice

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#24-01 AXA Tower,
Singapore 068811

Inv. No. : BA.RA.2003004
Inv. Date : 20-01-2020
Ref : 17/10/2019
Terms : 30 Days
Veh. No. : GBJ7000C
Make & Model : TOYOTA
HIACE

#	Description	Qty	Rate	Total
1	Repair Costs	1.0000	\$3,800.00	\$3,800.00
2	Loss of Use	4.0000	\$60.00	\$240.00
3	GIA/LTA Search Fees	1.0000	\$36.45	\$36.45

Remarks:
GBJ7000C (Car Out:xx/xx/xx)

Subtotal for invoice : S\$4,076.45
Total : S\$4,076.45

*I agree to the price as listed above and
affirm that the goods are received in good
condition.*

On behalf of **BIFROST AUTO PTE. LTD.**

(Customer's Signature and Company Stamp)


(Authorised Signature)*



Please make cheque payable to "BIFROST AUTO PTE LTD" and mail to 6001 BEACH ROAD #22-01, GOLDEN MILE TOWER Singapore 199589 or direct bank transfer to DBS Bank Current Account 070-902-886-1.

The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document.

6001 Beach Road #22-01, Golden Mile Tower, Singapore 199589

email: claims@bifrostauto.com



**Re:<MANDATE IA> - S9M0243S {ACCIDENT INVOLVING
SHD 5676B (OI) & GBJ 7000C (TP) ON 17/10/2019}**

Type

🔔 Question

Message

PLEASE PROCEED.

Reply

BIFROST AUTO PTE. LTD.

Co. Reg. No. : 201929175W

Our Ref : GBJ7000C
Your Ref : SHD5676B

11/12/2019

WITHOUT PREJUDICE

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#24-01 AXA Tower,
Singapore 068811

Attention: Motor Claims Department

Dear Sir/Mdm,

Accident on 17/10/2019 along Oxley Bizhub involving vehicles GBJ 7000 C & SHD 5676 B

We refer to the above-mentioned accident.

We are claiming as per below:-

1. Repair Cost	\$ 3,800.00
2. Loss of Use for 04 Days x \$100/- per day	\$ 400.00
3. LTA/GIA Search fee	\$ 36.45
TOTAL	\$ 4,236.45

Enclosed herewith a copy each of relevant GIA report, LTA, Proforma Tax invoice, Rental Agreement/Tax invoice and letter of Authorization for your attention. Kindly let us have your reply with the next 14 days upon receipt of this letter.

If you have any enquiries, please contact us @ 9648-8228 or you may email to us at claims@bifrostauto.com

Yours faithfully,
BIFROST AUTO PTE. LTD.



NOTE: # Please note that the Loss of Use will be paid based on negotiation and on the NIMA Protocol (Court Guideline).

This is a computer generated letter and does not need a signature.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19018835/Ega3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN ✓		Date : 03-04-2020 Code : ASM ✓		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 5676B ✓	Veh. Inspected	GBJ 7000C	
Policy No.	VFX/P1680520 ✓	Coverage (\$)	0.00	
Claim No.	S9M0243S ✓	Excess (\$)	0.00	
Assign From		Assign Date	23/10/2019 ✓	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982 ✓	
Engine No.	HIDDEN ✓	Year of Reg.	2019 ✓	
Chassis No.	JTFHT02P700249309	Colour	SILVER ✓	
Odometer	15502 ✓	Steering	IN ORDER ✓	
Brakes	IN ORDER ✓	Modification	STANDARD ALLOY RIM	
General	GOOD ✓			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15 ✓	BRIDGESTONE ✓	7 mm ✓	
L/H Front Tyre	195 R15 ✓	BRIDGESTONE ✓	7 mm ✓	
R/H Rear Tyre	195 R15 ✓	BRIDGESTONE ✓	7 mm ✓	
L/H Rear Tyre	195 R15 ✓	BRIDGESTONE ✓	7 mm ✓	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND O/S FRONT PORTION. DAMAGES SEE DETAILS. ✓				
5. General Information				
Accident Date	17/10/2019 ✓	Inspection Date	23/10/2019 ✓	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 ✓			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days ✓		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7000C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	CUT ✓	899.20	540.00
1	FRONT BUMPER RETAINER RH (CONSISTENT)	CRACKED ✓	84.70	55.00
1	HEAD LAMP RH (CONSISTENT)	CRACKED ✓	782.30	782.30
1	BONNET (CONSISTENT)	DENTED ✓	787.40	787.40
1	BONNET HINGE RH (CONSISTENT)	NOT NECESSARY ✓	161.70	-
1	BONNET HINGE LH (CONSISTENT)	NOT NECESSARY ✓	161.70	-
1	FRONT CORNER PANEL RH (CONSISTENT)	DENTED ✓	132.20	132.20
1	RH SIDE MIRROR ASSY (CONSISTENT)	SCRATCHED ✓	480.00	480.00
1	FRONT DOOR RH (CONSISTENT)	DENTED ✓	1,398.10	1,398.10
1	FRONT DOOR WINDOW FRAME RH (CONSISTENT)	NOT NECESSARY ✓	122.80	-
1	FRONT DOOR CHECKER (CONSISTENT)	TO REPAIR SEE LABOUR ✓	185.40	-
1	FRONT DOOR HINGE TOP (CONSISTENT)	NOT NECESSARY ✓	121.20	-
1	FRONT DOOR HINGE BOTTOM (CONSISTENT)	NOT NECESSARY ✓	121.20	-
1	FRONT DOOR LOCK (CONSISTENT)	NOT NECESSARY ✓	684.70	-
1	FRONT DOOR OUTER HANDLE (CONSISTENT)	SCRATCHED ✓	393.10	175.00
1	FRONT DOOR INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY ✓	684.70	-
1	FRONT DOOR REGULATOR (CONSISTENT)	NOT NECESSARY ✓	261.30	-
1	FRONT DOOR P/W MOTOR (CONSISTENT)	NOT NECESSARY ✓	467.20	-
1	FRONT DOOR RUBBER BEADING (CONSISTENT)	TORN ✓	185.40	185.40
1	RH DOOR CENTER PILLAR (CONSISTENT)	NOT NECESSARY ✓	982.50	-
1	RH SLIDING DOOR (CONSISTENT)	NOT NECESSARY ✓	1,972.60	-
1	RH SLIDING DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY ✓	382.20	-
	LESS 25% DISCOUNT		-	-1,133.85
			11,451.60	3,401.55
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY ✓	50.00	30.00
1	FRONT DOOR STICKER (SN) (CONSISTENT)	NECESSARY ✓	60.00	30.00
1	SET FRONT DOOR INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY ✓	50.00	-
1	FRONT DOOR SPEAKER (SN) (CONSISTENT)	NOT NECESSARY ✓	500.00	-

Report Ref No. CC4/ASM19018835/Fga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			710.00	60.00
	LABOUR			
	TO CHECK WIRING AND LIGHTING SYSTEM.)		100.00	30.00
	TO CONDUCT HEAD LAMP FOCUS.)		100.00	-
	TO SUPPLY ANTI RUST TREATMENT /PUTTY ON AFFECTED AREAS.		80.00	50.00
	TO R&R FRONT RH DOOR MECHANISM .		350.00	60.00
	TO REPAIR ,REPLACE & REALIGN DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF FRONT DOOR CHECKER .		1,200.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	700.00
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR .	NOT NECESSARY	150.00	-
			2,980.00	1,340.00
	GRAND TOTAL		15,141.60	4,801.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CC4/ASM19018835/Fga3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M02435
Reference	CC4/ASM19018835/Fg30q2
Loss Date	17 October 2019
Report Date	23 Oct 2019 9:07:00 AM
Request Date	25 March 2020
Due Date	

Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TPN)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	G8J7000C
Make	TPVO TOYOTA
Model	HIACE-3.0 D TURBO (M)
Service Address	

Primary Contact/Insured
TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler
TAN Jia
6568004844
jia.tan@jaa.com.sg

Additional Instructions

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Reports & Statement

Maintenance

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 CIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 TP FINAL EST LIST.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020
 PARF COE REBATE.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020
 LODD AND OTHER DOCUMENTS.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020
 MANDATE IA DO 18032020.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statment	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TFP)	18 March 2020
 TP - 1A.pdf	Firms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TFP)	25 October 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TFP)	25 October 2019
 SURVEY LIST SEND TO WORKSHOP.png	Letters and Correspondence	Workshop	KADRI Maateen	23 October 2019
 GIA REPORT OF GBJ7000C.PDF	Reports & Statement	GIA Report	KADRI Maateen	23 October 2019
 GIA REPORT OF SHD5676B.PDF	Reports & Statement	GIA Report	KADRI Maateen	23 October 2019
 EMAIL.png	Letters and Correspondence	Others	KADRI Maateen	23 October 2019