

Bifrost Auto Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201729175W

Vehicle No: GBJ7000C
 Model: Toyota Hiace
 Chassis No: JTFHT02P700249309
 Year of manufacture: 2019

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Front bumper <i>qcc+</i>	1	# 899.20	\$540
2	Front bumper retainer RH <i>qccra</i>	1	# 84.70	\$55
3	Head lamp RH <i>qccra</i>	1	# 782.30	
4	Bonnet <i>DD</i>	1	# 787.40	
5	Bonnet hinge RH <i>qccra</i>	1	# 161.70	
6	Bonnet hinge LH <i>qccra</i>	1	# 161.70	
7	Front corner panel RH <i>DD</i>	1	# 132.20	
8	RH side mirror assy <i>scr</i>	1	# 480.00	
9	Front door RH <i>DD</i>	1	# 1398.10	
10	Front door window frame RH <i>qccra</i>	1	# 122.80	
11	Front door checker <i>xnn R</i>	1	# 185.40	
12	Front door hinge top <i>xnn</i>	1	# 121.20	
13	Front door hinge bottom <i>xnn</i>	1	# 121.20	
14	Front door lock <i>xnn</i>	1	# 684.70	
15	Front door outer handle <i>scr</i>	1	# 393.10	\$175
16	Front door inner trim board <i>xnn</i>	1	# 684.70	
17	Front door regulator <i>xnn</i>	1	# 261.30	
18	Front door P/W motor <i>xnn</i>	1	# 467.20	
19	Front door rubber beading <i>qccra</i>	1	# 185.40	
20	RH door center pillar <i>xnn Repair</i>	1	# 982.50	
21	RH sliding door <i>xnn Repair</i>	1	# 1972.60	
22	RH sliding door outer handle <i>xnn</i>	1	# 382.20	

\$4535.40

25% = \$3401.55

0.00

Special Nett Items

23	Front bumper clip set <i>qccra</i>	1	50.00	\$30
24	Front door sticker <i>qccra</i>	1	60.00	\$30
25	Front door inner trim board clip set <i>qccra</i>	1	50.00	
26	Front door speaker <i>xnn</i>	1	500.00	

\$60

660.00

Labour & Miscellaneous Charge

27	To check wiring and lighting system	1	100.00	\$100
28	To conduct head lamp focus	1	100.00	\$100
29	To supply anti rust treatment / putty on affected areas	1	80.00	\$50

\$30

30	To R&R front RH door mechanism	1	350.00 \$60
31	To repair, replace & realign damaged areas	1	1200.00 \$1000 \$750 \$500
32	To spray painting on affected areas	1	1000.00 \$700
33	To perform water seepage test after repair	1	150.00 \$90 Xnn
34	Sundries	1	50.00 Xnn

 3030.00

List Items Subtotal
 Special Nett Items Subtotal
 Labour Items Subtotal
 Total

to Consultants hence notify
 insurer of the following:
 survey before/after spray painting
 display damaged part(s) during resurvey
 parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

[Signature]
 25/10/19 Ram (LKR)
 88622778mP
 Parasuram@LKKanto.com
 6 repair days
 23/10/19 1615hrs (LS)

List: \$3401.55

Nett: \$60

Labour: \$1340

Total: \$4801.55

aft 20% L/S: \$3800.00 *