

16h



ESTIMATE TO REPAIR

VEHICLE NO. : SKK 9902 A
 MAKE : MERCEDES BENZ
 MODEL : R300LA
 YEAR : 2012
 CHASSIS NO : WDC2511542A161876

SURVEYOR NAME : Kenneth (LKL)
 DATE OF SURVEY : 24.10.2019
 TIME OF SURVEY :

DATE : 21-Oct-19
 DATE OF ACCIDENT : 17-Oct-19
 THIRD PARTY REF : GBH9669X / CHINA TAIPING

No.	Parts Description / Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper	Nett	Bu	\$ 2,000.00	—
1 pc	rear bumper reinforcement	Nett	B	\$ 980.00	—
1 pc	rear bumper LH reflector	Nett	m	\$ 80.00	—
2 ps	rear bumper sensor	Nett	\$ 150.00	\$ 300.00	2 ipu 150 short 4
1 pc	rear bumper top chrome	Nett	cm	\$ 480.00	—
1 pc	tailgate star	Nett	na	\$ 60.00	—
1 pc	tailgate R300 emblem	Nett	na	\$ 53.00	—
				\$ 3,953.00	
	less 10%		2823.00	\$ 395.30	\$ 3,557.70
			2823		
	To putty and spray paint.		2540.70		\$ 500.00 450
			860.00		
	To check rear wiring & replace parking sensor.		3400.70		\$ 80.00 80
	Labour charges.				\$ 400.00 350
	Not Withheld		Jump \$ 2700		ole
	1/2m @ ?				
	Return After 4 days				
					APPROVED
TG-ML/-	TOTAL				\$ 4,537.70

Lim Tan Motor Pte Ltd

Blk 178 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

PV
PC