

ASS. REC. BY:

REF: CS/MSG 19018852/Vvf372 Special Instruction:

SUBJECT: Marius ASSIGNMENT (Office)From (Person): Kathrin Wong of MSLG Date/Time: 20-10-19 10:59 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLR 1159H Insured: FBH 8573Uat Workshop m/s Euro Success Tel: 98289277of 1 Kaki Bukit Ave 6 # 02-03Policy No: MSD/VMS/19-401243 Claim No: MSC/V/19-001267

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22-10-2019  
(Client's Record)CA / REV / REP. / REV 24 HRS <sup>map</sup> H.O.D. Endorsement: \_\_\_\_\_Date/Time: 20-10-19 10:55 AM Person Contacted: Ali Hwa Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLR 1159H - X
	FBH 8573U - NB / MSG 19018852/Vvf372 D.O.A. - 02/10/2019
25/10/19	Informed Katherine pending workshop est by merimen
30/10/19	Send proli revised via merimen

merimen

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLR1159H  
 at Workshop mis: Suro  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_


Veh No: SLR1159H Yr Regn: 7, 17  
 Type: Motor Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA /  
 Make: Toyota harrier c.c. 1980  
 Colour: 3/4cl A/C: Insured / Std / NI / NA  
 Sp. Reading: 79920 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 25U 60 0092200  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/65R17  
 R: \_\_\_\_\_  
 BS / DDH / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS LTA 6222  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Front: 6 mm Rear: 6 mm  
 R/Bal: \_\_\_\_\_ mm R/Bal: \_\_\_\_\_ mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A. 27/10/19 D.O.I. 24/10/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear n/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/10/19</u>	<u>1/5 @ 2900 confirmed with merime (Red 9405.69, 76%)</u>
RECEIVED 9 OCT 2019	
 <u>30/10/2019</u>	

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: -

Date/Time, File Return to? 30/10 - typist

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. invs (\$)  
 : Wash etc (\$)

Survey Fee:	
Transportation:	<u>200</u>
S + PS - SI	<u>11</u>
Photos	
Other	
TOTAL	<u>211</u>

Report Form: merime  
 Lump Sum / B.S. / G: 2900k

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Katherine Wong	<b>Date:</b> 30 Oct 2019
<b><u>Preliminary Advice</u></b>	

Insured Vehicle No : FBH8573U	
TP Vehicle No : SLR1159H	Accident Date : 22/10/2019
Make : TOYOTA HARRIER	Assignment Date : 24/10/2019
Date of Inspection : 24/10/2019	Est. Duration of Repair : 3.00
Inspection At : EURO SUCCESS SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY SINGAPORE 417883	

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

	:S\$	
Repairer's Estimate (Gross)	:S\$	12,305.69
Revised Amount	:S\$	2,900.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
<b>Total</b>	<b>:S\$</b>	<b>2,900.00</b>
Lump Sum Repair	:S\$	
<b>Total Loss Consideration</b>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### **Remarks**

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019		24 Oct 2019 10:15 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>[Created by insurer]</b>									
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	SHAIKH MOHAMED FIQRI BIN MOHAMED FRAIJ, ID: S9815635F, Tel: +6596756426, Email: NOEMAIL								
Main Claimant:	Koay Saw Eng, ID: S6973929F								
Vehicle Reg. No.:	SLR1159H	Date of Loss:	22/10/2019 20:00 - :59 [26 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-001267	Policy/Cover Note No.:	MSD/VMS/19-401243 (TP, Fire & Theft) Coverage: 01/07/2019 - 23/10/2020						
Vehicle Reg. No. (Insured):	FBH8573U	Policy No. (Claimant):	Excess:						
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel: 6594 2544								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 25/10/2019]</b>								
Driver/Custodian (Insured):	SHAIKH MOHAMED FIQRI BIN MOHAMED FRAIJ (21 / Male), NRIC: S9815635F, Tel: +6596756426 Email: NOEMAIL								
Adj Asg. Remarks:	on WP, Liab: clear, Agree on SJE. Assign: LKK Auto Consultants Pte Ltd, Contact: Ah Huat @ 6742 6231 / 9828 9277.								
			View All	Compose Case Mail					
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SLR1159H (MSC/V/19-001267)**  
**[FBH8573U]**

TP  
Kgay Saw Eng  
Oct 22 2019 8:00PM  
[SHAIKH MOHAMED FIQRI BIN MOHAMED FRAIJ]  
Euro Success Services Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 25/10/2019 10:04 AM.  
**To** MSI\_WCS  
**Subject** TP SURVEY SLR 1159H

Dear Katherine,

Please be informed that we have inspected the vehicle SLR 1159H on 24/10/2019.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

## Infratint Automotive Film

## Pickup trucks

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Owner's Second Car With Warranty.



Owner's Second Beautiful Car  
With Warranty. Low Mileage.  
Direct Owner StarAd

**HIN LUNG AUTO**  
Ho Bee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars  
30 years of car sale

Browse by Category

[Back](#) ( 1 2 3 ) [Next](#) >

Sort by Date Posted  20 results/page

44 vehicles

toyota harrier

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	toyota harrier		Any	Any	2017	Any	Any	Any	Available
	Toyota	Harrier 2.0A G-Grade Turbo	\$123,800	\$12,550 /yr	30-Dec-2017	1,998 cc	7,000 km	SUV	Available
<p>In House Finance Or Bank Loan Available, Borneo Motor 5 Years Warranty, Full Serviced Records. Road Tax Till Dec 2019. High Trade In... Speedo Motoring</p> <p>Posted: 24-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									
	Toyota	Harrier 2.0A G-Grade Turbo	\$130,588	\$13,390 /yr	29-Dec-2017	1,998 cc	29,156 km	SUV	Available
<p>Toyota Harrier Turbo 2.0 Premium Luxury Edition From Borneo Motors. Flagship Model. Fully Maintained And 7 Years Unlimited Mileage... Speedo Motoring</p> <p>Posted: 24-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									
	Toyota	Harrier 2.0A M-Grade Turbo	\$126,668	\$13,970 /yr	15-Aug-2017	1,998 cc	31,188 km	SUV	Available
<p>Borneo Motors Unit. Unique Dark Blue Mica Metallic Colour. Toyota Harrier Turbo 2.0 Elegance Edition. Flagship Model. Fully Maintained... Inchape Pre-Owned</p> <p>Posted: 23-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									
	Toyota	Harrier 2.0A G-Grade Turbo	\$120,800	\$12,430 /yr	31-Oct-2017	1,998 cc	22,600 km	SUV	Available
<p>5 Year Unlimited Mileage Warranty By Borneo Motors. Well Maintained By 01 Owner. Powerful And Smooth Transmission. Most Popular Ja... Speedo Motoring</p> <p>Posted: 23-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									
	<p>Lee Sheng Auto Pte Ltd - Specialist for Toyota Car repair, servicing &amp; maintenance Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting. More info about this shop</p>								
	Toyota	Harrier 2.0A Elegance Panoramic	\$108,800	\$11,710 /yr	03-Nov-2017	1,986 cc	18,213 km	SUV	Available
<p>Driven By Only 1 Mature Owner Who Takes Extra Care For This Harrier! Low Mileage Only Done 18K, Highest ARF Value At 29558! View... Speedo Motoring</p> <p>Posted: 23-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									
	Toyota	Harrier 2.0A Elegance Panoramic	\$99,500	\$11,470 /yr	14-Feb-2017	1,986 cc	38,022 km	SUV	Available
<p>1 Owner! Unlike Others, This Vehicle Is 100% Accident Free! STA / Vicom / Own Workshop Inspection Welcome! New Car Add 2k For U... Speedo Motoring</p> <p>Posted: 23-Oct-2019 <small>Tags: 2017 Toyota Harrier, 2017 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota</small></p>									

[Compare](#)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	929F
<b>Vehicle Details</b>	
Vehicle No.:	SLR1159H
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 CVT
Primary Colour:	Purple
Manufacturing Year:	2016
Engine No.:	3ZRB912518
Chassis No.:	ZSU600092200
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,840.00
Original Registration Date:	31 Jul 2017
First Registration Date:	31 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$33,776.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2027
PARF Rebate Amount:	\$25,332.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$36,889.00
<b>Total Rebate Amount:</b>	<b>\$62,221.00</b>

The information contained herein is correct as at 24 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/10/2019 16:31
Date Of Accident	22/10/2019 20:10
Exact Location Of Accident	BEDOK NORTH RD TWDS TAMPINES AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR1159H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOAY SAW ENG
NRIC No	S6973929F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97649567
Alternative Phone No	OFFICE-97649567

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA486447
Cover Note Number	

### Driver

Name of Driver	KOAY SAW ENG
NRIC No	S6973929F
Date Of Birth	04/04/1969
Occupation	INDOOR
Date Of Driving Pass	11/09/2008
Driving Experience	11 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97649567
Fax Number	
Contact Number	OFFICE-97649567
EMail Address	NOEMAIL

Address	BLK 714 PASIR RIS ST 72 #04-29
Postcode	510714
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KOAY LAY KHUAN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE ABOVE STATED DATE AND TIME, I WAS TRAVELLING ALONG BEDOK NORTH ROAD. I WAS TRAVELLING STRAIGHT WHEN SUDDENLY, I HEARD A VERY LOUD BANG ON MY VEHICLE REAR PORTION CAUSING MY VEHICLE TO MOVE FORWARD. I THEN JAM BRAKE TO PREVENT MY VEHICLE FROM COLLIDING ONTO THE VEHICLE IN FRONT. AFTER THAT, I ALIGHTED AND NOTICED THAT VEHICLE B HAD COLLIDED ONTO MY VEHICLE REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH8573U
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	96757426
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurers] who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, I was traveling along Bedok North Road. I was traveling straight when suddenly I heard a very loud bang on my vehicle rear portion causing my vehicle to moved forward. I then jam brake to prevent my vehicle from colliding on to the vehicle in front. After that I alighted and noticed that vehicle B have collided onto my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PPN No.:

EURO SUCCESS SERV PTE. LTD  
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SLR1159H

Model: TOYOTA HARRIER

Not Authorized  
Lkh  
4/5 \* 2900 /  
3day.  
The photo After repair

QTY	List Items	Price S
1	REAR TAILGATE 1712.05	2798.70
1	REAR TAILGATE GLASS MOULDING	187.98
1	REAR TAILGATE INNER LOCK	17 487.60 X
1	REAR TAILGATE STRIKER LOCK	17 89.14 X
1	REAR TAILGATE OUTER HANDLE	17 250.30 X
1	REAR TAILGATE EMBLEM	11 68.80 X
1	REAR TAILGATE HARRIER EMBLEM	11 63.98 ✓
1	REAR L/H TAILGATE LAMP	17 650.00 X
1	REAR TAILGATE INNER BOARD	17 596.98 X
1	REAR TAILGATE RUBBER	17 182.62 X
1	REAR END PANEL	17 695.90 X
1	REAR END PANEL INNER BOARD	17 927.60 X
1	REAR END PANEL SENSOR SWITCH	17 190.90 X
1	REAR BUMPER 1085-50	1887.95
1	REAR BUMPER SPONGE	17 110.76 ✓
2	REAR BUMPER REFLECTOR @45.5	17 91.00 X
1	REAR BUMPER BEAM	17 168.18 X
2	REAR L-R BUMPER RETAINER @89.6	17 179.20 X
TOTAL		\$9,627.59
LESS 25%		\$2,406.90
TOTAL		\$7,220.69

Special Nett Items		
1 SET	REAR BUMPER SENSOR	800.00 X
1 SET	REAR BUMPER CLIP	45.00 ✓
1 SET	REAR TAILGATE INNER BOARD CLIP	45.00 X
1 SET	REAR END PANEL INNER BOARD CLIP	45.00 X
1	REAR TAILGATE GLASS SEALANT	80.00 ✓
1	REAR NUMBER PLATE WITH BOX	50.00 X

\$1,065.00

P- 3160.27  
257  
P- 2370.20  
S.N- 85.00  
L- 1210.00  
3665.20  
207.  
2932.10

Labour Charges

TO REMOVE & REFIX REAR WINDSCREEN GLASS	200.00	120
TO APPLY UNDERCOATING ON ACCIDENT AFFECTED PARTS	350.00	30
TO TRANSFER REAR TAILGATE MECHANISM TO FACILITATE REPAIR	90.00	60
TO DISMENTLE & REPLACING REVERSE SENSOR	17 80.00	X
TO PROVIDE LABOUR, WORKMANSHIP TO DISMENTLE THE ABOVE MENTIONED PARTS INCLUDE OF CUT, WELD AND RE ALIGN BODY STRUCTURE AND DAMAGE PARTS CAUSED BY THE ACCIDENT	1800.00	400
TO RESPRAY PAINT ON ACCIDENT AFFECTED PARTS	1500.00	600
	<b>\$4,020.00</b>	

**ESTIMATE PARTS AND LABOUR GRAND TOTAL**

**\$12,305.69**

Auto Consultants hence notify the Repairer of the following:

- To estimate labour after spray painting
- To estimate damaged parts during resurvey
- To estimate repair subject to confirmation
- To estimate labour on a "Without Prejudice" basis
- To estimate (if applicable) is allowed
- To estimate items must be reviewed and subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018852/UVF3N2

Date: 31/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-401243
Claimant Vehicle No :	SLR1159H	Insured Vehicle No :	FBH8573U
Date of Loss:	22/10/2019	Nature of Claim:	TP
		Claim No:	MSCV/19-001267

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR1159H	Engine No:	3ZRB912518
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600092200
Reg. Date:	31/07/2017 (Man. Year: 2016)	Odometer:	79920 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65R17	Rear Tyre Size:	225/65R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,285.69	2,455.20	5,830.49	70.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,210.00	2,810.00	69.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,305.69</b>	<b>3,665.20</b>	<b>8,640.49</b>	<b>70.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,305.69</b>	<b>2,900.00</b>	<b>9,405.69</b>	<b>76.43</b>

INSPECTION

Date of Assignment:	24/10/2019	
Date Inspected:	24/10/2019	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2019)
<b>Parts:</b> M1-SUV	TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLR1159H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented/Bent	2,798.70 FL	*1,712.05 FL
2	1		*REAR TAILGATE GLASS MOULDING	Necessary	187.98 FL	*187.98 FL
3	1		*REAR TAILGATE INNER LOCK	Not Necessary	487.60 FL	*- FL
4	1		*REAR TAILGATE STRIKER LOCK	Not Necessary	89.14 FL	*- FL
5	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	250.30 FL	*- FL
6	1		*REAR TAILGATE EMBLEM	Not Necessary	68.80 FL	*- FL
7	1		*REAR TAILGATE HARRIER EMBLEM	Necessary	63.98 FL	*63.98 FL
8	1		*REAR L/H TAILGATE LAMP	Not Necessary	650.00 FL	*- FL
9	1		*REAR TAILGATE INNER BOARD	Not Necessary	596.98 FL	*- FL
10	1		*REAR TAILGATE RUBBER	Not Necessary	182.62 FL	*- FL
11	1		*REAR END PANEL	Repair	695.90 FL	*- FL
12	1		*REAR END PANEL INNER BOARD	Not Necessary	927.60 FL	*- FL
13	1		*REAR END PANEL SENSOR SWITCH	Not Necessary	190.90 FL	*- FL
14	1		*REAR BUMPER	Dented/Deformed	1,887.95 FL	*1,085.50 FL
15	1		*REAR BUMPER SPONGE	Torn	110.76 FL	*110.76 FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	91.00 FL	*- FL
17	1		*REAR BUMPER BEAM	Not Necessary	168.18 FL	*- FL
18	2		*REAR L-R BUMPER RETAINER	Not Necessary	179.20 FL	*- FL
19	1		*SET REAR BUMPER SENSOR	Serviceable	800.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
21	1		*SET REAR TAILGATE INNER BOARD CLIP	Not Necessary	45.00 FS	*- FS
22	1		*SET REAR END PANEL INNER BOARD CLIP	Not Necessary	45.00 FS	*- FS
23	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*REAR NUMBER PLATE WITH BOX	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,692.59</b>	<b>3,245.27</b>
- List Item Discount on L Items 25.00/25.00% (S\$)	2,406.90	790.07
<b>Total Parts (S\$)</b>	<b>8,285.69</b>	<b>2,455.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
2	TO APPLY UNDERCOATING ON ACCIDENT AFFECTED PARTS	New	350.00	30.00
3	TO TRANSFER REAR TAILGATE MECHANISM TO FACILITATE REPAIR	New	90.00	60.00
4	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	0.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO DISMENTLE THE ABOVE MENTIONED PARTS INCLUDE OF CUT, WELD AND RE-ALIGN BODY STRUCTURE AND DAMAGE PARTS CAUSED BY THE ACCIDENT	New	1,800.00	400.00
6	TO RESPRAY PAINT ON ACCIDENT AFFECTED PARTS	New	1,500.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>4,020.00</b>	<b>1,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >