

### SERVICE ESTIMATE

38671 - C00001 SL: SERVICE SALES - PC

Mr Choo Poh Guan Nicky  
8L East Coast Avenue

Singapore  
Singapore 454958

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 22/10/2019

WIP No. . : 43791

Veh.In/Out:

\*Tel.No. . :

Reg.No. . : SKD2228X

Reg.date . : 24/06/2016

Mileage . : 0

Chassis No: SALCA2AG9GH619251

Closed by . : Patricia Kueh Anak S

Svc Consultant :

Remarks . : Mr Choo Poh Guan Nic

| Op.No | Description | Mech | Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|------|-----|-------|-------|-----|--------|---|
|-------|-------------|------|-----|-------|-------|-----|--------|---|

|     |                                                                                       |  |   |         |   |  |          |   |
|-----|---------------------------------------------------------------------------------------|--|---|---------|---|--|----------|---|
| 802 | TO REPLACE REAR BUMPER,<br>REAR EXHAUST RH, RHR REFLECTOR<br>REPAIR REAR BOOTLID, ETC |  | 0 | 3600.00 | 0 |  | 3,600.00 | S |
|-----|---------------------------------------------------------------------------------------|--|---|---------|---|--|----------|---|

|     |                                                                            |  |   |         |   |  |          |   |
|-----|----------------------------------------------------------------------------|--|---|---------|---|--|----------|---|
| 800 | TO PUTTY SPRAYPAINT, BLEND<br>REAR BUMPER, BOOTLID,<br>REAR RH FENDER, ETC |  | 0 | 3000.00 | 0 |  | 3,000.00 | S |
|-----|----------------------------------------------------------------------------|--|---|---------|---|--|----------|---|

|     |                                                                   |  |   |        |   |  |        |   |
|-----|-------------------------------------------------------------------|--|---|--------|---|--|--------|---|
| 280 | TO CHECK WIRING INCLUDE<br>RESETTING OF ALL ELECTRICAL<br>MODULES |  | 0 | 510.00 | 0 |  | 510.00 | S |
|-----|-------------------------------------------------------------------|--|---|--------|---|--|--------|---|

|                       |        |         |  |          |   |
|-----------------------|--------|---------|--|----------|---|
| LLR073071/BUMPER - R  | 1.0 EA | 1640.70 |  | 1,640.70 | S |
| LAMP - FOG - REAR     | 1.0 EA | 337.00  |  | 337.00   | S |
| MUFFLER - REAR RH     | 1.0 EA | 2916.80 |  | 2,916.80 | S |
| CLAMP                 | 1.0 EA | 179.60  |  | 179.60   | S |
| MOULDING - REAR WHEEL | 1.0 EA | 297.50  |  | 297.50   | S |
| D PILLAR FINISHER RH  | 1.0 EA | 100.90  |  | 100.90   | S |
| ADHESIVE SEALER FL2   | 1.0 EA | 669.10  |  | 669.10   | S |

Gross Total. 13,251.60

|               |          |
|---------------|----------|
| Labour Total  | 7,110.00 |
| Parts Total   | 6,141.60 |
| Package Total | 0.00     |

|              |           |
|--------------|-----------|
| Net.....     | 13,251.60 |
| GST @ 7.0%   | 927.61    |
| Total.....   | 14,179.20 |
| Paid.....    | 0.00      |
| Please Pay.. | 14,179.20 |

GST: S=StdRated; O=OutOfScope; Z=ZeroRated