



Cecilia

### Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : PC3579Y

Accident date : 19/10/19

Model No : Man ( A69-6.9 D A)

Registered owner : Singapore Ducktours Pte Ltd

Date of Estimates : 8/11/19

#### Labour Charges

#### Total Charges.

1. Spray painting on affected parts and Putty sand and make good surface ~~S\$680~~ 300
2. To repair adjust and refit front bumper ~~S\$600~~ 300

Rasul  
Hp 90010068  
2 days  
P/P  
06/11/19 @ 1710  
Resurvey after repair

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

600  
2 days  
P/P

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg