

LEONG AUTO PTE LTD

160, Sin Ming Drive, Sin Ming Autocity, #02-13, Singapore 575722
 Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
 Business Registration No. 201312846W
 GST Registration No. 201312846W

Not Authorised ESTIMATE
11 Days 8?
Recovery After Paint
 Date: 23-10-2019
 DOA: 22-10-2019
 10-12 days

Vehicle No: SMJ7345C
 Make & Model: Toyota Harrier

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Tail Gate	\$ 1,943.70	✓
2	1	Rear Tail Gate Windscreen Moulding	\$ 225.10	✓
3	1	Rear Tail Gate Centre Logo	\$ 118.20	✓
4	1	Rear Tail Gate Centre Logo Garnish	\$ 622.10	✓
5	1	Rear Tail Gate "HARRIER" Emblem	\$ 81.30	✓
6	1	Rear Tail Gate "TURBO" Emblem	\$ 68.00	✓
7	1	Rear Tail Gate Lock Mechanism	\$ 641.10	✓
8	1	Rear Tail Gate Lock Catch	\$ 43.20	✓
9	1	Rear Tail Gate Weatherstrip	\$ 422.80	✓
10	1	Rear Tail Gate Wiper Motor	\$ 419.00	✓
11	1	Rear Tail Gate Inner Trim Board	\$ 834.80	✓
12	2	Rear Tail Gate Inner Handle	\$ 236.20	✓
13	2	Rear Tail Gate Reflector Lamp	\$ 1,302.50	✓
14	1	Rear Tail Gate Outer Garnish(Top)	\$ 268.80	✓
15	1	Rear Tail Gate Outer Garnish(Bottom)	\$ 748.60	✓
16	1	Rear Tail Gate Outer Garnish(Bottom) Opening Switch	\$ 256.50	✓
17	2	Rear Tail Gate No. Plate Lamp	\$ 382.20	✓
18	2	Rear Tail Gate Hydraulic Damper	\$ 849.20	✓
19	1	Rear Parking Camera	\$ 584.50	✓
20	2	Rear Tail Lamp	\$ 1,527.60	✓
21	2	Rear Tail Lamp Base Panel	\$ 845.20	✓
22	2	Rear Tail Lamp Retainer	\$ 398.70	✓
23	1	Rear End Panel (Outer)	\$ 645.40	✓
24	1	Rear End Panel (Inner)	\$ 656.40	✓
25	1	Rear End Panel Top Garnish	\$ 421.00	✓
26	1	Rear End Panel Beep Sound	\$ 142.50	✓
27	1	Rear End Panel Bracket	\$ 264.50	✓
28	2	Rear Fender Inner Trim Board	\$ 1,670.20	✓
29	1	Rear Floor Panel	\$ 727.60	✓
30	1	Rear Floor Panel Top Board	\$ 513.80	✓
31	1	Rear Floor Panel Top Tools Sponge	\$ 451.20	✓
32	1	Rear Floor Panel Top Tray Outer L/H	\$ 368.60	✓
33	1	Rear Floor Panel Top Tray Outer R/H	\$ 368.60	✓
34	1	Rear Floor Panel Top Tray Inner L/H	\$ 321.90	✓
35	1	Rear Floor Panel Top Tray Inner R/H	\$ 321.90	✓
36	1	Rear Floor Panel Top Tray Centre	\$ 629.60	✓
37	1	Rear L/H Door	\$ 1,504.60	✓
38	1	Rear L/H Door Lock Mechanism	\$ 488.50	✓
39	1	Rear L/H Door Inner Trim Board	\$ 834.80	✓
40	1	Rear L/H Door Weatherstrip	\$ 248.40	✓
41	1	Rear L/H Door Lower Weatherstrip	\$ 125.70	✓
42	1	Rear Bumper	\$ 1,517.70	✓
43	2	Rear Bumper Reflector	\$ 210.00	✓
44	2	Rear Bumper Retainer	\$ 147.90	✓
45	2	Rear Bumper Bracket	\$ 362.90	✓
46	1	Rear Bumper Reinforcement	\$ 627.00	✓
47	1	Rear Bumper Sponge	\$ 126.40	✓

48	1	Rear Bumper L/H Air Duct		\$	522.70	?
49	1	Rear Bumper Lower Lip	CM	\$	436.70	✓
50	2	Rear Bumper Parking Sensor	pr? sha	\$	1,089.80	✓
51	2	Rear Bumper Parking Sensor Holder		\$	97.10	?
				\$	28,662.70	
Less 25%				\$	7,165.68	
				\$	21,497.03	
<u>Special Nett Items</u>						
1		Sundries		\$	50.00	?
2	1	Rear Tail Gate Windscreen Sealant	na	\$	120.00	401m
3	1	Rear Tail Gate Windscreen Damping Seal	na	\$	120.00	301m
4	1 set	Rear Tail Gate Outer Garnish (Top) Clips	na	\$	80.00	—
5	1 set	Rear Tail Gate Outer Garnish (Bottom) Clips	na	\$	80.00	—
6	1 set	Rear Tail Gate Inner Trim Board Clips	na	\$	80.00	✓
7	2	Rear Tail Lamp Sealant		\$	80.00	?
8	2 set	Rear Tail Lamp Clips	na	\$	50.00	✓
9	1	Rear End Panel (Outer) Sealant	na	\$	120.00	301m
10	1	Rear End Panel (Inner) Sealant		\$	120.00	?
11	1 set	Rear End Panel Top Garnish Clips	na	\$	80.00	✓
12	1	Rear Floor Panel		\$	150.00	?
13	1 set	Rear Floor Panel Top Tray Outer L/H Clips	na	\$	50.00	X
14	1 set	Rear Floor Panel Top Tray Outer R/H Clips	na	\$	50.00	X
15	1 set	Rear Floor Panel Top Tray Inner L/H Clips	na	\$	50.00	X
16	1 set	Rear Floor Panel Top Tray Inner R/H Clips	na	\$	50.00	X
17	1 set	Rear Floor Panel Top Tray Centre Clips	na	\$	50.00	X
18	2 set	Rear Fender Inner Trim Board Clips		\$	80.00	?
19	2 set	Rear Fender Inner Shield Clips	na	\$	50.00	X
20	1 set	Rear Bumper Clips	na	\$	50.00	✓
21	2 set	Rear Bumper Reflector Clips	na	\$	50.00	X
22	1 set	Rear Bumper Lower Lip Clips	na	\$	120.00	✓
23	1 set	Number Plate with Garnish	na	\$	80.00	X
				\$	1,810.00	
Total parts				\$	23,307.03	
S/N	Labour Description			Amount	Amount	
	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.			\$	2,200.00	?
1	To putty and spray painting rear portion.			\$	1,600.00	1200
2	To check rear lighting and wiring.			\$	80.00	200
3	To remove and install rear tail gate lock mechanism.			\$	120.00	600
4	To remove and install rear seat, inner garnish and trim to facilitate the repair.			\$	380.00	1200
5	To apply anti rust proofing to rear affected area.			\$	250.00	?
6	To remove and install rear reverse sensor.			\$	80.00	600
7	To remove and install rear windscreen.			\$	150.00	1200
8	To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage			\$	120.00	600
9	Total labour :			\$	4,980.00	
Total parts :				\$	23,307.03	
Total labour :				\$	4,980.00	
Total repair cost : (Before GST)				\$	28,287.03	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: