

INS. CASE OWNER:

Surveyor:

Pre-assign / CCU / FTE

Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :\$

Is driver the owner?

If NO. Driver Name / Age :

Driver Tel No. :

DOI:

(V/L: YES / NO)

Insured Liability :

Final ? Yes / No

Date / Time :

Registered in Merimen:

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

Final ? Yes / No

G6E 66892

INSRS:
WSP:
Tel:
Liability:
RMKS:Tong
LuckINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

2800.00

15

days

Reduction:

5290.50

46

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

W.

If NO or B 28, Ass. Lia.:

Repair Cost:

\$

2926.00

Loss of Rental (LOR):

\$

-

(days)

Loss of Use (LOU):

\$

420.00

(\$ 60 x 7

days)

100 x 7 = 700

Loss of Income (LOI):

\$

-

(\$ x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$

29.00

Medical:

\$

-

Disbursement:

\$

-

(e.g. Tow/ Independent)

Legal Cost

\$

-

(3775)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$

3440.00

Global Sum \$:

3440.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

3440.00

Name 1:

Tong Luck Auto Pte Ltd.

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

ASS. REG. BY:

REP: ASM (AXA)

ASSIGNMENT

From: _____ Date: 24.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 6689Z

at Workshop m/s Tong Luck Auto

of 160 Sin Ming Drive #07-01/06

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 854K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GA / DR Scen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE 6689Z (r Regn: 02 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Hiace C.C. 2982

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 62196 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFH702P100191018

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 9/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 24/10/19



Date / Time

Action / Instruction

4/5 \$2800/- (Red = \$2392.50 / 46%)

* 5 repair days + 1 PPS + 1 Sunday = 7 days.

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Form:

Comp. Sum / M.B. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Wind end (\$

Survey Fee:

Transportation:

S + PS = \$

Photos

Other

TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJC5892A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 09/10/2019

TP VEH REG NO : SJC5892A

ESTIMATE

NO : QUOT201910-000055(00)

DATE : 22/10/2019

POLICY NO : 999995580

VEH REG NO : GBE6689Z

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02P100191018

ENGINE NO : 1KD2594346

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBE6689Z

Description	Quantity	Unit Price	Amount
		S\$	S\$

LIST PRICE

1 Tailamp-assy - LH	1	280.00	280.00
2 Tailamp-lower garnish - LH	1	85.00	85.00
3 Rear fender - LH	1	1,700.00	1,700.00
4 Rear bumper	1	390.00	390.00
5 Rear bumper clips	15	5.00	75.00
6 Rear wheel hup cap - LH	1	180.00	180.00

2,710.00

Less 25% 677.50

2,032.50

LABOUR

7 To remove and refit rear bumper sensor	1	100.00	100.00
8 To check and rectify wiring system	1	80.00	80.00
9 To remove and refix LH rear fender interior garnishes and trimboard to facilitate the repair	1	120.00	120.00
10 To computerised check wheel alignment	1	80.00	80.00
11 To panel beat and straighten LH tailamp panel, LH rear chassis frame, to cut and weld out LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
12 To putty and spray same on affected areas	1	800.00	800.00
13 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
14 To supply artwork and paste sticker on LH body panel	1	1,100.00	1,100.00

3,160.00

TOTAL S\$ 5,192.50

ADD GST @ 7% 363.48

GRAND TOTAL S\$ 5,555.98

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-FIVE AND CENTS NINETY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJC5892A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 09/10/2019

TP VEH REG NO : SJC5892A

ESTIMATE

NO : QUOT201910-000055(00)

DATE : 22/10/2019

POLICY NO : 999995580

VEH REG NO : GBE6689Z

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02P100191018

ENGINE NO : 1KD2594346

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBE6689Z

Description	Quantity	Unit Price	Amount
LIST PRICE		S\$	S\$
1 Taillamp assy - LH	1	280.00	280.00
2 Taillamp lower garnish - LH	1	85.00	85.00
3 Rear fender - LH	1	1,700.00	1,700.00
4 Rear bumper	1	390.00	390.00
5 Rear bumper clips	15	5.00	75.00
6 Rear wheel hup cap - LH	1	180.00	180.00
			2,710.00
			Less 25%
			677.50
			2,032.50
LABOUR			
7 To remove and refit rear bumper sensor	1	100.00	100.00
8 To check and rectify wiring system	1	80.00	80.00
9 To remove and refit LH rear fender interior garnishes and trimboard to facilitate the repair	1	120.00	120.00
10 To computerised check wheel alignment	1	80.00	80.00
11 To panel beat and straighten LH taillamp panel, LH rear chassis frame, to cut and weld out LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
12 To putty and spray same on affected areas	1	800.00	800.00
13 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
14 To supply artwork and paste sticker on LH body panel	1	1,100.00	1,100.00
			3,160.00
TOTAL			S\$ 5,192.50
ADD GST @ 7%			363.48
GRAND TOTAL			S\$ 5,555.98

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-FIVE AND CENTS NINETY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

 <MANDATE IA> - S9M023B3 {ACCIDENT INVOLVING
SJC 5892A & GBE 6689Z ON 09/10/2019}

Type

 Question

Message

LIABILITY: 100% BOLA S10 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3725.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/12/2019

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/12/2019

Survey Details:

Date of loss	9-Oct-19
Date of appointment	24-Oct-19
Date of survey	24-Oct-19
Location of survey	TONG LUCK AUTO PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBE 6689Z
Make and Model	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Date of registration	24/2/2016
Excess	
Market Value	\$54,000
Parf Rebate	\$25,744
Nett Loss	\$28,256

Repair details:

Initial Estimate	\$ 5,192.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,623.75
Check items (estimate)	\$ -
Labour	\$ 1,920.00
Total	\$ 3,543.75
Lump Sum(if applicable)	\$ 2,800.00
Number of days for repair	5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

05 RECOMMENDED REPAIR DAYS + 1PRS + 1SUNDAY = 7DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,996.00	W/GST
Loss of use	\$ 700.00	7days x \$100
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 29.00	
Others	\$ -	
Proposed Total	\$ 3,725.00	



**Re:<MANDATE IA> - S9M023B3 {ACCIDENT INVOLVING
SJC 5892A & GBE 6689Z ON 09/10/2019}**

Type

🔍 Question

Message

Please proceed

Reply

JE-GRAPHICS PTE LTD

48 Toh Guan Road East
#08-123 EnterpriseHub
Singapore 608586
Tel: 6316-7246 Fax: 6316-7248
E-MAIL: sales@jegraphics.com.sg
GST REG NO.: 200504725D
CO REG NO.: 200504725D

TO: TONG LUCK AUTO PTE LTD

TAX INVOICE : 20191037

ATTN : Terence Tan
TEL/FAX : 9623 5378

DATE : 31/10/2019
P/O :
D/O :
TERMS : CASH
SALESMAN CODE : PN
PAGE NO. : 001

NO.	DESCRIPTION	QTY UOM	UNIT-PRICE	AMOUNT
			SGD	SGD
	GRAPHIC REINSTATEMENT ON GBE6689Z TOYOTA HIACE	1.000 LOT	680.00	680.00

TO REINSTATE WORK ON LEFT BODY

JE REF: JE/2019/10128

SUB-TOTAL 680.00


ADD 7.00% GST 47.60
TOTAL 727.60

SINGAPORE DOLLARS: SEVEN HUNDRED TWENTY-SEVEN & CENTS SIXTY ONLY

Cheque should be crossed and made payable to JE-GRAPHICS PTE LTD.
1.5% interest shall be charged for all overdue invoices. Discrepancies if any, should be verified within 7 days from date hereof. Deposit are not refundable & transferable.

E. & O.E

JE-GRAPHICS PTE LT





TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBE6689Z

Yours Ref : SJC5892A

AXA INSURANCE SINGAPORE PTE LTD

02 December 2019

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBE6689Z & SJC5892A ON 09/10/2019 @ 17:40 HRS ALONG UBI CRESCENT UBI TECHPARK LOBBY E CARPARK

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair	:	S\$2,996.00
Loss of Use (\$ 100.00 x 5 days)	:	S\$500.00
Additional Loss of Use (\$100.00 x 2days) – Weekend/PH:	:	S\$200.00
GIA / LTA Search	:	S\$29.00
		<u>S\$3,725.00</u>

Kindly revert within SEVEN days. Failing which we reserve our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

**TONG LUCK AUTO PTE LTD**

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
 1 GATEWAY DRIVE
 #15-08 WESTGATE TOWER
 SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : SJC5892A
 CLAIM TYPE : THIRD PARTY
 ACCIDENT DATE : 09/10/2019
 TP VEHICLE NO : SJC5892A

TAX INVOICE

NO : AR201912-0004
 CLAIM NO : QUOT201910-000055(01)
 DATE : 02/12/2019
 POLICY NO : 999995580
 VEH REG : GBE6689Z
 MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
 TURBO 5 DR MANUAL
 CHASIS NO : JTFHT02P100191018
 ENGINE NO : 1KD2594348
 REG. DATE : 2016

Final Repair Cost to Vehicle No : GBE6689Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
LIST PRICE			
1 Rear fender - LH	1	1,700.00	1,700.00
2 Rear bumper	1	390.00	390.00
3 Rear bumper clips	15	5.00	75.00
			2,165.00
		Less 25%	541.25
			1,623.75
DISCOUNT			
4	-1	743.75	-743.75
LABOUR			
5 To remove and refit rear bumper sensor	1	50.00	50.00
6 To check and rectify wiring system	1	20.00	20.00
7 To remove and refit LH rear fender interior garnishes and trimboard to facilitate the repair	1	80.00	80.00
8 To computerised check wheel alignment	1	60.00	60.00
9 To panel beat and straighten LH taillamp panel, LH rear chassis frame, to cut and weld out LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	600.00	600.00
10 To putty and spray same on affected areas	1	400.00	400.00
11 To apply rust proofing on repaired and replaced panels	1	30.00	30.00
12 To supply artwork and paste sticker on LH body panel	1	680.00	680.00
			1,176.25
TOTAL:			S\$2,800.00
ADD GST @ 7%:			196.00
GRAND TOTAL:			S\$2,996.00

SINGAPORE DOLLARS TWO THOUSAND NINE HUNDRED AND NINETY-SIX AND CENTS ZERO ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : SJC5892A

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 09/10/2019

TP VEHICLE NO : SJC5892A

TAX INVOICE

NO : AR201912-0004
CLAIM NO : QUOT201910-000055(01)
DATE : 02/12/2019
POLICY NO : 999995580
VEH REG : GBE6689Z
MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL
CHASIS NO : JTFHT02P100191018
ENGINE NO : 1KD2584346
REG. DATE : 2016

Final Repair Cost to Vehicle No : GBE6689Z

Description	Quantity	List Price	Amount
		S\$	S\$

TONG LUCK AUTO PTE LTD

E & O.E.

AUTHORISED SIGNATURE

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

To: DAIMLER FLEET MANAGEMENT SINGAPORE
PTE. LTD.
1 Gateway Drive #15-08
Westgate Tower
Singapore 608534

Bill No : 19.11/90749
Date : 2 December 2019
Our Ref : LCH.my/jp/SMTLA-90749.19

RE: ACCIDENT INVOLVING YOUR VEHICLE GBE 6689 Z & SJC 5892 A ON 9 OCTOBER 2019

Description	Amount	Total
<i>TO OUR PROFESSIONAL CHARGES</i> in connection with this matter (where necessary) attendance, perusals, preparation and examination of documents and Court Register, preparation of case, appearances in Court when required, correspondence, attendance, perusals, telephone calls, searches and all incidental work necessary for carrying out the business entrusted to us inclusive of all advices.		
<u>Disbursements</u>		
GIA Application to search	\$15.00	
GIA Purchase of report	\$14.00	
		\$29.00
	Total	\$29.00

We reserve the rights to deliver a subsequent bill for any disbursements omitted


CHEONGHOH LAW CORPORATION
Advocates & Solicitors
Singapore

<< Re:<MANDATE IA> - S9M023B3 {ACCIDENT INVOLVING
SJC 5892A & GBE 6689Z ON 09/10/2019}

Type

🔔 Question

Message

Please proceed

Reply

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19018899/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:YVONNE

Date : 19-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJC 5892A	Veh. Inspected	GBE 6689Z
Policy No.	GA438391	Coverage (\$)	0.00
Claim No.	S9M023B3	Excess (\$)	0.00
Assign From		Assign Date	24/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFHT02P100191018	Colour	YELLOW
Odometer	62196	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/10/2019	Inspection Date	24/10/2019
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6689Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILLAMP ASSY-LH (CONSISTENT)	SERVICEABLE	280.00	-
1	TAILLAMP LOWER GARNISH -LH (CONSISTENT)	NOT NECESSARY	85.00	-
1	REAR FENDER -LH (CONSISTENT)	BENT	1,700.00	1,700.00
1	REAR BUMPER (CONSISTENT)	CUT	390.00	390.00
15	REAR BUMPER CLIPS @\$5.00 (CONSISTENT)	NECESSARY	75.00	75.00
1	REAR WHEEL HUP CAP -LH (CONSISTENT)	SERVICEABLE	180.00	-
	LESS 25% DISCOUNT		-677.50	-541.25
			2,032.50	1,623.75
LABOUR				
	TO REMOVE AND REFIT REAR BUMPER SENSOR .		100.00	50.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO REMOVE AND REFIX LH REAR FENDER INTERIOR GARNISHES AND TRIMBOARD TO FACILITATE THE REPAIR .		120.00	80.00
	TO COMPUTERISED CHECK WHEEL ALIGNMENT .		80.00	60.00
	TO PANEL BEAT AND STRAIGHTEN LH TAILLAMP PANEL ,LH REAR CHASSIS FRAME ,TO CUT AND WELD OUT LH REAR FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME.		800.00	600.00
	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS.		800.00	400.00
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.		80.00	30.00
	TO SUPPLY ATWORK AND PASTE STICKER ON LH BODY PANEL.		1,100.00	680.00
			3,160.00	1,920.00
GRAND TOTAL			5,192.50	3,543.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CC4/ASM19018899/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M02383
Reference	CC4/ASM1901899/Kga3a2
Loss Date	9 October 2019
Report Date	10 Oct 2019 12:00:00 AM
Request Date	23 October 2019
Due Date	

Vendor Name	LK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Approve Invoice

Vehicle Information

Incident Vehicle Registration #

G8E6689Z

Make

TRIM TOYOTA

Model

HIACE VAN TURBO 5 DR

Service Address

...

Primary Contact/Insured

JIANG EN ZE

BLK 53 PIHIT ROAD, #14-124, 370053, Singapore
96274819

JIANGENZE@SINGNET.COM.SG

Claim Handler

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type Document Subtype

Upload Document

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LKKAdjustment1a (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 PAIF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 MANDATE IA DD 20122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 BODY STICKER ARTWORK INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 EMAIL FROM WS FOR TP LOD.mng	Letters and Correspondence	Others	NIRAM Santosh Pandurang	6 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP-IA 6689.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2019
 SUC5892A IWS GIA.PDF	Reports & Statement	GIA Report	DHINWAR Namrata	23 October 2019
 TP PRI EMAIL FROM WORKSHOP.pdf	Letters and Correspondence	Third Party	DHINWAR Namrata	23 October 2019
 ESTIMATE & GIB6689Z TP GIA.pdf	Forms / Claim Documents	Estimate / Quotation	DHINWAR Namrata	23 October 2019
 TP PRI EMAIL FROM WORKSHOP.mig	Letters and Correspondence	Workshop	DHINWAR Namrata	23 October 2019