



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJC5892A

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 09/10/2019

TP VEH REG NO : SJC5892A

ESTIMATE

NO : QUOT201910-000055(00)

DATE : 22/10/2019

POLICY NO : 999995580

VEH REG NO : GBE6689Z

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02P100191018

ENGINE NO : 1KD2594346

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBE6689Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Taillamp assy - LH	1	280.00	280.00 X
2 Taillamp lower garnish - LH	1	85.00	85.00 ?
3 Rear fender - LH	1	1,700.00	1,700.00 ✓
4 Rear bumper	1	390.00	390.00 ✓
5 Rear bumper clips	15	5.00	75.00 ✓
6 Rear wheel hup cap - LH	1	180.00	180.00 X
			2,710.00
		Less 25%	677.50
			2,032.50
LABOUR			
7 To remove and refit rear bumper sensor	1	100.00	100.00 500
8 To check and rectify wiring system	1	80.00	80.00 200
9 To remove and refix LH rear fender interior garnishes and trimboard to facilitate the repair	1	120.00	120.00 800
10 To computerised check wheel alignment	1	80.00	80.00 600
11 To panel beat and straighten LH taillamp panel, LH rear chassis frame, to cut and weld out LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 6000
12 To putty and spray same on affected areas	1	800.00	800.00 4000
13 To apply rust proofing on repaired and replaced panels	1	80.00	80.00 300
14 To supply artwork and paste sticker on LH body panel	1	1,100.00	1,100.00 ?
			3,160.00
		TOTAL	S\$ 5,192.50
		ADD GST @ 7%	363.48
		GRAND TOTAL	S\$ 5,555.98

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-FIVE AND CENTS NINETY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE