

ASS-REC. BY:

REF: CS/FCI 19018903/Ut302 Special Instruction:

SUBJECT: Mir/us

ASSIGNMENT (Office)

From (Person): Sithara of FCI Date/Time: 24.10.19 3.06pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Smk 2391X Insured: SHD 8501C

at Workshop m/s Fastech Auto Tel: 67465405

of 1 raki Bukit Ave 6 #01-46/42

Policy No: Claim No: D1900674 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 23.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.10.19 3.18pm Person Contacted: Ling

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMK 2391X - X
	SHD 8501C - X
25/10 @ 4.55pm	sent email pending estimate

ASS. REC. BY:

REP:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA PR Seen:

Consistent?: Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Bm / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/10/19

D.O.I.

24/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 38579 have video

After rep: 5-11-19

16/1/20 Confirmed 4/5 @ 15.000 with ACR. (Red: 31920.81; 68%)

RECEIVED 10 JAN 2020

Date/Time, File Pass to?

1) 16/1 Typist

Date/Time, File Return to?

2)

Enforce Form:

Enforce Form / L.P. /



: Preli. Report



: Final Report

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. invs (\$



: Misc. invs (\$

Survey Fee:

Transportation:

S + PS \$

Parking

Office

TOTAL

37X15 = 555

170+555

50

50+50

190

1065

TP

1510001-

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 25 October 2019 4:55 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006774MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMK 2391X on 24/10/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 24 October 2019 5:28 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006774MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 24 October 2019 3:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006774MFSH/1

MOTOR SURVEY ASSIGNMENT

Date	24-10-2019	Our Ref No. D19006774MFSH
Accident Date	23-10-2019	Claim Type. Third Party
Insured Vehicle	SHD8501C	Third Party Vehicle. SMK2391X
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	LINA	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



guidebook

Build a beautiful mobile app in 4 easy steps.

LEARN MORE

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Feb 2018 Mercedes-Benz C180 Avantgarde, 1 Owner!



Lowest Price & Interest In

Market! Near New Car Car

Condition! View To Believe!

Auto Zoom Enterprise StarAd



click here to view

our PRISTINE USED CARS

at GREAT PRICES

Browse by Category

Back (1 2) Next

Sort by Date Posted

20 results/page

23 vehicles

Vezel

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Vezel		Any	Any	2019	Any	Any	Any	Available
	Honda	Vezel 1.5A X Honda Sensing	\$85,800	\$8,130 /yr	20-Jun-2019	1,496 cc	10 km	SUV	Available
5 Years Warranty! 3 x Free Servicing! 2019 Latest Model! Vitas Ready Stock Of White, Flexible Loan And High Trade In. Dynamic And Re... Shuang Hup Credit									
Posted: 24-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$86,800	\$7,970 /yr	14-Oct-2019	1,496 cc	56 km	SUV	Available
New Facelift 2018, Almost New, Grey, With Warranty, Reliable And Outstanding Car, Low Maintenance Cost, PHV 100% 10 Years Loan A...									
Posted: 24-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$91,800	\$8,650 /yr	26-Jul-2019	1,496 cc	-	SUV	Available
Good Condition. Non-Sensing. Please Call For Viewing.									
Posted: 19-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X Honda Sensing (OPC)	\$75,777	\$7,270 /yr	27-Feb-2019	1,496 cc	-	SUV	Available
2019 Model Vezel, Vitas Ready, Deliver Immediate, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Existing C...									
HTS Motor									
Posted: 18-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Door Visor Honda Vezel Door Visor / Honda HRV Door Visor More info about this product.								
	Honda	Vezel 1.5A X	\$86,800	\$8,540 /yr	27-Feb-2019	1,496 cc	800 km	SUV	Available
Excellent Condition Unit With Low Mileage Clocked. Comes With 4 x Free Servicing, Premium Solar Film, In Car Camera (Front And Rear)...									
Posted: 15-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel Hybrid 1.5A X	\$99,800	\$9,700 /yr	25-Jan-2019	1,496 cc	1,900 km	SUV	Available
Fuel Type: Petrol-Electric 1 Owner Owned Honda Vezel Hybrid 1.5X. Low Mileage Clocked! Nice Leather Interior! Regularly Serviced And Maintained By Seller! Ori...									
Posted: 15-Oct-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
Compare	Honda	Vezel Hybrid 1.5A X	\$99,800	\$9,550 /yr	19-Mar-2019	1,496 cc	1,500 km	SUV	Available
Fuel Type: Petrol-Electric									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	400G
Vehicle Details	
Vehicle No.:	SMK2391X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2018
Engine No.:	L15B5561262
Chassis No.:	RU11311252
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,786.00
Original Registration Date:	01 Apr 2019
First Registration Date:	01 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$13,901.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2029
PARF Rebate Amount:	\$10,425.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$25,154.00
Total Rebate Amount:	\$35,579.00

The information contained herein is correct as at 24 Oct 2019

OK

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

not Authorized
HHL
24/10/19
2/5 @ 15.000
120kg.

VEHICLE NO:SMK 2391X

QTY	PARTICULAR		DO/BAC		
1 PCS	BONNET	825.30	SW	\$1,150.30	✓
2 PCS	BONNET HINGES @\$85.00		SW	\$170.00	X
1 PCS	BONNET LOCK		17	\$166.30	X
1 PCS	BONNET INSULATOR	266.50	Toon	\$285.30	✓
1 SET	BONNET INSULATOR CLIPS		SW	\$50.00	✓
1 PCS	BONNET SIDE Rubber		SW	\$68.20	✓
1 PCS	FRONT BUNPER	801.70	17.5	\$850.00	✓
1 PCS	FRONT BUMPER SIDE RETAINER O/S		CNE	\$52.50	✓
1 PCS	FRONT BUMPER CENTRE GRILLE		Toon	\$285.00	✓
1 PCS	FRONT BUMPER REINFORCEMENT	321	SW	\$399.00	✓
1 SET	FRONT BUMPER CLIPS	39.00	SW	\$50.00	✓
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	85.00	17.5	\$185.00	✓
1 PCS	FRONT BUMPER FOG LAMP O/S	327.00	CNE	\$445.00	✓
1 PCS	FRONT GRILLE	385.00	CNE	\$566.20	✓
1 PCS	FRONT GRILLE OUTER CHROME	390.00	CNE	\$588.50	✓
1 PCS	FRONT BUMPER LOWER SPOILER	481.00	17.5	\$520.00	✓
1 PCS	FRONT BUMPER UNDER COVER		17	\$311.20	X
1 SET	FRONT BUMPER UNDER COVER CLIPS		17	\$40.00	X
1 PCS	FRONT SUPPORT PANEL	576.20	SW	\$745.11	✓
1 PCS	FRONT FENDER O/S	615.00	SW	\$765.00	✓
1 PCS	FRONT FENDER INNERSHIELD O/S	266.50	Toon	\$288.30	✓
1 SET	FRONT FENDER INNERSHIELD CLIP O/S		SW	\$40.00	✓
1 PCS	FRONT FENDER INNER PANEL O/S		SW	\$699.20	✓
1 PCS	FRONT WHEEL HOUSING PANEL O/S		17	\$650.50	X
1 PCS	FRONT FENDER OUTER PROTECTOR O/S	295.00	17.5	\$395.00	✓
1 PCS	WIPER WASHER TANK		17.5	\$292.80	✓
1 PCS	AIR CON CONDENSER		17	\$1,250.00	X
1 PCS	RADIATOR		17	\$1,817.00	X
1 PCS	RADIATOR FAN ASSY		17	\$485.00	X
1 PCS	FRONT SUPPORT PANEL TOP GARNISH		17	\$365.00	X
1 PCS	ENGINE MOUNTING O/S	366.50	Toon	\$485.00	✓
2 PCS	HEADLAMP ASSYS @\$3200.00	1820.50	15340	\$6,400.00	12C
1 PCS	HEADLAMP LOWER BRACKET O/S	105.00	CNE	\$185.00	✓
1 PCS	HEADLAMP TOP CHROME MOULDING O/S	280	CNE	\$305.00	✓
1 PCS	AIRCON SIDE GARNISH O/S	146.00	Toon	\$162.00	✓
1 PCS	ABS PUMP		SW	\$4,850.00	X
1 PCS	ABS PUMP WIRE	2450.00	CNE	\$2,500.00	✓
1 PCS	FUSE BOX ASSY		17	\$615.00	X
1 PCS	FRONT SHOCK ABSORBER O/S	450.50	SW	\$488.20	✓
1 PCS	FRONT SHOCK ABSORBER MOUNTING O/S		17	\$121.50	X
1 PCS	FRONT LOWER ARM O/S	395.20	SW	\$499.20	✓
1 PCS	FRONT KNUCKLE ARM O/S	453.30	SW	\$545.50	✓
1 PCS	FRONT KNUCKLE ARM BEARING O/S	245.50	SW/17	\$250.20	✓
1 PCS	FRONT DRIVE SHAFT O/S		SW/17	\$1,815.00	✓
1 PCS	FRONT STEERING RACK ASSY	1805.00	SW/17	\$2,655.00	✓
1 PCS	FRONT CROSS MEMBER		17/17	\$1,545.20	✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018903/Uif3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8501C	Veh. Inspected	SMK 2391X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006774MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	24/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	RU11311252	Colour	GREEN	
Odometer	11679	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2019	Inspection Date	24/10/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 2391X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED / BUCKLED	1,150.30	825.30
2	BONNET HINGES @\$85.00	SERVICEABLE	170.00	-
1	BONNET LOCK	NOT NECESSARY	166.30	-
1	BONNET INSULATOR	TORN	285.30	266.50
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	BONNET SIDE RUBBER	NECESSARY	68.20	68.20
1	FRONT BUMPER	DISTORTED	850.00	801.70
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	52.50	52.50
1	FRONT BUMPER CENTRE GRILLE	TORN	285.00	285.00
1	FRONT BUMPER REINFORCEMENT	BENT	399.00	321.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	39.00
1	FRONT BUMPER FOG LAMP COVER O/S	DISTORTED	185.00	85.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	445.00	327.00
1	FRONT GRILLE	CRACKED	566.20	385.00
1	FRONT GRILLE OUTER CHROME	CRACKED	588.50	390.00
1	FRONT BUMPER LOWER SPOILER	DISTORTED	520.00	480.00
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	311.20	-
1	SET FRONT BUMPER UNDER COVER CLIPS	NOT NECESSARY	40.00	-
1	FRONT SUPPORT PANEL	BENT	745.11	576.20
1	FRONT FENDER O/S	BUCKLED	765.00	615.00
1	FRONT FENDER INNERSHIELD O/S	TORN	288.30	266.50
1	SET FRONT FENDER INNERSHIELD CLIP O/S	NECESSARY	40.00	40.00
1	FRONT FENDER INNER PANEL O/S	BENT	699.20	699.20
1	FRONT WHEEL HOUSING PANEL O/S	TO REPAIR SEE LABOUR	650.50	-
1	FRONT FENDER OUTER PROTECTOR O/S	DISTORTED	395.00	295.00
1	WIPER WASHER TANK	DISTORTED	292.80	292.80
1	AIR CON CONDENSER	NOT NECESSARY	1,250.00	-
1	RADIATOR	NOT NECESSARY	1,817.00	-
1	RADIATOR FAN ASSY	NOT NECESSARY	485.00	-

Report Ref No. CS/FCI19018903/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	365.00	-
1	ENGINE MOUNTING O/S	TORN	485.00	366.50
2	HEADLAMP ASSYS @\$3200.00	O/S BROKEN	6,400.00	1,820.50
1	HEADLAMP LOWER BRACKET O/S	CRACKED	185.00	105.00
1	HEADLAMP TOP CHROME MOULDING O/S	CRACKED	305.00	280.00
1	AIRCON SIDE GARNISH O/S	TORN	162.00	146.00
1	ABS PUMP	SERVICEABLE	4,850.00	-
1	ABS PUMP WIRE	CRACKED	2,500.00	2,450.00
1	FUSE BOX ASSY	NOT NECESSARY	615.00	-
1	FRONT SHOCK ABSORBER O/S	TWISTED	488.20	450.50
1	FRONT SHOCK ABSORBER MOUNTING O/S	NOT NECESSARY	121.50	-
1	FRONT LOWER ARM O/S	TWISTED	499.20	395.20
1	FRONT KNUCKLE ARM O/S	BENT	545.50	455.30
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	250.20	245.50
1	FRONT DRIVE SHAFT O/S	BENT / TWISTED	1,815.00	1,815.00
1	FRONT STEERING RACK ASSY	BENT / JAMMED	2,655.00	1,805.00
1	FRONT CROSS MEMBER	DENTED / TWISTED	1,545.20	1,545.20
1	AIR CON COMPRESSOR	NOT NECESSARY	1,820.00	-
1	ROCKER PANEL GARNISH O/S	DEFORMED / TORN	466.80	466.80
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	620.50	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	911.30	-
	LESS 20% DISCOUNT		-	-3,901.48
			41,215.81	15,605.92
	LABOUR			
	TOWING CHARGE.		65.00	50.00
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		180.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACING FRONT UNDER CARRIAGE.		380.00	350.00
	TO DISMANTLE & REPLACING ABS PUMP.		300.00	80.00
	TO DISMANTLE & REFIX ENGINE.	NOT NECESSARY	500.00	-

Report Ref No. CS/FCI19018903/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT WHEEL HOUSING PANEL O/S,ROCKER PANEL O/S AND FRONT DOOR O/S.		2,200.00	1,400.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,200.00
			6,005.00	3,290.00
GRAND TOTAL			47,220.81	18,895.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FCI19018903/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.