

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064; 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JHMF D462075200865

LEO CAR RENTALS LLP
542 JELAPANG ROAD
#08-44
S 670542

TPAYA.
Cecilia.

Date :31.10.2019
Vehicle No :SGV 7143 B
Make/Model :HONDA CIVIC
Accident date :18.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bootlid Distorted	1	\$ 671.8 ✓
2	Rear bootlid hinges @ \$77.00 Bent	2	\$ 154 ✓
3	Rear bootlid upper lock Damaged. NW	1	\$ 221.8 X
4	Rear bootlid lower lock NW	1	\$ 46.2 X
5	Rear bootlid H emblem	1	\$ 39.6 ✓
6	Rear bootlid Civic emblem	1	\$ 39.6 ✓
7	Rear bootlid 1.6 emblem	1	\$ 20.9 ✓
8	Rear bootlid Vtec emblem	1	\$ 39.6 ✓
9	Rear bootlid reflector @ \$184.80 crinkled	2	\$ 369.6 ✓
10	Rear bootlid weather strip	1	\$ 104.5 ✓
11	Rear number plate lamp @ \$35.20 NW	2	\$ 70.4 X
12	Rear end panel Distorted	1	\$ 401 ✓
13	Rear end panel top garnish Deformed	1	\$ 71.5 ✓
14	Rear lamp @ \$266.20 crinkled	2	\$ 532.4 ✓
15	Rear lamp housing @ \$80.30 Buckled	2	\$ 160.6 ✓
16	Rear bumper Distorted	1	\$ 701.8-638
17	Rear bumper side holder @ \$23.10 NW	2	\$ 46.2 ✓
18	Rear bumper bracket @ \$23.10 NW	2	\$ 46.2 X
19	Rear bumper clips (1 set) NW	1	\$ 66 30
20	Rear mud flap @ \$96.30 NW	2	\$ 192.6 X
21	Rear lamp lower bracket @ \$31.90 NW	2	\$ 63.8 X
22	Rear fender @ \$871.20 Repair	2	\$ 1742.4 X
23	Rear fender inner trim @ \$242.1 torn	2	\$ 484 ✓
24	Rear spare tyre top board Deformed	1	\$ 349.8 ✓
25	Rear spare tyre well Repair	1	\$ 960.3 X
26	Rear spare tyre well insulation @ \$93.50 NW	3	\$ 280.5 X
27	Rear exhaust pipe @ \$159.50 Bent	2	\$ 319 ✓
28	Rear exhaust Bent	1	\$ 629.2 ✓
29	Rear exhaust pipe mounting NW	1	\$ 23.1 X
			\$ 8712
Less 20% Disc			\$ 1742.4
Total			\$ 6969.6

5101.30

4081.04

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LEO CAR RENTALS LLP
542 JELAPANG ROAD
#08-44
S 670542

Date :31.10.2019
Vehicle No :SGV 7143 B
Make/Model :HONDA CIVIC
Accident date :18.10.2019

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>Damaged</i>		\$ 800-200
2	Rear number plate <i>3 Best</i>	260	\$ 50-30
3	Rear number plate holder		\$ 50-30
Total			\$ 900

Labour Cost

1 To supply rear windscreen sealant	\$ 50 X
2 To supply rear end panel inner sealant	\$ 200 60
3 Remove & reinstall rear windscreen	\$ 150 X
4 Remove & reinstall reverse sensor	\$ 150 60
5 Remove & reinstall exhaust pipe	\$ 150 80
6 Remove & reinstall roof lining + cushion	\$ 200 60
7 Remove & reinstall petrol tank	\$ 150 X
8 Towing fee	\$ 150 50
9 Remove ,replace & repair consistent to the accident	\$ 1800 1400
10 Respray painting	\$ 1400 1400
11 Tuff kote	\$ 150 60
Total	\$ 4550
Grand Total	\$ 12419.6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 7511.04.

h/s: GK.

08 days

GK