

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53194**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Fang Liang
BLK 147 PASIR RIS GROVE
#10-74

Singapore 518138

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT9596R	WBA2D920105E91454	17/11/2017	216i G TOURER	0

DESCRIPTION	VALUE
Replace rear bumper include remove attachment etc and repair on accident damage area	1700 2,125.00
Spray rear boot lid and rear bumper	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 271.00
To replace rear windscreen glass.	? 574.00
To conduct water leak tests.	? 75.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
To supply and install rear windscreen solar film.	? 531.00
Total Labour 1:	5,944.00

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <i>5f</i>	1	1,210.35	1,210.35
REAR BUMPER CARRIER ?	1	458.10	458.10
SUPPORT ?	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE ?	1	67.55	67.55
RR BUMPER RH INNER SIDE GUIDE ?	1	67.55	67.55
REAR BUMPER TRIM STRIP (CHROM) <i>see</i>	1	110.55	110.55
LEFT PROTECT ?	1	11.20	11.20
RIGHT PROTEC ?	1	11.20	11.20
REAR BUMPER PANEL PRIMED (LINES PDC <i>de</i>)	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR ?	1	60.35	60.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53194**
Date Estimated : **24/10/2019**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT9596R	WBA2D920105E91454	17/11/2017	216i G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TOWING FLAP EYE PRIMED *	1	42.85	42.85
LETTERING 216 i <i>nee</i>	1	64.10	64.10
GROMMET <i>nee</i>	2	0.80	1.60
PLAQUE 74MM <i>nee</i>	1	71.25	71.25
BUMP STOP <i>nee</i>	10	3.75	37.50
REAR WINDOW ?	1	657.60	657.60
HOOK AND LOOP FASTENER <i>nee</i>	4	2.85	11.40
(DG) CLEANER R1 (100ML) <i>nee</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>nee</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>nee</i>	1	27.85	27.85

Total Parts : **4,291.00**

Claims OD / 3 rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>04/11/19 @ 1030</u>	Excess S\$ _____
Surveyor's Name <u>RASM</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <input type="checkbox"/> PML Yes / No <input type="checkbox"/>	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>5 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,944.00
Parts	:	4,291.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	716.45
Grand Total	:	10,951.45

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****