

Kanchag

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 53194	Page No. : 1 of 5
Date Estimated : 24/10/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Fang Liang BLK 147 PASIR RIS GROVE #10-74  Singapore 518138	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT9596R	WBA2D920105E91454	17/11/2017	216i G TOURER	0

DESCRIPTION	VALUE
Replace rear bumper include remove attachment etc and repair on accident damage area	1700 <del>2,125.00</del>
Spray rear boot lid and rear bumper	1730 <del>1,923.00</del>
To check electrical wiring systems and lightings at the rear section for proper function.	150 <del>177.00</del>
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 <del>271.00</del>
To replace rear windscreen glass.	? 574.00
To conduct water leak tests.	? 75.00
To carry out body cavity preservation. (Per panel).	100 <del>118.00</del>
Sundries.	80? 150.00
To supply and install rear windscreen solar film.	max? 531.00

Total Labour 1: **5,944.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <del>5f</del>	1	1,210.35	1,210.35
REAR BUMPER CARRIER ? <del>X</del> <i>xsuc</i>	1	458.10	458.10
SUPPORT ? <del>X</del> <i>xsuc</i>	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE ? <del>X</del> <i>xsuc</i>	1	67.55	67.55
RR BUMPER RH INNER SIDE GUIDE ? <del>X</del> <i>xsuc</i>	1	67.55	67.55
REAR BUMPER TRIM STRIP (CHROM) <del>scr</del>	1	110.55	110.55
LEFT PROTECT ? <del>X</del> <i>xsuc</i>	1	11.20	11.20
RIGHT PROTEC ? <del>X</del> <i>xsuc</i>	1	11.20	11.20
REAR BUMPER PANEL PRIMED (LINES PDC <del>de</del>	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR ? <del>X</del> <i>xsuc</i>	1	60.35	60.35

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559M GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)



103, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax: 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax: 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax: 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 53194	Page No. : 2 of 5
Date Estimated : 24/10/2019	
Prepared By : Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT9596R	WBA2D920105E91454	17/11/2017	216i G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TOWING FLAP EYE PRIMED <i>XAN</i>	1	42.85	42.85
LETTERING 216i <i>XAN</i>	1	64.10	64.10
GROMMET <i>XAN</i>	2	0.80	1.60
PLAQUE 74MM <i>XAN</i>	1	71.25	71.25
BUMP STOP <i>XAN</i>	10	3.75	37.50
REAR WINDOW ? <i>XAN</i>	1	657.60	657.60
HOOK AND LOOP FASTENER <i>XAN</i>	4	2.85	11.40
(DG) CLEANER R1 (100ML) <i>XAN</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>XAN</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>XAN</i>	1	27.85	27.85
Total Parts :			<b>4,291.00</b>

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No _____	Claim No. _____
Date & Time <u>04/11/19 @ 1030</u>	Excess S\$ _____
Surveyor's Name <u>RBM</u>	Sign _____
Surveyor's Tel <u>90010066</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>5 days</u>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Labour 1	:	<b>5,944.00</b>
Parts	:	<b>4,291.00</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>716.45</b>
<b>Grand Total</b>	:	<b>10,951.45</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : b1 53194  
Date Estimated : #####  
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Fang Liang  
39 Amber Road  
#13-23

Singapore 439947

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT9596R	WBA2D920105E91454	17/11/2017	2161 G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and rear boot lid including to remove and install body parts in order to carry out painting job.	1,700.00	0.00	1,700.00 ✓
To respray rear bumper and rear boot lid.	1,730.00	0.00	1,730.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00	0.00	230.00 ✓
To remove and install rear windscreen glass to facilitate repairs	574.00	0.00	574.00 ✓
To conduct water leak tests.	75.00	0.00	75.00 ✓
To carry out body cavity preservation.	100.00	0.00	100.00 ✓
Sundries.	80.00	0.00	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,210.35	1	0	1,210.35 ✓
REAR BUMPER TRIM STRIP (CHROM)	110.55	1	0	110.55 ✓
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1	0	1,045.45 ✓
GROMMET	0.80	2	0	1.60 ✓
PLAQUE 74MM	71.25	1	0	71.25 ✓

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Total Labour :	4,639.00
Total Parts :	2,439.20
Total Labour & Parts :	<del>7,078.20</del>
GST @7%:	495.47
Grand Total :	<u>7,573.67</u>

W/ TO FAX NO		RASW/ LKE	21/11/19	5
FAX TO FAX NO				

LOU \$60 X 5 DAYS  
GIA SEARCH FEE \$2.00

PLEASE SEEK MANDATE FROM YOUR PRINCIPLE ASAP.