

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

? Photo
Lump sum repair
repair days 4

TOTUM Lin
25/10/19

Resurvey on 29/10/19
1400hrs/Min

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201729175W

Vehicle No: GBJ5874K
Model: Nissan NV350 2.5D
Chassis No: JN1MC2E26Z0031257
Year of manufacture 2019

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Front bumper	1	✓ 580.70	DD ✓
2	Front bumper retainer RH	1	22.70 85.50	} NEC ✓
3	Front bumper retainer LH	1	22.70 85.50	
4	Front bumper towing cap	1	35.00 75.00	
5	Front bumper center grille	1	✓ 192.60	MIS ✓
6	Front bumper lower garnish	1	✓ 183.60	BR ✓
7	Front bumper reinforcement	1	704.60 734.80	? DD ✓
8	Fog lamp garnish RH	4	115.80 182.70	} DL ✓
9	Fog lamp garnish LH	4	115.80 182.70	
10	Front panel	1	1560.20	RX
11	Front grille	1	520.00 654.50	? BR ✓
12	Front grille chrome	1	285.00 352.90	BR ✓
13	Front grille logo	1	45.70 92.00	NEC ✓
14	Head lamp RH	1	476.30 563.40	? BR ✓
15	Head lamp LH	1	476.30 563.40	BR ✓
			3726.80	
			372.68	
			3354.12	
			3726.80	6089.50

Special Nett Items

16	Front bumper clip set	1	30.00 50.00	} NEC
17	Front grille clip set	1	30.00 50.00	
18	Front panel sealant	1	50.00	
19	Front panel sticker	1	30.00 60.00	
20	Front number plate	1	30.00 45.00	BT ✓
21	Head lamp protector RH	1	100.00 250.00	
22	Head lamp protector LH	1	100.00 250.00	
			320.00	
				755.00

Labour & Miscellaneous Charge

23	To check wiring and lighting system	1	50.00 100.00	
24	To conduct head lamp focus	1	40.00 80.00	
25				
	To supply under-coating / anti rust on affected areas	160.00	100.00	
26	To repair, replace & realign damaged areas	1500.00	1000.00	
27	To spray painting on affected areas	1400.00	1000.00	
28	Sundries	1	50.00	NAX
			1050.00	2330.00
			80.00	
			1130.00	

3354.12

1845.00

320.00

1130.00

6649.12

1329.82

5,319.30

@ 20%

11,520.12

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: GBJ5874K
Model: Nissan NV350 2.5D
Chassis No: JN1MC2E26Z0031257
Year of manufacture: 2019

NO.	DESCRIPTION	QTY	U/P	AMT
#	Supplementary Item			
1	Turbo Inter-cooler	1	2975.30	2975.30
			2050.00	0.00
	Labour & Miscellaneous Charge			
2	To R&R Turbo Inter-cooler assy	1	80.00	200.00
				200.00

DDV
@ 10% 205.00
1845.00

parts = 7504.60 - 10% AAA
= 6754.14

List Items Subtotal
Special Nett Items Subtotal
Labour Items Subtotal
Total

S/N = 320

Labour = 1130

Resurvey on 29/10/19
1400 hrs
Termin
lin

P+L = 8204.14 - 20% L/S
= \$6550

Parts 5199.12
SN 320.00
Labour 1130.00
6649.12
@ 20% 1329.82
5319.30