LCRF PTE LTD **CARROS CENTER** 60 JALAN LAM HUAT #04-01 S(737869) Main +65 62524991

P = 1934,48. N = 270L = 1,050

3,254,48

20%

2,603.58

ESTIMATE

VEHICLE NO.: SLL1170E CHASSIS NO: RU31220317

Attn: MOTOR CLAIMS DEPT

Date: 24/10/2019

MAKE / MODEL: VEZEL HYBRID 1.5X AUTO

Ms AIG Asia Pacific Insurance Pte Ltd

DATE OF ACCIDENT: 02/09/2019

YOUR INSURED VEHICLE NUMBER: SLH2171E

415 = \$2,600

3 days

	PARTS DISCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Rear tailgate / pp	1PC	\$1,450.00	\$1,450.00 1,100
2	Rear tailgate Vezel emblem ✓ N₹c	1PC	\$86.80	\$86.80 /
3	Rear tailgate Honda emblem / Nec	1PC	\$81.30	\$81.30
4	Rear tailgate Windscreen moulding / Nec	1PC	\$195.00	\$195.00
5	Rear tailgate weatherstrip X SVC	1PC	\$155.00	\$155.00
6	Rear tailgate lock > 5 vc	1PC	\$550.00	\$550.00
7	Rear tailgate lock catch × 5VC	1PC	\$180.00	\$180.00
10	Rear bumper / pb.	1PC	\$955.00	\$955.00 /

LIST TOTAL \$5: \$3,653.10 2,418.1 20.00% DISCOUNT S\$: \$730.62 483.62 \$2,922.48 1,934.48

SPECIAL NETT

1	Rear bumper clips / Net.	1 SET	\$80.00 \$30
2	End panel top garnish clips ×	1 SET	\$80.00 X
3	Reverse sencor /short.	1PC	\$490.00 200
4	Body sealant X	1SET	\$300.00 ×
5	Windscreen sealant / Nec	1PC	\$100.00 40.

Special Nett Total S\$: \$1,050.00 270

LABOUR CHARGES

	The second secon		
1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate reapirs and replacement of demage parts.	\$900.00	500.
2	To respray rear tailgate, end panel and spare tyre panel	\$800.00	400
	To conduct a standard of operating		
	procedures post repair scan test as a	\$300.00	X
	requirement upon completion of collision		
3	To remove and install rear tailgate glass	\$180.00	120
4	To deactivate and active high voltage hybrid battery as safety precautions	\$300.00	×
5	To apply rustproofing on all demaged parts	\$180.00	X
			/
6			
	To check wiring system		
	To effect withing system	\$100.00	30.
			The second secon

Repair days - 3 days

Sun Pm 24/10/2019. Lump-Sum Repair. After spray photo.

TP without Pregudice.

1,050 LABOUR TOTAL S\$: \$2,760.00

TOTAL S\$: \$6,732.48

7% GST \$471.27

GRAND TOTAL S\$: \$7,203.75

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Oi Sun Pin (LKK Auto)

From:

Sent: To: Subject:	Wednesday, 4 December, 2019 9:26 AM Oi Sun Pin (LKK Auto) Re: Final Bill: SLL1170E
Subject.	Re. Fillal Bill. SEETI70E
Follow Up Flag: Flag Status:	Follow up Flagged
Sun Pin Ok confirmed lump sum \$2,600	0/3 days
Regards S.T.Sim (65-97422188 Manager Accident Reporting Cente 60 Jalan Lam Huat #04-35/36 Carros Centre Singapore 737869	
On Wed, Dec 4, 2019 at 8:58 A	AM Oi Sun Pin (LKK Auto) < <u>sunpin@lkkauto.com</u> > wrote:
Dear Mr Sim,	
Kindly refer the finalize amount	\$2,600. Repair days 3 days (L/S repair, before gst).
If agree please reply .	
Thank you.	
Best Regards,	
Oi Sun Pin Assistant Automoti	ve Assessor
LKK Auto Consultants	
Phone: 6256 3561 Email: Sunpin@	Dlkkauto.com fax: 6256-4315

Siak Tong Sim <siaktong@lioncityrentals.com.sg>

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)