

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11317

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1090/2019/NS
Date	:	10-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Omnititan Venture Pte Ltd
Address	:	8 Amber Road #10-04 Singapore 439853
Telephone	:	HP +65 90100928
Type of Claim	:	Own Damage Claim
Policy No.	:	1800074627
Vehicle No	:	SJY 868 M
Model Code	:	Audi Q5 SPORT 2.0 TFSI QU
Model / Year	:	27/6/2018
Engine No	:	DAX 033136
Chassis No	:	WAUZZZFY1J2136493
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Sep-19
Place of Accident	:	Dunman Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJY 868 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 500.	
3	To respray rear upper bumper, rear lower bumper and both rear wheel arch trims.	\$ 3,000.00 1600	$2 \times 550 = 1100$ $\text{Arch Trim} \times 02 = 250 \times 2 = 500$
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ <u>4,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 868 M

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	REAR BUMPER - UPPER <i>Repair</i>	\$ 1,571.00	X
2	REAR BUMPER - LOWER <i>3 changed</i>	\$ 1,077.00	✓
3	REAR BUMPER SPOILER	\$ 754.00	✓
4	REAR BUMPER TOWING EYE COVER - LH / RH <i>RH changed</i>	\$ 69.00 34.50	
5	REAR BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 86.00	X
6	REAR BUMPER TRIM - RH ?	\$ 213.00	?
7	TAIL LIGHT - RH <i>cracked</i>	\$ 627.00	✓
8	BOOT LID CONTROL UNIT	\$ 387.00	X
9	REAR BUMPER CARRIER	\$ 831.00	X
10	REAR BUMPER HOLDING STRAP	\$ 151.00	X
11	REAR BUMPER GUIDE SECTION - RH	\$ 76.00	X
12	REAR BUMPER FOAM FILLER PIECE - RH	\$ 56.00	X
13	REAR PARKING AID SENSOR	2 \$ 462.00	X
14	REAR PARKING AID SENSOR SEAL RING	4 \$ 12.00	X
15	REAR WHEEL COVER - LH / RH <i>new</i>	2 \$ 974.00	✓
16	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 7,646.00	
TOTAL LABOUR CHARGES		: \$ 4,752.00	
GRAND TOTAL		: \$ 12,398.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adam Lij

Surveyed Date

: 24/10/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant