

ASS. REC. BY:

REF

TNI/CC3/TM2 19018943/KS f3n2

ASSIGNMENT

From

Date

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop no:

of

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Est. of Market Value

8113,400

IDAC Accident Report

Consistent? Yes or No

GIA / PR. Secat

Consistent? Yes or No

Est. Repairs

05 days

Res. Yes or No

Lem Sum

20 %

BVA. Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacts:

Vehicle IN / OUT

Action / Instruction

PK 1000 70

Veh No

SHD 757

Yr Regn

12, 15

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Mw

220

cc

2143

Colour

White

A/C

Insured / Std / NI / NA

Sp Reading

533219

T-Radio

Insured / Std / NI / NA

Eng No

C/Nr

WDD 2120012B 22 4063

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size

F:

225/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

C/M

Front

R/Sal

8

mm

Rear

R/Sal

8

mm

L/Sal

8

mm

L/Sal

8

mm

D.O.A

22/10/19

D.O.A

24/10/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 02 JAN 2020

C/Rmp @ 7850/-

SHD 757 - X

SGT 35981 - CS/TM117015435/1046n2

DON - 16/07/2017

22/10/19

Confirmed Hs \$ 7,850/- @ 5 days with Kenneth
(\$ 49,849.27 Red - 86%)

Discontinue File Pass to:

02/01/20

Typist

Discontinue File Return to:



Prel Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee

Transportation

D.F.S. or

V.C. or

Other

Add Fee:



Site Insp 15



Interview 15



Train 15



Workshop 15

Report Format:

Temp Sum / L.B.F.T.S

\$ 7,850/- Us

250
11

261

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0008529-2

Print Date/Time : 23 Oct 2019 / 16:52:41

Receipt Date/Time : 23 Oct 2019 / 16:52:41

Tax Invoice/Receipt

Receipt No. : ITNET-00000-191023-002817

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SG1080A As at 22 Oct 2019/16:50:00 Insurance Co: INDIA INTL INS PTE LTD				
1	Insurance Enquiry - SG1080A Enquiry Fee 20191023165144913522	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SGT3598J As at 22 Oct 2019/23:45:00 Insurance Co: TOKIO MARINE INSURANCE SINGAPORE LTD				
2	Insurance Enquiry - SGT3598J Enquiry Fee 20191023165145009710	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - GZ2803S As at 23 Oct 2019/07:05:00 Insurance Co: LONPAC INSURANCE BHD				
3	Insurance Enquiry - GZ2803S Enquiry Fee 20191023165145072616	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		21.00	1.47	22.47
Rounding Difference				0.02
Total Amount Payable				22.45
Paid By				
		xxxxxxxxxxxx8127	Credit Card: Visa/MasterCard	22.45
Total				22.45
Cash Change				0.00
Tendered Amount				22.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Shirley Hiew (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 2 January 2020 3:10 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: TCS REF: AAD1910-173--Accident involving SHD 75T & SGT 3598J on 22/10/2019
Attachments: DSCF7467.JPG; DSCF7465.JPG; DSCF7466.JPG

Without Prejudice

Dear Shirley

Amount confirmed \$ 7,850 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 29 October, 2019 10:18 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TCS REF: AAD1910-173--Accident involving SHD 75T & SGT 3598J on 22/10/2019

Dear Wai Yin,

Please confirm final fig \$ 7,850.00 (lump sum) @ 5 days of repairs before GST.

Kindly provide us after paint photo.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 25 October 2019 3:04 pm
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,
DOA:22/10/2019, SHD 75T (TP VEHICLE), SGT 3598J (OI VEHICLE)
Attachments: TP GIA REPORT.pdf; ESTIMATE.pdf; PRELI ADVISE - SHD 75T.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 75T at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 24/10/2019

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD75T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220 BLUETEC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	65192432772105
Chassis No.:	WDD2120012B224065
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$43,891.00
Original Registration Date:	16 Dec 2015
First Registration Date:	16 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$45,948.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2023
PARF Rebate Amount:	\$34,461.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,466.00
COE Rebate Amount:	\$23,546.00
Total Rebate Amount:	\$58,007.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 10:25
Date Of Accident	22/10/2019 23:45
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD75T
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	MB E 220 BLUE TEC
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	NEO KIM SENG
NRIC No	S1318760F
Date Of Birth	10/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	06/05/1992
Driving Experience	27 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81896486
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 224 TAMPINES STREET 23 #04-225
Postcode	521224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRLIZZING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 22.10.2019 at about 2345hours, I was Stationary straight on the third lane along Geylang Road when the traffic light was red. While stationary, suddenly I felt an impact. Vehicle B (SGT3598J) hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT3598J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pis see attach su Rpat

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 75T

AAD1910-173

*Not Authored
11 Sep @ 7850h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

24 OCT 2019

SHD 75T

WDD2120012B224065

MERCEDES BENZ

E 220 BLUETEC

22.10.19

TOKIO MARINE

16/12/2015

			PART
1	1	Rear Bumper	1510
2	1	Rear Bumper Lower	325
3	1	Rear Bumper Centre Pad	
4	1	Rear Bumper Side Pad	
5	1	Rear Bumper Tow Hook Cover	
6	1	Rear Bumper Bracket	
7	1	Rear Bumper Side Retainer Bracket	
8	1	Rear Bumper Inner Frame	
9	1	Rear Bumper Bottom Bracket	
10	1	Rear Bumper Top Bracket	
11	1	Rear Bumper Side Holder Bracket	
12	1	Rear Bumper Inner Bracket LH	
13	1	Rear Bumper Inner Bracket RH	
14	1	Rear Bumper Beam	1150
15	1	Rear Bumper Beam Bracket LH	
16	1	Rear Bumper Beam Bracket RH	
17	1	Rear Bumper Bracket Centre	
18	1	Rear Bumper Retainer Bracket LH	
19	1	Rear Bumper Retainer Bracket RH	
20	1	Bootlid	2470
21	1	Bootlid 'E220' Badge	
22	1	Bootlid 'BLUETEC' Badge	

		LIST	
\$	R	3,105.00	✓
\$	R	1,080.00	✓
\$	N/A	307.83	X
\$	N/A	186.33	X
\$	CM	42.00	✓
\$	M-1	22.50	✓
\$	S	132.00	X
\$	CM	297.00	✓
\$	M-1	60.00	✓
\$	R	129.00	X
\$	S	135.00	X
\$	R	198.00	✓
\$	R	198.00	X
\$	R	1,215.00	✓
\$	R	307.50	X
\$	R	307.50	✓
\$	S	461.75	X
\$	S	202.50	X
\$	S	202.50	X
\$	R	4,140.00	✓
\$	R	153.00	✓
\$	R	153.00	✓

Trans-cab Auto Services Pte Ltd**AAD1910-173**

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 75T

23	1	Bootlid Centre Logo Badge	\$	<i>me</i>	153.00	✓
24	1	Bootlid Protector Garnish With Chrome	\$	<i>SL</i>	732.00	X
25	1	Bootlid Weatherstrip <i>240</i>	\$	<i>pu/di</i>	360.00	✓
26	1	Bootlid Lock - Top	\$	<i>me</i>	300.00	✓
27	1	Bootlid Lock - Bottom	\$	<i>n</i>	216.00	X
28	1	Bootlid Lock Actuator	\$	<i>SL</i>	420.00	X
29	1	Bootlid Weatherstrip	\$	<i>SL</i>	240.00	X
30	1	Bootlid Third Brake Lamp	\$	<i>SL</i>	577.50	X
31	1	Rear Trunk Lid Lamp RH	\$	<i>SL</i>	1,170.00	X
32	1	Rear Trunk Lid Lamp LH	\$	<i>SL</i>	1,170.00	X
33	1	Rear End Panel Outer <i>990.</i>	\$	<i>me</i>	1,971.00	✓
34	1	Rear End Panel Inner	\$	<i>n</i>	324.00	X
35	1	Rear End Panel Inner Trim <i>325</i>	\$	<i>cm</i>	630.00	✓
36	1	Rear End Panel Inner Trim Flap	\$	<i>SL</i>	360.00	X
37	1	Rear Lamp RH	\$	<i>SL</i>	1,170.00	} X
38	1	Rear Lamp Panel Outer RH	\$	<i>n</i>	382.95	
39	1	Rear Lamp LH	\$	<i>SL</i>	1,170.00	
40	1	Rear Lamp Panel Outer LH	\$	<i>n</i>	382.95	
41	1	Rear Luggage Floor Panel Tray	\$	<i>me</i>	762.00	
42	1	Rear Luggage Floor Compartment Tray	\$	<i>SL</i>	116.00	
43	1	Rear Luggage Floor Panel Trim Board	\$	<i>SL</i>	420.00	
44	1	Rear Fender LH	\$	<i>n</i>	3,620.00	
45	1	Rear Fender RH	\$	<i>n</i>	3,620.00	
46	1	Rear Fender Top Garnish RH	\$	<i>SL</i>	67.50	
47	1	Rear Fender Inner Trim RH	\$	<i>SL</i>	517.50	
48	1	Rear Fender Top Garnish LH	\$	<i>SL</i>	67.50	
49	1	Rear Fender Inner Trim LH	\$	<i>SL</i>	517.50	
TOTAL			\$		34,472.81	
10%			\$		3,447.28	
			\$		31,025.53	

Trans-cab Auto Services Pte Ltd

AAD1910-173

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 75T**Special Nett**

1	1SET	Rear Bumper Parking Sensor	\$	Phat 1,200.00	500.00
2	1SET	Bootlid Inner Trim Clip	\$	na 90.00	X
3	1SET	Rear End Panel Inner Trim Clip	\$	na 90.00	—
4	1SET	Rear Bumper Fastener Clip	\$	na 101.54	—
5	1SET	Rear Fender Top Garnish Clip	\$	na 90.00	X
6	1SET	Rear Fender Inner Trim Clip	\$	na 45.00	X
7	1SET	License plate	\$	na 225.00	X
8	1	Rear Windscreen Glass Sealant	\$	na 225.00	} X
9	1	Rear Windscreen Glass Inner Seal	\$	na 180.00	
10	1	Rear Windscreen Moulding	\$	na 180.00	
11	1	Tyre Mechanical Jack	\$	Ph 605.48	
12	1	Tyre Mechanical Jack Holder Bracket	\$	Ph 177.98	
13	1	Rear Bootlid 'DYNASTY' Sticker	\$	na 33.75	
14	1	Windscreen Sealant Moulding	\$	na 180.00	
15	1	Windscreen Inner Sponge Seal	\$	na 180.00	
16	1	Rear Tyre RH	\$	Ph 550.00	} X
17	1	Rear Alloy Rim RH	\$	Ph 1,050.00	
TOTAL			\$	5,203.74	

GRAND TOTAL \$ 36,229.27**LABOUR**

To Transfer Of Bumper Fittings, Attachment And Perform Water Seepage Test.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	8,500.00	Fool
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-173**

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 75T

Putty And Spray Painting Of The Affected Portion.	\$	8,500.00	7501
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	380.00	801
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	601
To rust-proofing of the affected areas.	\$	<i>Repair</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00	X
To Reinstall Rear Bumper Parking Sensor.	\$	170.00	601
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>~</i> 170.00	X
Towing Fees	\$	<i>~</i> 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>~</i> 380.00	X
To Transfer Of Rear Fender Fittings, Attachment And Perform Water Seepage Test.	\$	<i>~</i> 380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-173**

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 75TTo Supply And Re-Do Rear Luggage Floor Panel
Insulation Padding.\$ *nn* 380.00 XTo transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.\$ *nn* 170.00 XTo drop diesel tank, pipes, hoses to facilitate
bodywork repair, final checking and testing.\$ *nn* 380.00 XTo remove and refit air bag system and reset
vehicle warning indicators.\$ *nn* 480.00 X**TOTAL \$ 21,470.00****Over all total \$ 57,699.27****(LUMP SUM) Repair Days***25 DAYS**5 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19018943/KSF3N2
Date: 07/01/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000850

Claimant Vehicle No: SHD75T

Insured Vehicle No: SGT3598J

Date of Loss: 22/10/2019

Nature of Claim: TP Claim No: M1909240

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD75T
Make & Model: MERCEDES-BENZ E220 BLUETEC, 2.1 D (A)
Reg. Date: 16/12/2015 (Man. Year: 2015)
Colour: White
Engine Capacity: 2143 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

Engine No: 65192432772105
Chassis No: WDD2120012B224065
Odometer: 533219 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55ZR16 Rear Tyre Size: 225/55ZR16
Front Left Side: Citi 8 mm Rear Left Side: Citi 8 mm
Front Right Side: Citi 8 mm Rear Right Side: Citi 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,229.28	8,062.99	28,166.29	77.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,470.00	1,730.00	19,740.00	91.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,699.28	9,792.99	47,906.29	83.03
Approved Total (Overridden) (S\$)		7,850.00		
(S\$)	57,699.28	7,850.00	49,849.28	86.39
+ GST 7.00/7.00% (S\$)	4,038.95	549.50	3,489.45	86.39
Nett Amount (S\$)	61,738.23	8,399.50	53,338.73	86.39

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 24/10/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)

Parts: 143 MERCEDES-BENZ E220 BLUETEC 2.1 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD75T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*REAR BUMPER	Bent	3,105.00 FL	-	*1,510.00 FL
2	1	*REAR BUMPER LOWER	Bent	1,080.00 FL	-	*325.00 FL
3	1	*REAR BUMPER CENTRE PAD	No such part	307.83 FL	-	*- FL
4	1	*REAR BUMPER SIDE PAD	No such part	186.33 FL	-	*- FL
5	1	*REAR BUMPER TOW HOOK COVER	Cracked	42.00 FL	-	*42.00 FL
6	1	*REAR BUMPER BRACKET	Missing	22.50 FL	-	*22.50 FL
7	1	*REAR BUMPER SIDE RETAINER BRACKET	Serviceable	132.00 FL	-	*- FL
8	1	*REAR BUMPER INNER FRAME	Cracked	297.00 FL	-	*297.00 FL
9	1	*REAR BUMPER BOTTOM BRACKET	Missing	60.00 FL	-	*60.00 FL
10	1	*REAR BUMPER TOP BRACKET	Repair	129.00 FL	-	*- FL
11	1	*REAR BUMPER SIDE HOLDER BRACKET	Serviceable	135.00 FL	-	*- FL
12	1	*REAR BUMPER INNER BRACKET LH	Repair	198.00 FL	-	*- FL
13	1	*REAR BUMPER INNER BRACKET RH	Repair	198.00 FL	-	*- FL
14	1	*REAR BUMPER BEAM	Bent	1,215.00 FL	-	*1,150.00 FL
15	1	*REAR BUMPER BEAM BRACKET LH	Repair	307.50 FL	-	*- FL
16	1	*REAR BUMPER BEAM BRACKET RH	Repair	307.50 FL	-	*- FL
17	1	*REAR BUMPER BRACKET CENTRE	Serviceable	461.75 FL	-	*- FL
18	1	*REAR BUMPER RETAINER BRACKET LH	Serviceable	202.50 FL	-	*- FL
19	1	*REAR BUMPER RETAINER BRACKET RH	Serviceable	202.50 FL	-	*- FL
20	1	*BOOTLID	Buckled	4,140.00 FL	-	*2,470.00 FL
21	1	*BOOTLID E220 BADGE	Necessary	153.00 FL	-	*153.00 FL
22	1	*BOOTLID BLUETEC BADGE	Necessary	153.00 FL	-	*153.00 FL
23	1	*BOOTLID CENTRE LOGO BADGE	Necessary	153.00 FL	-	*153.00 FL
24	1	*BOOTLID PROTECTOR GARNISH WITH CHROME	Serviceable	732.00 FL	-	*- FL
25	1	*BOOTLID WEATHERSTRIP	Dented/Distorted	360.00 FL	-	*240.00 FL
26	1	*BOOTLID LOCK-TOP	Dented	300.00 FL	-	*300.00 FL
27	1	*BOOTLID LOCK-BOTTOM	Repair	216.00 FL	-	*- FL
28	1	*BOOTLID LOCK ACTUATOR	Serviceable	420.00 FL	-	*- FL
29	1	*BOOTLID WEATHERSTRIP	Serviceable	240.00 FL	-	*- FL
30	1	*BOOTLID THIRD BRAKE LAMP	Serviceable	577.50 FL	-	*- FL
31	1	*REAR TRUNK LID LAMP RH	Serviceable	1,170.00 FL	-	*- FL
32	1	*REAR TRUNK LID LAMP LH	Serviceable	1,170.00 FL	-	*- FL
33	1	*REAR END PANEL OUTER	Bent	1,971.00 FL	-	*990.00 FL
34	1	*REAR END PANEL INNER	Repair	324.00 FL	-	*- FL
35	1	*REAR END PANEL INNER TRIM	Cracked	630.00 FL	-	*325.00 FL
36	1	*REAR END PANEL INNER TRIM FLAP	Serviceable	360.00 FL	-	*- FL
37	1	*REAR LAMP RH	Serviceable	1,170.00 FL	-	*- FL
38	1	*REAR LAMP PANEL OUTER RH	Repair	382.95 FL	-	*- FL
39	1	*REAR LAMP LH	Serviceable	1,170.00 FL	-	*- FL
40	1	*REAR LAMP PANEL OUTER LH	Repair	382.95 FL	-	*- FL
41	1	*REAR LUGGAGE FLOOR PANEL TRAY	Serviceable	762.00 FL	-	*- FL
42	1	*REAR LUGGAGE FLOOR COMPARTMENT TRAY	Serviceable	116.00 FL	-	*- FL
43	1	*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	420.00 FL	-	*- FL
44	1	*REAR FENDER LH	Repair	3,620.00 FL	-	*- FL
45	1	*REAR FENDER RH	Repair	3,620.00 FL	-	*- FL
46	1	*REAR FENDER TOP GARNISH RH	Serviceable	67.50 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
47	1	*REAR FENDER INNER TRIM RH	Serviceable	517.50 FL	-	*- FL
48	1	*REAR FENDER TOP GARNISH LH	Serviceable	67.50 FL	-	*- FL
49	1	*REAR FENDER INNER TRIM LH	Serviceable	517.50 FL	-	*- FL
50	1	*SET REAR BUMPER PARKING SENSOR	Shorted	1,200.00 FS	-	*500.00 FS
51	1	*SET BOOTLID INNER TRIM CLIP	Not Necessary	90.00 FS	-	*- FS
52	1	*SET REAR END PANEL INNER TRIM CLIP	Necessary	90.00 FS	-	*90.00 FS
53	1	*SET REAR BUMPER FASTENER CLIP	Necessary	101.54 FS	-	*101.54 FS
54	1	*SET REAR FENDER TOP GARNISH CLIP	Not Necessary	90.00 FS	-	*- FS
55	1	*SET REAR FENDER INNER TRIM CLIP	Not Necessary	45.00 FS	-	*- FS
56	1	*SET LICENSE PLATE	Not Necessary	225.00 FS	-	*- FS
57	1	*REAR WINDSCREEN GLASS SEALANT	Not Necessary	225.00 FS	-	*- FS
58	1	*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	180.00 FS	-	*- FS
59	1	*REAR WINDSCREEN MOULDING	Not Necessary	180.00 FS	-	*- FS
60	1	*TYRE MECHANICAL JACK	Serviceable	605.48 FS	-	*- FS
61	1	*TYRE MECHANICAL JACK HOLDER BRACKET	Repair	177.98 FS	-	*- FS
62	1	*REAR BOOTLID DYNASTY STICKER	Not Necessary	33.75 FS	-	*- FS
63	1	*WINDSCREEN SEALANT MOULDING	Not Necessary	180.00 FS	-	*- FS
64	1	*WINDSCREEN INNER SPONGE SEAL	Not Necessary	180.00 FS	-	*- FS
65	1	*REAR TYRE RH	Serviceable	550.00 FS	-	*- FS
66	1	*REAR ALLOY RIM RH	Serviceable	1,050.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	39,676.56	8,882.04
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,447.28	819.05
Total Parts (\$\$)	36,229.28	8,062.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	8,500.00	700.00
3	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	8,500.00	750.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	80.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
12	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
13	TOWING FEES	New	170.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
15	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
17	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
18	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
19	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
20	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS	New	480.00	0.00
Gross Labour Cost (S\$)			21,470.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >