

ASS. REC BY:

REF: CS/LPC/19018948A/f362

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ong Li Li

of: Lompac

Date/Time: 25.10.19 8.58am

Estimated Cost: 62199.354

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 5000C

Insured:

at Workshop w/a: K Kim Hin

Tel: 64527018

of: 160 Sn Ming Drive #02-20

Policy No: 2/19/V06/104779

Claim No: 19/19/19/V06/022540

Sum Insured:

Excess: 5750.00

Make of Veh:

D.O.A 17.10.2019

(Client's Record)

CA REV / REP. / REV 24 HRS

H.O.D Endorsement:

Date/Time: 25.10.19 9.44am

Person Contacted: Sandra

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 5000C - CS/LPC/19019037/Hqd3 R00 - 17/10/2019

29/10/19 @ 11.50am report to Ong Li Li via messenger.

29/10/19 @ 13:02 - Approval by Chew Beng Kee

30/10 @ 8:58am Inform workshop authorise repair excess \$3501.

\$13,962.20 confirm part by part, 8 days (Red: 10181.65: 34%)

ASS. REC BY:

REF

LPC/

ASSIGNMENT

From

Date

Estimated Cost

CD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop no.

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Proxy Condition)

Remark: The veh had commenced its
repair at the time of inspection

Est. or Market Value

EMC Accident Report

Consistent? Yes or No

GIA PR Seat

Consistent? Yes or No

Est. Repairs

days

Res

Yes or No

Lyn form

%

Yes

Yes or No

CA (REV) REP. 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Veh No

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Se Reading

Eng No

Chassis

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Incorporated / Jammed / Leaked / Burnt or

Brake: Incorporated / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD / AirRim or

Tyre Size

R:

BS / DUN / EXNOVA / GY / FS / LITZ / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R-Sai

L-Sai

D.O.A

Survey held at

Des. of Damages: PIR / Rear / OIS / N/S / UIC / Roof top or

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 13 JAN 2020

Draw Time: File Pass to:

13/1 Typst

Data Time: File Return to:



Preli Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



PA & PUK (\$



Lunch & Tea (\$

Report Format

Lump Sum / FR

OD

18,962-20

Survey Fee

Transportation

Lunch & Tea

Lunch & Tea

Lunch & Tea

Lunch & Tea

350

11

361

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019 19:35 Sendback Est	24 Oct 2019 21:15 S\$28,459.60	25 Oct 2019 08:38 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TROPIC PLANNERS & LANDSCAPE PTE LTD, Co. Reg. No.: 200210768H		
Vehicle Reg. No.:	GBC5000C	Date of Loss:	17/10/2019 23:00 - :59 [32 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 19/19/19/VC06/022540	Policy/Cover Note No.:	Z/19/VC06/104779 (Comprehensive)
Vehicle Reg. No. (TP):	SJY1156C	Policy No. (TP):	
		Excess:	S\$750.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/11/2019]		
Driver/Custodian:	YAP GEK PING, JESSICA (31 / Female), NRIC: S8802354D, Tel: +6591770737 Email: JESSICAYAP@TROPICPLANNERS.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

10/25/2019

OD: Longpac

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	RTI Assigned	Ins Auth'd	Status
Main	23 Oct 2019 19:35		24 Oct 2019 21:15 S\$28,459.60	25 Oct 2019 08:38		Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TROPIC PLANNERS & LANDSCAPE PTE LTD , Co. Reg. No.: 200210768H		
Vehicle Reg. No.:	GBC5000C	Date of Loss:	17/10/2019 23:00 - :59 [32 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 19/19/19/VC06/022540	Policy/Cover Note No.:	Z/19/VC06/104779 (Comprehensive)
Vehicle Reg. No. (TP):	SJY1156C	Policy No. (TP):	
		Excess:	S\$750.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561		
Driver/Custodian:	YAP GEK PING, JESSICA (31 / Female) , NRIC: S8802354D, Tel: +6591770737 Email: JESSICAYAP@TROPICPLANNERS.COM.SG		

ASSOCIATED MAIL RECEIVED[View All](#)[Compose Case Mail](#)

There are no mail for this case.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 30 October 2019 8:58 AM
To: 'sandrakhong@gmail.com'; 'service@kkimhin.com.sg'
Cc: SUR
Subject: GBC 5000C / OD / LONPAC

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBC 5000C (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

GBC5000C (19/19/19/VC06/022540)
[SJY1156C]

OD
Oct 17 2019 11:00PM
[TROPIC PLANNERS & LANDSCAPE PTE LTD]
K Kim Hin Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 29/10/2019 18:02 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$23212.85) - GBC5000C - Claim Handler: Ong Li Li

Approved:23212.85.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 29 Oct 2019

Preliminary Advice

Vehicle No	: GBC5000C	Accident Date	: 17/10/2019
Make	: MERCEDES-BENZ VITO 114	Policy No.	: Z/19/VC06/104779
Assignment Date	: 25/10/2019	Excess	: S\$750.00
Date of Inspection	: 25/10/2019	Est. Duration of Repair	: 8.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,459.60
Revised Amount	:S\$	14,579.55
Check Items (Estimated)	:S\$	8,633.30
Total	:S\$	23,212.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	34,337.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,663.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	768H

Vehicle Details

Vehicle No.:	GBC5000C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	VITO 114 CDI PANEL VAN LONG AT ABS 5DR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	6519033683617
Chassis No.:	WDF44760323214590
Maximum Power Output:	-
Open Market Value:	\$38,181.00
Original Registration Date:	08 Feb 2017
First Registration Date:	08 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$1,910.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	07 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$47,001.00
COE Rebate Amount:	\$34,337.00
Total Rebate Amount:	\$34,337.00

The information contained herein is correct as at 18 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2019 18:25
Date Of Accident	17/10/2019 23:40
Exact Location Of Accident	CTE TWDS BKE BEFORE ANG MO KIO AVE 3 & 5 SLIP RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC5000C
Insured/Policyholder	
Name Of Registered Owner	TROPIC PLANNERS & LANDSCAPE PTE LTD
Co Reg No	200210768H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67620500

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO 114-2.1 CDI PANEL VAN LONG ABS 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19/VC06/104779
Cover Note Number	

Driver

Name of Driver	YAP GEK PING, JESSICA
NRIC No	S8802354D
Date Of Birth	27/01/1988
Occupation	INDOOR
Date Of Driving Pass	02/03/2012
Driving Experience	7 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91770737
Fax Number	
Contact Number	
EEmail Address	JESSICAYAP@TROPICPLANNERS.COM.SG

Address	BLK 547 WOODLANDS DRIVE 16 #08-199
Postcode	730547
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : LIN SHIHONG GENDER: : MALE
Passenger 2	NAME: : JACKLYNN RAJAN GENDER: : FEMALE
Passenger 3	NAME: : RACHEL LARA GENDER: : FEMALE
Passenger 4	NAME: : GIBRONE CANO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN & POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY1156C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA KAK LEE
NRIC/Passport Number	S6912697I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC8550R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHA5985A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	YAP GEK PING, JESSICA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBC5000C
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

18/10/19 @ 5.39pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



A = GBC5000C
B = SJY1156C
C = SHC8550R
D = SHA5985A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT. - T|20191018|7011

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Company Chop (if applicable)

Driver's Signature _____

(If driver is not the policyholder)

Date & Time: 18/10/19 @ 5.39pm

Reporting Officer's Signature

Name:

NRIC/FIN No. _____



**SINGAPORE
POLICE FORCE**



T/20191018/7011

1 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20191018/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2019 14:29		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: YAP GEK PING, JESSICA			Address: APT BLK 547 WOODLANDS DRIVE 16 #08-199 SINGAPORE 730547		
ID Type / ID No.: NRIC NO / S8802354D			Contact No.: Home/Office: Mobile: 91770737		
Nationality: SINGAPORE CITIZEN			Email: jessica.yapgp@gmail.com		
Sex: Female	Age: 31	Date of Birth: 27/01/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Landscape operations manager			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/10/2019 23:35	Type of Location: Straight Road
Location: CTE towards BKE				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

Details of Vehicle Involved


Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC5000C	Van					0
SJY1156C	Car		Honda Civic	Grey	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191018/7011

2 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191018/7011

CONTINUATION OF REPORT

Driver			
Name	YAP GEK PING, JESSICA		ID No. S8802354D
Related Vehicle	GBC5000C (Van)		Contact No. 91770737
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	18/10/2019	Date Discharge	18/10/2019
No. of Days granted Medical Leave	01	Degree of Injury	Slight
Driver			
Name	CHUA KAK LEE		ID No. S6912697I
Related Vehicle	GBC5000C (Van)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	LIN SHIHONG		ID No. S8600078D
Related Vehicle	GBC5000C (Van)		Contact No. 92312414
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	GIBRONE CANO		ID No. NIL
Related Vehicle	GBC5000C (Van)		Contact No. 83150914
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20191018/7011

3 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20191018/7011

CONTINUATION OF REPORT

Passenger			
Name	JACKLYNN RAJAN	ID No.	NIL
Related Vehicle	GBC5000C (Van)	Contact No.	90694161
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	RACHEL LARA	ID No.	NIL
Related Vehicle	GBC5000C (Van)	Contact No.	97247106
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	LAU TECK SOON	ID No.	S7625318H
Related Vehicle	SJY1156C (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

It was along CTE towards BKE, just before slip road to Ang Mo Kio Ave 3 and Ave 5. I had 4 passengers at that point of collision. They are my colleagues whom I was driving back to home in Sembawang and Woodlands. It was a chain collision involving 7 vehicles and 2 motorbikes.

I saw 1st vehicle stopped suddenly which caused 2nd vehicle to hit 1st vehicle rear. 3rd vehicle was in front of me and tried to slow down to avoid the collision. I thought it managed to avoid the hit but couldn't and hit 2nd vehicle hence stopped suddenly. I tried to brake in time but 3rd vehicle stopped way too sudden, that it was inevitable to avoid so my vehicle hit the 3rd vehicle.

My air bag inflated because of the collision and burst as well. I was the 4th vehicle in line of the collision.

The 5th vehicle (behind me) managed to stop in time, leaving a gap between us. However the 6th vehicle hit the 5th one, and 2 motorbikes were involved as well as the 7th vehicle (last vehicle in line).



**SINGAPORE
POLICE FORCE**



T/20191018/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 5

Report No. T/20191018/7011

CONTINUATION OF REPORT

No ambulance came except a traffic marshal. Some vehicles were towed and some managed to drive away. My vehicle was towed last. I did not hear that anyone was injured except myself. I had bruise on my wrist and was swollen. X-ray did not show any sign of fracture but was given a tendon injection due to open wound at my wrist. Doctor advised to monitor condition and go for follow-up if swelling and pain continue.



**SINGAPORE
POLICE FORCE**



T/20191018/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

5 of 5

Report No. T/20191018/7011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Informant:
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Signature Of Interpreter:
Not applicable

Date/Time:
18/10/2019 14:29

Officer In Charge Of Case:
TP / TP1B /
ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP168

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Oct 2019)

Parts: N/A MERCEDES-BENZ VITO 114 2.1 CDI PANEL VAN LONG ABS 5DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*front bumper	0.00	0.00	R ₂ *640.00 F ✓
2	2		*front bumper side retainer (LH & RH)	0.00	0.00	D11 *80.00 F ✓
3	2		*front bumper bracket (LH & RH)	0.00	0.00	10 *20.00 F ✓
4	2		*front bumper inside part (LH & RH)	0.00	0.00	50 *100.00 F 2+
5	2		*front bumper lower bracket (LH & RH)	0.00	0.00	*24.00 F X
6	1		*front bumper lower cross member	0.00	0.00	R *150.00 F X
7	1		*front bumper under cover	0.00	0.00	Sn *62.00 F X
8	10		*front bumper clips	0.00	0.00	Rn *20.00 F ✓
9	1		*front bumper reinforcement	0.00	0.00	R ₂ *380.00 F ✓
10	2		*front bumper reinforcement bracket (LH & RH)	0.00	0.00	*4,060.00 F X
11	1		*front support panel	0.00	0.00	CM *220.00 F ✓
12	2		*front support panel side bracket (LH & RH)	0.00	0.00	26 *80.00 F 2+
13	1		*front support panel spring element	0.00	0.00	*20.00 F ✓
14	2		*front support panel stop buffer	0.00	0.00	Rn *16.00 F X
15	1		*front brace panel	0.00	0.00	R ₂ *52.00 F ✓
16	2		*front brace panel bracket (LH & RH)	0.00	0.00	CM *30.00 F ✓
17	1		*front grille	0.00	0.00	CM *88.00 F ✓
18	10		*front grille clips	0.00	0.00	Rn ²⁰ *40.00 F ✓
19	1		*front grille top garnish	0.00	0.00	CM *42.00 F ✓
20	2		*front grille chrome moulding top (LH & RH)	0.00	0.00	Rn *200.00 F ✓
21	2		*front grille chrome moulding centre (LH & RH)	0.00	0.00	Rn *200.00 F ✓
22	1		*front grille chrome moulding bottom	0.00	0.00	D11 *220.00 F ✓
23	1		*front grille logo	0.00	0.00	CM ₂ *70.00 F ✓
24	1		*front grille logo base	0.00	0.00	Rn *40.00 F ✓
25	2		*front fender (LH & RH)	0.00	0.00	Sn *880.00 F X
26	2		*front fender inner shield (LH & RH)	0.00	0.00	Sn *180.00 F X
27	1		*bonnet	0.00	0.00	R ₂ *830.00 F ✓
28	2		*bonnet hinges (LH & RH)	0.00	0.00	D11 *100.00 F 2+
29	1		*bonnet stay	0.00	0.00	Sn *47.00 F X
30	1		*bonnet stay clip holder	0.00	0.00	Rn *3.00 F ✓
31	1		*bonnet stay top garnish	0.00	0.00	Sn *15.00 F X
32	1		*bonnet stay lower lock	0.00	0.00	D11 *72.00 F ✓
33	1		*bonnet stay lower lock switch	0.00	0.00	Sn *66.00 F X
34	1		*bonnet stay upper lock catch	0.00	0.00	D11 *32.00 F ✓
35	1		*bonnet stay pull lock cable	0.00	0.00	Sn *32.00 F X
36	1		*air intake duct	0.00	0.00	CM *120.00 F ✓
37	1		*air cleaner box assy	0.00	0.00	CM ₂ *165.00 F ✓
38	1		*air cleaner box rear bracket LH	0.00	0.00	R *22.00 F X
39	1		*air cleaner box rear bracket RH	0.00	0.00	R *22.00 F ✓
40	1		*air intake pipe	0.00	0.00	Sn *150.00 F X
41	1		*air filter	0.00	0.00	Rn *22.00 F X
42	2		*headlamp (LH & RH)	0.00	0.00	*3,960.00 F ✓
43	2		*headlamp control unit (LH & RH)	0.00	0.00	Sn *710.00 F X
44	2		*headlamp voltage converter (LH & RH)	0.00	0.00	Sn *140.00 F X
45	1		*air con condenser	0.00	0.00	Rn *220.00 F 2+

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*air con condenser frame	0.00	0.00	CM 62.00F ✓
47	1		*radiator	Sm 0.00	0.00	240.00F X
48	1		*radiator air guide top	Sm 0.00	0.00	30.00F X
49	2		*radiator side air guide LH & RH	o/sim 0.00	0.00	40 380.00F ✓
50	2		*radiator top bush	0.00	0.00	Sm 28.00F X
51	2		*radiator top pin	Dis 0.00	0.00	Sm 16.00F X
52	2		*radiator bottom bracket	0.00	0.00	Sm 32.00F X
53	1		*radiator spare tank	0.00	0.00	Sm 62.00F X
54	1		*radiator spare tank top bypass hose	0.00	0.00	Sm 45.00F X
55	1		*radiator spare tank bottom bypass hose	0.00	0.00	Sm 55.00F X
56	1		*radiator fan assy	Sm 0.00	0.00	Sm 575.00F X
57	1		*inter cooler	Pr 0.00	0.00	Pr 510.00F X
58	1		*inter cooler air guide	Sm 0.00	0.00	Sm 66.00F X
59	1		*transmission oil	0.00	0.00	Sm 98.00F ✓
60	1		*transmission oil cooler	0.00	0.00	Pr 380.00F ✓
61	2		*engine mounting LH & RH	Sm 0.00	0.00	Sm 300.00F ✓
62	1		*gearbox mounting	Sm 0.00	0.00	Sm 130.00F ✓
63	1		*gearbox mounting bracket	Sm 0.00	0.00	Sm 340.00F ✓
64	1		*propeller shaft	0.00	0.00	Sm 715.00F X
65	2		*front crash sensor	Pr 0.00	0.00	Pr 0.00F ✓
66	1		*air bag control unit	0.00	0.00	Pr 820.00F ✓
67	1		*driver seat belt	0.00	0.00	Sm 430.00F ✓
68	1		*driver seat belt buckle	Sm 0.00	0.00	Sm 120.00F X
69	1		*steering air bag	Pr 0.00	0.00	Pr 1,600.00F ✓
70	1		*front passenger seat belt	0.00	0.00	Sm 430.00F ✓
71	1		*front passenger seat belt buckle	Sm 0.00	0.00	Sm 50.00F X
72	1		*front passenger air bag	Pr 0.00	0.00	Pr 1,600.00F ✓
73	1		*wiper washer tank neck	0.00	0.00	Sm 20.00F X
74	1		*front number plate	0	0.00	Pr 40.00FS ✓
75	1		*front bumper parking sensor	Sm 0	0.00	Sm 220.00FS X
76	1		*radiator coolant	0	0.00	Pr 48.00FS ✓

F=Franchise part. S=SpclNett.

Sub Total (\$\$)	21,692.00
+ Margin on L,N Items 15.00% (\$\$)	3,207.60
Total Parts (\$\$)	24,899.60

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary

1pc Battery Fuse Box (Ambig) ✓ 265.00 CM ✓
A4475404326.
1pc Front Centre Seat Belt ✓ 430.00 Sm ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING CHARGES	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New 600	1,000.00
3	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING, ONLINE RE-SETTING, PROGRAMMING AND LIGHTING OPERATION.	New 200	380.00
4	TO REMOVE AIR CON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS.	New	100.00 ✓
5	TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS.	New 250	280.00
6	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELT ASSY, TO REWIRING AND RE-SETTING PROGRAM.	New 240	300.00
7	TO REMOVE AND RENEW PROPELLER SHAFT.	New NN	200.00 X
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New 800	1,300.00
Gross Labour Cost (S\$)			3,560.00

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

\$ 13,813.00 - Part
+ \$ 695.00 - Supp

\$ 14,508.00

+ 157

\$ 16,684.20

\$ 88.00 - s/n

\$ 2,190.00 - Labor

P/P = \$ 18,962.20

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 05 Nov 2019)**Parts:** N/A MERCEDES-BENZ VITO 114 2.1 CDI PANEL VAN LONG ABS 5DR (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBC5000C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BATTERY FUSE BOX (AIRBAG)	0.00	0.00	265 465.00F
2	1		*FRONT CENTRE SEAT BELT	0.00	0.00	430.00 430.00F
F=Franchise part.						
Sub Total (S\$)						595.00
+ Margin on L,N Items 15.00% (S\$)						89.25
Total Parts (S\$)						684.25

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64599882
Business Reg & GST NO : 201512120M



TAX INVOICE

REPRINT

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.GBC5000C

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I258986
DATE : 01/11/2019
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 01/11/2019 09:48:23

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	124 990 0492TK	CLIP ✓	SS2A31	10	PCS	2.00	20.00
2	447 888 0023 9B51	RAD GILLE 9B51 ✓	3W2G02	1	PCD	86.00	86.00
3	207 817 0016MB	RAD GRILL STAR ✓	SS2D05	1	PCS	70.00	70.00
4	207 888 0260MB	RAD GRILL SUPPORT ✓	SS3B07	1	PCS	40.00	40.00
5	447 906 5400MB	HEAD LAMP UNIT LH ✓	3W2A06	1	PCS	1,980.0	1,980.00
6	447 906 5500MB	FRONT HEADLAMP RH ✓	3W2A02	1	PCS	1,980.0	1,980.00
7	000 991 2195MB	RAD CLIP ✓	SS2A25	2	PCS	8.00	16.00
8	001 989 7703 10	AT OIL 7G TRONIC 1LTR ✓	2W1D00	3	PCS	14.00	42.00
9	447 880 7701MB	FRONT BONNET	LC	1	PCS	830.00	830.00

RECEIVED BY

PICKED BY: M

SUB-TOTAL : S\$ 5,064.00
ADD 7% GST : S\$ 354.48
TOTAL : S\$ 5,418.48

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512420M



TAX INVOICE

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.GBC5000C

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I259854
DATE : 07/11/2019
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 08/11/2019 09:03:23

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
S 1	447 885 0064MB	FRONT PANEL LINK BLOCK	3W	1	PCS	10.00	10.00

RECEIVED BY

PICKED BY: M

SUB-TOTAL : S\$ 10.00
ADD 7% GST : S\$ 0.70
TOTAL : S\$ 10.70

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D258898

TAX INVOICE

REPRINT

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.GBC5000C

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I258898
DATE : 02/11/2019
A/C NO : 304710
TERM : 60
PAGE : 1 OF 2
ISSUE : APS

Printed on 04/11/2019 13:05:10

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT
1	447 885 0825 9999	FRONT TRIM, BUMPER	3W	1	PCS	640.00	640.00
2	447 880 0612MB	MOUNTING RAIL LH	3W	1	PCS	40.00	40.00
3	447 880 0724MB	FRT BUMPER BRACKET RH	3W	1	PCS	26.00	26.00
4	447 880 0712MB	FRONT BUMPER BRACKET RH	3W	1	PCS	40.00	40.00
5	000 991 9440MB	EXPANSION RIVET	3W	10	PCS	2.00	20.00
6	447 880 0316 9051	FRT BUMPER INSIDE PARTS RH	3W	1	PCS	50.00	50.00
7	447 620 0630MB	CROSSMEMBER,FRONT	3W	1	PCS	380.00	380.00
8	447 880 0127MB	BONNET SPRING	3W	2	PCS	20.00	40.00
9	447 880 1103MB	FRONT PANEL BEAM	3W	1	PCS	220.00	220.00
10	447 880 1003MB	FRONT BRACE PANEL	3W	1	PCS	52.00	52.00
11	447 885 0814MB	BRACKET LH	3W	1	PC	15.00	15.00
12	447 885 0914MB	BRACKET RH	3W	1	PC	15.00	15.00
13	447 885 0236 9051	AIR DUCT	3W	1	PC	42.00	42.00
14	447 888 01002B30	RAD.GRILLE CHROME LH	3W	1	PC	100.00	100.00
15	447 888 02002B30	RAD.GRILLE CHROME RH	3W	1	PC	100.00	100.00
16	447 888 0300 2B30	TRIM STRIP,LH	3W	1	PCS	100.00	100.00
17	447 888 0400 2B30	TRIM STRIP,RH	3W	1	PCS	100.00	100.00
18	447 888 0500 2B30	TRIM STRIP,BOTTOM	3W	1	PCS	220.00	220.00
19	447 880 4500MB	HINGE LH	3W	1	PCS	50.00	50.00
20	447 880 4600MB	HINGE RH	3W	1	PCS	50.00	50.00
21	447 880 0060MB	LOWER LOCK	3W	1	PCS	72.00	72.00
22	447 528 0724MB	AIR INTAKE DUCT	3W	1	PCS	120.00	120.00
23	447 528 0306MB	AIR BOX	3W	1	PC	165.00	165.00
24	447 835 0070MB	CONDENSER	3W	1	PCS	220.00	220.00
25	447 505 0041	AIR CON CONDERSOR FRAME	3W	1	PCS	40.00	40.00
26	447 501 1301MB	CHARGE AIR COOLER , AIR	3W	1	PCS	510.00	510.00
27	447 500 0001MB	OIL COOLER	3W	1	PCS	380.00	380.00

8514



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D259261

TAX INVOICE

K.KIM HIN AUTO PTE LTD
BLK160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
S'PORE 575708
REMARK : VEH NO.GBC5000C

DELIVER TO :
ENGINE #02-18/19
BODY PARTS #02-20/21

INV NO : I259261
DATE : 05/11/2019
A/C NO : 304710
TERM : 60
PAGE : 1 OF 1
ISSUE : APS

Printed on 02/11/2019 11:03:42

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	447 880 0160MB	UPPER LOCK CATAH	LC	1	PCS	32.00	32.00
2	447 900 0900MB	CONTROL UNIT AIR BAG	LC	1	PCS	820.00	820.00
3	447 860 3785 9C94	SEAT BELT	LC	1	PCS	430.00	430.00
4	447 860 0700 9C94	FRT SEAT BELT LH	DC	1	PCS	430.00	430.00
5	447 860 2585 9C97	FRT SEAT BELT CENTER	DC	1	PCS	430.00	430.00
6	000 860 1402 9116	DRIVER'S AIRBAG	DC	1	PCS	1,600.0	1,600.00
7	447 860 0202 9116	FRONT PASSENGER AIRBAG	DC	1	PCS	1,600.0	1,600.00

RECEIVED BY

PICKED BY:

SUB-TOTAL : S\$ 5,342.00
ADD 7% GST : S\$ 373.94
TOTAL : S\$ 5,715.94

Goods sold are not returnable except Repairs/Service at authorized workshop.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Oct 2019)

Parts: N/A MERCEDES-BENZ VITO 114 2.1 CDI PANEL VAN LONG ABS 5DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*front bumper	0.00	0.00	R ₁ *640.00 F	✓
2	2		*front bumper side retainer (LH & RH)	0.00	0.00	D11 *80.00 F	✓
3	2		*front bumper bracket (LH & RH)	0.00	0.00	*20.00 F	✓
4	2		*front bumper inside part (LH & RH)	0.00	0.00	50 *100.00 F	7
5	2		*front bumper lower bracket (LH & RH)	0.00	0.00	X *24.00 F	7
6	1		*front bumper lower cross member	0.00	0.00	R *150.00 F	X
7	1		*front bumper under cover	0.00	0.00	X *62.00 F	7
8	10		*front bumper clips	0.00	0.00	m *20.00 F	✓
9	1		*front bumper reinforcement	0.00	0.00	B ₁ *380.00 F	✓
10	2		*front bumper reinforcement bracket (LH & RH)	0.00	0.00	X *1,060.00 F	7
11	1		*front support panel	0.00	0.00	*220.00 F	7
12	2		*front support panel side bracket (LH & RH)	0.00	0.00	X *80.00 F	7
13	1		*front support panel spring element	0.00	0.00	hi *20.00 F	✓
14	2		*front support panel stop buffer	0.00	0.00	R ₁ *16.00 F	X
15	1		*front brace panel	0.00	0.00	cm *52.00 F	✓
16	2		*front brace panel bracket (LH & RH)	0.00	0.00	cm *30.00 F	✓
17	1		*front grille	0.00	0.00	cm *86.00 F	✓
18	10		*front grille clips	0.00	0.00	m *40.00 F	✓
19	1		*front grille top garnish	0.00	0.00	cm *42.00 F	✓
20	2		*front grille chrome moulding top (LH & RH)	0.00	0.00	m *200.00 F	✓
21	2		*front grille chrome moulding centre (LH & RH)	0.00	0.00	m *200.00 F	✓
22	1		*front grille chrome moulding bottom	0.00	0.00	D11 *220.00 F	✓
23	1		*front grille logo	0.00	0.00	cm *70.00 F	✓
24	1		*front grille logo base	0.00	0.00	nd *40.00 F	✓
25	2		*front fender (LH & RH)	0.00	0.00	R *860.00 F	X
26	2		*front fender inner shield (LH & RH)	0.00	0.00	sm *180.00 F	X
27	1		*bonnet	0.00	0.00	B ₁ *830.00 F	✓
28	2		*bonnet hinges (LH & RH)	0.00	0.00	R *100.00 F	7
29	1		*bonnet stay	0.00	0.00	sm *17.00 F	X
30	1		*bonnet stay clip holder	0.00	0.00	sm *3.00 F	✓
31	1		*bonnet stay top garnish	0.00	0.00	sm *15.00 F	X
32	1		*bonnet stay lower lock	0.00	0.00	D11 *72.00 F	✓
33	1		*bonnet stay lower lock switch	0.00	0.00	X *66.00 F	7
34	1		*bonnet stay upper lock catch	0.00	0.00	D11 *32.00 F	✓
35	1		*bonnet stay pull lock cable	0.00	0.00	X *32.00 F	7
36	1		*air intake duct	0.00	0.00	cm *120.00 F	✓
37	1		*air cleaner box assy	0.00	0.00	cm *165.00 F	✓
38	1		*air cleaner box rear bracket LH	0.00	0.00	R *22.00 F	X
39	1		*air cleaner box rear bracket RH	0.00	0.00	R *22.00 F	✓
40	1		*air intake pipe	0.00	0.00	sm *150.00 F	7
41	1		*air filter	0.00	0.00	sm *22.00 F	X
42	2		*headlamp (LH & RH)	0.00	0.00	ols nd/hy *3,960.00 F	✓
43	2		*headlamp control unit (LH & RH)	0.00	0.00	X *710.00 F	7
44	2		*headlamp voltage converter (LH & RH)	0.00	0.00	X *1,100.00 F	7
45	1		*air con condenser	0.00	0.00	*220.00 F	7

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*air con condenser frame	0.00	0.00	40 *62.00 F ?
47	1		*radiator	0.00	0.00	X *240.00 F ?
48	1		*radiator air guide top	0.00	0.00	X *30.00 F ?
49	2		*radiator side air guide LH & RH	0.00	0.00	40 *80.00 F ?
50	2		*radiator top bush	0.00	0.00	2 X *28.00 F X
51	2		*radiator top pin	0.00	0.00	2 X *16.00 F X
52	2		*radiator bottom bracket	0.00	0.00	2 X *32.00 F X
53	1		*radiator spare tank	0.00	0.00	2 X *62.00 F X
54	1		*radiator spare tank top bypass hose	0.00	0.00	2 X *45.00 F X
55	1		*radiator spare tank bottom bypass hose	0.00	0.00	2 X *55.00 F X
56	1		*radiator fan assy	0.00	0.00	X *575.00 F ?
57	1		*inter cooler	0.00	0.00	2 X *510.00 F ?
58	1		*inter cooler air guide	0.00	0.00	X *66.00 F ?
59	1		*transmission oil	0.00	0.00	2 X *98.00 F ✓
60	1		*transmission oil cooler	0.00	0.00	2 X *380.00 F ✓
61	2		*engine mounting LH & RH	0.00	0.00	X *300.00 F ?
62	1		*gearbox mounting	0.00	0.00	X *130.00 F ?
63	1		*gearbox mounting bracket	0.00	0.00	X *340.00 F ?
64	1		*propeller shaft	0.00	0.00	X *715.00 F ?
65	2		*front crash sensor	0.00	0.00	2 X *F ✓
66	1		*air bag control unit	0.00	0.00	2 X *820.00 F ✓
67	1		*driver seat belt	0.00	0.00	2 X *430.00 F ✓
68	1		*driver seat belt buckle	0.00	0.00	X *120.00 F ?
69	1		*steering air bag	0.00	0.00	2 X *1,600.00 F ✓
70	1		*front passenger seat belt	0.00	0.00	2 X *430.00 F ✓
71	1		*front passenger seat belt buckle	0.00	0.00	X *50.00 F ?
72	1		*front passenger air bag	0.00	0.00	2 X *1,600.00 F ✓
73	1		*wiper washer tank neck	0.00	0.00	2 X *20.00 F X
74	1		*front number plate	0	0.00	2 X *40.00 FS ✓
75	1		*front bumper parking sensor	0	0.00	X *220.00 FS ?
76	1		*radiator coolant	0	0.00	2 X *48.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	21,692.00
+ Margin on L,N Items 15.00% (\$\$)	3,207.60
Total Parts (\$\$)	24,899.60

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING CHARGES	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	600 1,000.00
3	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING, ONLINE RE-SETTING, PROGRAMMING AND LIGHTING OPERATION.	New	200 380.00
4	TO REMOVE AIR CON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS.	New	100.00 ✓
5	TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS.	New	250 280.00
6	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELT ASSY, TO REWIRING AND RE-SETTING PROGRAM.	New	240 300.00
7	TO REMOVE AND RENEW PROPELLER SHAFT.	New	200.00 ?
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	800 1,300.00
Gross Labour Cost (S\$)			3,560.00

K Kim Hin Auto Pte Ltd/GBC5000C/24/10/2019 21:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

CO. REG. NO: 199402370D
GST NO: M2-0123250-3**K. Kim Hin** AUTO PTE LTD**金興(龔)汽車私人有限公司**160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sgINSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC06/104779	Date of Loss:	17/10/2019
Vehicle Reg. No.:	GBC5000C	Driveable?	
Driver Age/Info:	31 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	TROPIC PLANNERS & LANDSCAPE PTE LTD		
Driver:	YAP GEK PING, JESSICA		

Make/Model:	MERCEDES-BENZ VITO 114, 2.1 CDI PANEL VAN LONG ABS 5DR (A)	Vehicle Reg. Date:	08/02/2017
Vehicle Colour:	BLACK	Chassis No:	WDF44760323214590
Engine No:	6519033683617		
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

8 days



Not authorized
Repair B4 paint
Ex 8750/
Fax: 62564315

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN & POLICE REPORT.

Remarks: DEAR OFFICER, PLS ARRANGE FOR SURVEY. VEHICLE TOWED IN. PLS NOTE NO STOCK, NEED TO ORDER ABOUT 15 DAYS. FRONT CRASH SENSOR NO PRICE. THANKS - SANDRA

Present Location: K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	24,899.60
Miscellaneous Items	0.00
Labour	3,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	28,459.60
+ GST 7.00% (\$\$)	1,992.17
Nett Amount (\$\$)	30,451.77

This claim is handled by: SANDRA KHONG YEE TENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019 19:35	24 Oct 2019 21:15	25 Oct 2019 08:38	S\$18,962.20	S\$18,962.20		Pending for Survey Report
	Sendback Est	S\$28,459.60	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	05 Nov 2019 15:57	05 Nov 2019 15:58	05 Nov 2019 15:58			(Combined)	Combined with Main
		S\$684.25					Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TROPIC PLANNERS & LANDSCAPE PTE LTD, Co. Reg. No.: 200210768H		
Vehicle Reg. No.:	GBC5000C	Date of Loss:	17/10/2019 23:00 - :59 [32 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 19/19/19/VC06/022540	Policy/Cover Note No.:	Z/19/VC06/104779 (Comprehensive)
Vehicle Reg. No. (TP):	SJY1156C	Policy No. (TP):	
		Excess:	S\$750.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/11/2019]		
Driver/Custodian:	YAP GEK PING, JESSICA (31 / Female) , NRIC: S8802354D, Tel: +6591770737 Email: JESSICAYAP@TROPICPLANNERS.COM.SG		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (10/01/2020): Adjuster mandate request
- LONPAC_HQ (29/10/2019): Alert - Adj Mandate Approved (S\$23212.85) - GBC5000C - Claim Handler: Ong Li Li

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBC5000C (19/19/19/VC06/022540)
[SJY1156C]
OD
Oct 17 2019 11:00PM
[TROPIC PLANNERS & LANDSCAPE PTE LTD]
K Kim Hin Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 18:45	Video - Accident [Linked Accident Report Documents]	Load MP4	

Letters/Correspondences

1 per page

No	Finalized On	Lonpac Insurance Bhd (HQ)	Thumbnail	Print
1	25/10/19 08:47	OD Letter	Load HTM	

Assessment Reports

1 per page

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	24/10/19 21:15	Repairer Estimates	Load HTM	
2	05/11/19 15:58	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/19 11:49	Adjuster Immediate Advice	Load HTM	
2	09/01/20 12:11	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/19 11:40	General View	Load JPG	☒
2	29/10/19 11:40	General View	Load JPG	☒
3	29/10/19 11:40	General View	Load JPG	☒
4	29/10/19 11:40	General View	Load JPG	☒
5	29/10/19 11:40	General View	Load JPG	☒
6	29/10/19 11:40	General View	Load JPG	☒
7	29/10/19 11:40	General View	Load JPG	☒
8	29/10/19 11:40	General View	Load JPG	☒
9	29/10/19 11:40	General View	Load JPG	☒
10	29/10/19 11:40	General View	Load JPG	☒
11	29/10/19 11:40	General View	Load JPG	☒
12	29/10/19 11:40	General View	Load JPG	☒
13	29/10/19 11:40	General View	Load JPG	☒
14	29/10/19 11:40	General View	Load JPG	☒
15	29/10/19 11:40	General View	Load JPG	☒
16	29/10/19 11:40	Odometer Reading	Load JPG	☒
17	29/10/19 11:40	General View	Load JPG	☒
18	29/10/19 11:40	General View	Load JPG	☒
19	29/10/19 11:40	Chassis Number	Load JPG	☒
20	29/10/19 11:40	General View	Load JPG	☒
21	29/10/19 11:40	General View	Load JPG	☒
22	29/10/19 11:40	General View	Load JPG	☒
23	29/10/19 11:40	General View	Load JPG	☒
24	09/01/20 12:01	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
25	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
26	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
27	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
28	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
29	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
30	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
31	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
32	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
33	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
34	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
35	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
36	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
37	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
38	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
39	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
40	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
41	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
42	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
43	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
44	09/01/20 12:01	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/10/19 19:36	Log card (if available)	 Load PDF	
2	23/10/19 19:36	Driver's Driving License	 Load PDF	
3	23/10/19 19:36	Transfer Fee	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/19 11:40	ESTIMATE	 Load PDF	
2	09/01/20 11:52	ESTIMATE	 Load PDF	
3	09/01/20 11:52	SUPPLEMENTARY	 Load PDF	
4	23/01/20 14:03	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 18:45	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 19:05	Accident Statement	 Load HTM	
2	06/12/19 19:07	Accident Statement	 Load HTM	
3	06/12/19 19:12	Accident Statement	 Load HTM	
4	06/12/19 19:14	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 18:37	Accident Photo	 Load JPG	☒
2	18/10/19 18:37	Accident Photo	 Load JPG	☒
3	18/10/19 18:37	Accident Photo	 Load JPG	☒
4	18/10/19 18:37	Accident Photo	 Load JPG	☒
5	18/10/19 18:37	Accident Photo	 Load JPG	☒
6	18/10/19 18:37	Accident Photo	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
7	18/10/19 18:37	Accident Photo		Load JPG	☒
8	18/10/19 18:37	Accident Photo		Load JPG	☒
9	18/10/19 18:43	Accident Photo		Load JPG	☒
10	18/10/19 18:43	Accident Photo		Load JPG	☒
11	18/10/19 18:43	Accident Photo		Load JPG	☒
12	18/10/19 18:43	Accident Photo		Load JPG	☒
13	18/10/19 18:43	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	18/10/19 18:36	Sketch Plan		Load TIF	
2	18/10/19 18:36	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19018948/KTF3E2

Date: 23/01/2020

REFERENCE

Insured/Claimant: TROPIC PLANNERS & LANDSCAPE PTE LTD

Policy No: Z/19/VC06/104779

Date of Loss: 17/10/2019

Nature of Claim:

OD

Claim No:

19/19/19/VC06/022540

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC5000C

Make & Model: MERCEDES-BENZ VITO 114, 2.1 CDI PANEL VAN
LONG ABS 5DR (A)

Engine No: 6519033683617

Reg. Date: 08/02/2017 (Man. Year: 2016)

Chassis No: WDF44760323214590

Colour: Black

Odometer: 63939 km

Engine Capacity: 2143 cc

Market Value/New Car Price: S\$71,000.00

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,583.85	16,772.20	8,811.65	34.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,190.00	1,370.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,143.85	18,962.20	10,181.65	34.94
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	29,143.85	18,212.20	10,931.65	37.51
+ GST 7.00/7.00% (\$\$)	2,040.07	1,274.85	765.22	37.51
Nett Amount (\$\$)	31,183.92	19,487.05	11,696.87	37.51

INSPECTION

Date of Assignment: 25/10/2019 Present Location:
Date Inspected: 25/10/2019 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Jan 2020)	
Parts:	N/A	MERCEDES-BENZ VITO 114 2.1 CDI PANEL VAN LONG ABS 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC5000C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bumper (WCP)	Bent	640.00 F	*640.00 F
2	2		*front bumper side retainer (LH & RH) (WCP)	Distorted	80.00 F	*80.00 F
3	2		*front bumper bracket (LH & RH) (WCP)	N/S Distorted / O/S Cracked	20.00 F	*10.00 F
4	1		*front bumper inside part (LH & RH) (WCP)	O/S Cracked	100.00 F	*50.00 F
5	2		*front bumper lower bracket (LH & RH) (WCP)	Repair	24.00 F	*- F
6	1		*front bumper lower cross member (WCP)	Repair	150.00 F	*- F
7	1		*front bumper under cover (WCP)	Serviceable	62.00 F	*- F
8	10		*front bumper clips (WCP)	Necessary	20.00 F	*20.00 F
9	1		*front bumper reinforcement (WCP)	Bent	380.00 F	*380.00 F
10	2		*front bumper reinforcement bracket (LH & RH) (WCP)	Repair	1,060.00 F	*- F
11	1		*front support panel (WCP)	Cracked	220.00 F	*220.00 F
12	1		*front support panel side bracket (LH & RH) (WCP)	O/S Cracked	80.00 F	*26.00 F
13	1		*front support panel spring element (WCP)	Missing	20.00 F	*20.00 F
14	2		*front support panel stop buffer (WCP)	Serviceable	16.00 F	*- F
15	1		*front brace panel (WCP)	Bent	52.00 F	*52.00 F
16	2		*front brace panel bracket (LH & RH) (WCP)	Cracked	30.00 F	*30.00 F
17	1		*front grille (WCP)	Cracked	86.00 F	*86.00 F
18	10		*front grille clips (WCP)	Necessary	40.00 F	*20.00 F
19	1		*front grille top garnish (WCP)	Cracked	42.00 F	*42.00 F
20	2		*front grille chrome moulding top (LH & RH) (WCP)	Necessary	200.00 F	*200.00 F
21	2		*front grille chrome moulding centre (LH & RH) (WCP)	Necessary	200.00 F	*200.00 F
22	1			Distorted	220.00 F	*220.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*front grille chrome moulding bottom (WCP)			
23	1		*front grille logo (WCP)	Cracked	70.00 F	*70.00 F
24	1		*front grille logo base (WCP)	Dented	40.00 F	*40.00 F
25	2		*front fender (LH & RH) (WCP)	Repair	860.00 F	*- F
26	2		*front fender inner shield (LH & RH) (WCP)	Serviceable	180.00 F	*- F
27	1		*bonnet (WCP)	Bent	830.00 F	*830.00 F
28	2		*bonnet hinges (LH & RH) (WCP)	Distorted	100.00 F	*100.00 F
29	1		*bonnet stay (WCP)	Serviceable	17.00 F	*- F
30	1		*bonnet stay clip holder (WCP)	Serviceable	3.00 F	*- F
31	1		*bonnet stay top garnish (WCP)	Serviceable	15.00 F	*- F
32	1		*bonnet stay lower lock (WCP)	Distorted	72.00 F	*72.00 F
33	1		*bonnet stay lower lock switch (WCP)	Serviceable	66.00 F	*- F
34	1		*bonnet stay upper lock catch (WCP)	Distorted	32.00 F	*32.00 F
35	1		*bonnet stay pull lock cable (WCP)	Serviceable	32.00 F	*- F
36	1		*air intake duct (WCP)	Cracked	120.00 F	*120.00 F
37	1		*air cleaner box assy (WCP)	Cracked	165.00 F	*165.00 F
38	1		*air cleaner box rear bracket LH (WCP)	Repair	22.00 F	*- F
39	1		*air cleaner box rear bracket RH (WCP)	Repair	22.00 F	*- F
40	1		*air intake pipe (WCP)	Serviceable	150.00 F	*- F
41	1		*air filter (WCP)	Serviceable	22.00 F	*- F
42	2		*headlamp (LH & RH) (WCP)	O/S Dented / Cut / N/S Cracked	3,960.00 F	*3,960.00 F
43	2		*headlamp control unit (LH & RH) (WCP)	Serviceable	710.00 F	*- F
44	2		*headlamp voltage converter (LH & RH) (WCP)	Serviceable	1,100.00 F	*- F
45	1		*air con condenser (WCP)	Punctured	220.00 F	*220.00 F
46	1		*air con condenser frame (WCP)	Cracked	62.00 F	*40.00 F
47	1		*radiator (WCP)	Serviceable	240.00 F	*- F
48	1		*radiator air guide top (WCP)	Serviceable	30.00 F	*- F
49	1		*radiator side air guide LH & RH (WCP)	O/S Cracked	80.00 F	*40.00 F
50	2		*radiator top bush (WCP)	Serviceable	28.00 F	*- F
51	2		*radiator top pin (WCP)	Distorted	16.00 F	*16.00 F
52	2		*radiator bottom bracket (WCP)	Repair	32.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*radiator spare tank (WCP)	Serviceable	62.00 F	*- F
54	1		*radiator spare tank top bypass hose (WCP)	Serviceable	45.00 F	*- F
55	1		*radiator spare tank bottom bypass hose (WCP)	Serviceable	55.00 F	*- F
56	1		*radiator fan assy (WCP)	Serviceable	575.00 F	*- F
57	1		*inter cooler (WCP)	Punctured	510.00 F	*510.00 F
58	1		*inter cooler air guide (WCP)	Serviceable	66.00 F	*- F
59	1		*transmission oil (WCP)	Necessary	98.00 F	*42.00 F
60	1		*transmission oil cooler (WCP)	Punctured	380.00 F	*380.00 F
61	2		*engine mounting LH & RH (WCP)	Serviceable	300.00 F	*- F
62	1		*gearbox mounting (WCP)	Serviceable	130.00 F	*- F
63	1		*gearbox mounting bracket (WCP)	Serviceable	340.00 F	*- F
64	1		*propeller shaft (WCP)	Repair	715.00 F	*- F
65	2		*front crash sensor (NPA)	Necessary	0.00 F	*- F
66	1		*air bag control unit (WCP)	Necessary	820.00 F	*820.00 F
67	1		*driver seat belt (WCP)	Jammed	430.00 F	*430.00 F
68	1		*driver seat belt buckle (WCP)	Serviceable	120.00 F	*- F
69	1		*steering air bag (WCP)	Burst	1,600.00 F	*1,600.00 F
70	1		*front passenger seat belt (WCP)	Jammed	430.00 F	*430.00 F
71	1		*front passenger seat belt buckle (WCP)	Serviceable	50.00 F	*- F
72	1		*front passenger air bag (WCP)	Burst	1,600.00 F	*1,600.00 F
73	1		*wiper washer tank neck (WCP)	Serviceable	20.00 F	*- F
74	1		*front number plate	Bent	40.00 FS	*40.00 FS
75	1		*front bumper parking sensor	Serviceable	220.00 FS	*- FS
76	1		*radiator coolant	Necessary	48.00 FS	*48.00 FS
Supplementary #1						
77	1		*BATTERY FUSE BOX (AIRBAG) (WCP)	Cracked	165.00 F	*265.00 F
78	1		*FRONT CENTRE SEAT BELT (WCP)	Jammed	430.00 F	*430.00 F

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	22,287.00	14,596.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	3,296.85	2,176.20
Total Parts (\$\$)	25,583.85	16,772.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES (NPA)	New	0.00	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1,000.00	600.00
3	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING, ONLINE RE-SETTING, PROGRAMMING AND LIGHTING OPERATION.	New	380.00	200.00
4	TO REMOVE AIR CON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS.	New	100.00	100.00
5	TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS.	New	280.00	250.00
6	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELT ASSY, TO REWIRING AND RE-SETTING PROGRAM.	New	300.00	240.00
7	TO REMOVE AND RENEW PROPELLER SHAFT.	New	200.00	0.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,300.00	800.00
Gross Labour Cost (\$\$)			3,560.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >