

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBD9727H		
TP Vehicle No	: SMM3543H	Accident Date	: 21/10/2019
Make	: HONDA SHUTTLE HYBRID	Assignment Date	: 25/10/2019
Date of Inspection	: 25/10/2019	Est. Duration of Repair	: 4 days
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion, rear windscreen shattered and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,193.60
Revised Amount	:S\$	2,526.32
Check Items (Estimated)	:S\$	1,645.28
Total	:S\$	4,171.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP