

ASS. REC. BY:

REF:

EG190018959/Usd300

Special Instruction:

Summr: Marcus

Meunmen

ASSIGNMENT (Office)

From (Person):

Pauline soh

of

EGI

Date/Time:

25/10/2019 @ 10.51 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 3543H

Insured:

GBD 9727H

at Workshop m/s

Yew Tee Automobile

Tel:

6702 3113

of

25 kiki Bukit Road 4 # 01-G1 Synergy

Policy No:

Claim No:

CDMCG19001994

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:24 am 25/10/19

Person Contacted:

Venice

Vehicle

IN/OUT

Date/Time

Action/Instruction

Tohond? ✓

RMM 3543H - X

GBD 9727H - X.

29/10/19

@ 11:53 am revised PA to Pauline Soh via meunmen.

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A52145

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smm 35434

Yr Regn:

6, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Shuttle Hybrid 1496

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

17503

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP 7 2003031

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/10/19

D.O.I.

25/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 7/5. & Rear wheel

The U/C / Chassis frame / Body Structure affected due to collision.

shattered

Date / Time

Action / Instruction

30/10/19 @ 2446.32 confirmed with Maj
(\$ 7,747.28 Red - 76%)

RECEIVED 30 OCT 2019

Date/Time, File Pass to?

30/10/19

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



W/End (\$

Survey Fee:

350

Transportation:

3 + RS \$

Photos

Others

TOTAL

11

361

Report Form:

Lump Sum / U/C:

\$ 2,446.32 r/p

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Friday, 25 October 2019 10:51 AM
To: YT(KB); Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Ivy Yong; Phoebe Xie; utauto@singnet.com.sg
Subject: RE: Claims ref no. (P) CDMCG19001994 Accident involving SMM3543H (MSIG) claiming against GBD9727H (Ergo) on 21/10/2019

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: YT(KB) [mailto:info@yewteegroup.com]
Sent: Friday, 25 October 2019 9:48 am
To: ERGO Insurance Pte. Ltd. (Claims Department); Pauline Soh
Cc: Ivy Yong; Phoebe Xie; utauto@singnet.com.sg
Subject: RE: Claims ref no. (P) CDMCG19001994 Accident involving SMM3543H (MSIG) claiming against GBD9727H (Ergo) on 21/10/2019

Hi,

We choose LKK.

Any possibility can arrange the survey on today?

Thank you.

Best Regards



Yew Tee Automobile Tech Pte Ltd

Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4,
#01-61, Singapore 417800

Office: 6702 3113

Email: utauto2@singnet.com.sg



Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>

Sent: Friday, October 25, 2019 9:40 AM

To: info@yewteegroup.com; Pauline Soh <pauline.soh@ergo.com.sg>

Cc: Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>

Subject: FW: Claims ref no. (P) CDMCG19001994 Accident involving SMM3543H (MSIG) claiming against GBD9727H (Ergo) on 21/10/2019

Dear May

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
pauline.soh@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: YT(KB) [<mailto:info@yewteegroup.com>]
Sent: Thursday, 24 October 2019 10:11 am
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: utauto@singnet.com.sg
Subject: Accident involving SMM3543H (MSIG) claiming against GBD9727H (Ergo) on 21/10/2019

Hi,

Kindly find attached GIA Report and arrange survey before repair at Kaki Bukit.

Do let us know the Officer In Charge and Surveyor list to choose.

Thank you.

Best Regards

MAY



Yew Tee Automobile Tech Pte Ltd

Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4,
#01-61, Singapore 417800

Office: 6702 3113

Email: utauto2@singnet.com.sg

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	694C
Vehicle Details	
Vehicle No.:	SMM3543H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB7104013
Chassis No.:	GP72003031
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,333.00
Original Registration Date:	26 Jun 2019
First Registration Date:	26 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$14,667.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2029
PARF Rebate Amount:	\$11,000.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,564.00
COE Rebate Amount:	\$41,145.00
Total Rebate Amount:	\$52,145.00

The information contained herein is correct as at 25 Oct 2019

OK

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

New 5 Years Renewal COE Honda Stream 1.8A.










2.88% P.A, \$0 Admin, Monthly
From \$688, 2 Year Warranty
Engine.
StarAd

Browse by Category Sort by Date Posted 20 results/page

18 vehicles

shuttle

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	shuttle		Any	Any	2019	Any	Any	Any	Available
	Honda	Shuttle 1.5A G Honda Sensing	\$79,888	\$7,440 /yr	10-Sep-2019	1,496 cc	3 km	Stationwagon	Available
2019 New Facelift, Vitas Ready, Immediate Delivery, Full Accessories With GPS, Front And Rear Recording Camera, High Trade In Your... HTS Motor Posted: 25-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									
	Honda	Shuttle Hybrid 1.5A	\$85,800	\$8,610 /yr	21-Jan-2019	1,496 cc	9 km	Stationwagon	Available
Fuel Type: Petrol-Electric 5 Years Warranty! 3 x Free Servicing! 2019 Latest Model! Vitas Ready, Flexible Loan And High Trade In. Dynamic And Responsive, Rugg... Shuang Hup Credit Posted: 24-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									
	Honda	Shuttle Hybrid 1.5A	\$83,800	\$8,460 /yr	23-Jan-2019	1,496 cc	14,107 km	Stationwagon	Available
Fuel Type: Petrol-Electric Zero Down Payment Or High Loan Can Be Arranged With Attractive Interest Rates. Featuring Honda's Latest Hybrid Technology, The Sh... Swee Seng Motors Posted: 23-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									
	Honda	Shuttle 1.5A G	\$79,800	\$7,950 /yr	21-Mar-2019	1,496 cc	12,000 km	Stationwagon	Available
Cheapest In The Market, Full Loan Available, Still Under 3 Years Warranty! Well Taken Care By Previous Owner, Accident Free Condition,... Heritage Auto Enterprise Pte Ltd Posted: 22-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									
	Scuff Plate (With LED) Shuttle LED moving scuff plate with 1 year company warranty. LED color available in white, red or blue. More info about this product								
	Honda	Shuttle Hybrid 1.5A	\$94,800	\$9,510 /yr	18-Jan-2019	1,496 cc	10 km	Stationwagon	Available
Fuel Type: Petrol-Electric Low-Interest Rate. 2019 Facelift Model. 3 Years Warranty With 3 Free Servicing. Balloon Scheme, In House Financing Options Available.... GOwheeler Pte Ltd Posted: 17-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									
	Honda	Shuttle 1.5A G	\$89,800	\$8,830 /yr	30-May-2019	1,496 cc	-	Stationwagon	Available
Newly Registered Honda Shuttle In Petrol Or Hybrid. Super Extra Large Boot Space And Quiet Drive. Good Fuel Consumption With Sport... Car (S) Pte Ltd Posted: 16-Oct-2019 Tags: 2019 Honda Shuttle, 2019 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used									

Compare

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBD9727H	Accident Date	: 21/10/2019
TP Vehicle No	: SMM3543H	Assignment Date	: 25/10/2019
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 4 days
Date of Inspection	: 25/10/2019		
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion, rear windscreen shattered and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,193.60
Revised Amount	:S\$	2,526.32
Check Items (Estimated)	:S\$	1,645.28
Total	:S\$	4,171.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2019 11:11
Date Of Accident	21/10/2019 17:45
Exact Location Of Accident	PIE TOWARDS CHANGI (PIE & KJE JUNCTION)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM3543H
Insured/Policyholder	
Name Of Registered Owner	ADVANCE LIMO & RENTAL PTE LTD
Co Reg No	201406694C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97944506

Vehicle Particulars

Manufacturer	HONDA
Model	HONDA SHUTTLE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29128626MCX
Cover Note Number	

Driver

Name of Driver	TOH MEOW CHENG
NRIC No	S8369005D
Date Of Birth	25/01/1983
Occupation	OUTDOOR
Date Of Driving Pass	03/07/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97944506
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 117 JURONG EAST STREET 13 #03-147
Postcode	600117
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9727H
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG KIM YOKE
NRIC/Passport Number	S6868213D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

Form No. 1 (Rev. 4)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to the relevant parties involved.
2. This Form will be completed by the Policyholder and/or the Exchange Driver.
3. All information provided must be as truthful and accurate as possible and will be used to manage and settling of claims. Falsely stating insurance companies to avoid its policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with regulatory requirements and the Regulatory News Distribution System.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Date & Time

Witnessing Centre Personnel's Signature
Name:
NRIC/ID No.:

Sketch Plan #2



A = 9MM3543H

B = 9BD9727H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight, front car already stop and I was slowing down and stopped. After a few second, CAR B suddenly collided into my rear left portion with strong impact.

DECLARATION

I hereby declare that the foregoing particulars are true and correct.



Signature
Date & Time:

Driver's Signature
(If driver is not the police officer)
Date & Time:

Inspector's Signature
Name
NR (Officer's Name):

Estimate Report

10/25/2019

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : MSIG INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	B29128626MCX	Date of Loss:	21/10/2019
Vehicle Reg. No.:	SMM3543H	Driveable?	yes
Driver Age:	0000-00-00	Third Party Vehicle No.:	GBD9727H
Any Injuries?	no	Contact No:	97944506
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	TOH MEOW CHENG

Make/Model:	Honda, HONDA HYBRID 1.5G AUTO	Vehicle Reg. Date:	26/06/2019
Vehicle Colour:	WHITE	Engine Number:	LEB7104013
Chassis No:	GP72003031	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD TO REAR

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	6,909.60
Miscellaneous Items	939.00
Labour	1,290.00
Paintwork Labour	1,055.00
Towing	0.00
Gross Total(S\$):	10,193.60
GST 7.00%(S\$):	713.55
Nett Amount(S\$):	10,907.15

This claim is handled by: Venice

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- * To inspect damaged part(s) during resurvey
- * Resurvey results are subject to confirmation
- * To resurvey is on a "Without Prejudice" basis
- * No further modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
 after
 the ph. before resurvey
 25/10/19
 4dy.
 2/28 2446.32

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	REAR TAILGATE <i>n</i>	1,198.20	-20.00	958.56	X
2	1	TAILGATE TOP SPOILER <i>n</i>	1,050.20	-20.00	840.16	X
3	1	TAILGATE "SHUTTLE" EMBLEM <i>nu</i>	55.40	-20.00	44.32	X
4	1	TAILGATE OUTER GARNISH <i>su</i>	383.20	-20.00	306.56	X
5	1	TAILGATE OUTER CHROME <i>u1</i>	383.20	-20.00	306.56	X
6	1	BOOTLID TAILLAMP LH <i>su</i>	340.80	-20.00	272.64	X
7	1	TAILGATE "H" EMBLEM <i>u1</i>	38.40	-20.00	30.72	X
8	1	TAILGATE "HYBRID" EMBLEM <i>nu</i>	75.40	-20.00	60.32	X
9	1	TAILGATE WIPER BLADE <i>u1</i>	48.20	-20.00	38.56	X
10	1	TAILGATE WIPER MOTOR <i>u1</i>	490.00	-20.00	392.00	X
11	1	TAILGATE BRAKE LAMP <i>u1</i>	168.20	-20.00	134.56	X
12	1	TAILGATE INSULATOR <i>u1</i>	320.00	-20.00	256.00	X
13	1	TAILGATE INNER TOP GARNISH <i>su</i>	0.00	-20.00	0.00	X
14	1	TAILGATE INNER SIDE GARNISH LH <i>su</i>	0.00	-20.00	0.00	X
15	1	REAR WINDSCREEN GLASS <i>Shorho</i>	1,210.40	-20.00	968.32	X
16	1	REAR WINDSCREEN GLASS MOULDING <i>nu</i>	149.20	-20.00	119.36	X
17	1	REAR BUMPER <i>n</i>	1,150.20	-20.00	920.16	X
18	1	REAR BUMPER REFLECTOR LH <i>su</i>	45.20	-20.00	36.16	X
19	1	TAILLAMP LH <i>su</i>	520.40	-20.00	416.32	X
20	1	REAR LH FENDER <i>n</i>	1,010.40	-20.00	808.32	X

Total Parts (\$\$) 6,909.60

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	CAMERA SET <i>u1</i>	550.00	0.00	550.00	X
2	1	WINDSCREEN SEALANT <i>nu</i>	24.00	0.00	24.00	X
3	1	PRIVATE HIRER DECAL <i>nu</i>	20.00	0.00	20.00	X
4	1	REAR BUMPER SENSOR <i>u1</i>	300.00	0.00	300.00	X
5	1	REAR BUMPER CLIP <i>u1</i>	45.00	0.00	45.00	X

Sub Total (\$\$) 939.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	0.00	200.00	40
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00	X
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00	X
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00	X
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00	20
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00	300

Gross Labour Cost (\$\$) 1,290.00

P- 1490.40
20%
P- 1192.32
S.N- 44.00
L- 1210.00
~ 1.1.1.1.1.1 ~

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	950.00	0.00	950.00

Gross Labour Cost (\$\$) 1,055.00

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Oct 2019 11:49 Edit Reg		25 Oct 2019 00:00 Edit Adj Rpt	S\$2,446.32 Edit Estimates	S\$2,446.32 View Rpt		Pending for Survey Report Cancel Case





Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: SMM3543H		Date of Loss: 21/10/2019 00:00 - :59 [3 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBD9727H		Policy No. (Claimant):							
		Excess:							
Repairer: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113									
Handling Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMM3543H
[GBD9727H]
TP
-

Oct 21 2019 12:00AM
[-]
Yew Tee Automobile Tech Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/19 11:53	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	30/10/19 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/10/19 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	30/10/19 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	30/10/19 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19018959/USD3E2

Date: 31/10/2019

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMM3543H

Insured Vehicle No : GBD9727H

Date of Loss: 21/10/2019

Nature of Claim:

TP

Claim No: CDMCG19001994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMM3543H

Make & Model:

HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No:

LEB7104013

Reg. Date:

26/06/2019 (Man. Year: 2018)

Chassis No:

GP72003031

Colour:

White

Odometer:

17503 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side:

Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side:

Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,848.60	1,236.32	6,612.28	84.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,345.00	1,210.00	1,135.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,193.60	2,446.32	7,747.28	76.00
+ GST 7.00/7.00% (S\$)	713.55	171.24	542.31	76.00
Nett Amount (S\$)	10,907.15	2,617.56	8,289.59	76.00

INSPECTION

Date of Assignment:

25/10/2019

Date Inspected:

25/10/2019 Inspected At:

Yew Tee Automobile Tech Pte Ltd
(Kaki Bukit)
Blk 25 Kaki Bukit Road 4, #01-61
SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Oct 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3543H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,198.20 FL	*- FL
2	1		*TAILGATE TOP SPOILER	Repair	1,050.20 FL	*- FL
3	1		*TAILGATE SHUTTLE EMBLEM	Necessary	55.40 FL	*55.40 FL
4	1		*TAILGATE OUTER GARNISH	Serviceable	383.20 FL	*- FL
5	1		*TAILGATE OUTER CHROME	Not Necessary	383.20 FL	*- FL
6	1		*BOOTLID TAILLAMP LH	Serviceable	340.80 FL	*- FL
7	1		*TAILGATE H EMBLEM	Not Necessary	38.40 FL	*- FL
8	1		*TAILGATE HYBRID EMBLEM	Necessary	75.40 FL	*75.40 FL
9	1		*TAILGATE WIPER BLADE	Not Necessary	48.20 FL	*- FL
10	1		*TAILGATE WIPER MOTOR	Not Necessary	490.00 FL	*- FL
11	1		*TAILGATE BRAKE LAMP	Not Necessary	168.20 FL	*- FL
12	1		*TAILGATE INSULATOR	Not Necessary	320.00 FL	*- FL
13	1		*TAILGATE INNER TOP GARNISH (NPA)	Serviceable	0.00 FL	*- FL
14	1		*TAILGATE INNER SIDE GARNISH LH (NPA)	Serviceable	0.00 FL	*- FL
15	1		*REAR WINDSCREEN GLASS	Shorted	1,210.40 FL	*1,210.40 FL
16	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	149.20 FL	*149.20 FL
17	1		*REAR BUMPER	Repair	1,150.20 FL	*- FL
18	1		*REAR BUMPER REFLECTOR LH	Serviceable	45.20 FL	*- FL
19	1		*TAILLAMP LH	Serviceable	520.40 FL	*- FL
20	1		*REAR LH FENDER	Repair	1,010.40 FL	*- FL
21	1		*SET CAMERA	Not Necessary	550.00 FS	*- FS
22	1		*WINDSCREEN SEALANT	Necessary	24.00 FS	*24.00 FS
23	1		*PRIVATE HIRER DECAL	Necessary	20.00 FS	*20.00 FS
24	1		*REAR BUMPER SENSOR	Not Necessary	300.00 FS	*- FS
25	1		*REAR BUMPER CLIP	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,576.00	1,534.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,727.40	298.08
Total Parts (\$\$)	7,848.60	1,236.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DO UP INTERIOR CLEANING AND CHEMICAL WASH	New	200.00	40.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	0.00
3	TO TRANSFER REAR TAILGATE	New	80.00	0.00
4	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	30.00	20.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	800.00	300.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	0.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	0.00
9	TO SPRAY PAINTING ON THE REPLACED ANG REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	950.00	750.00
Gross Labour Cost (\$\$)			2,345.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >