



新福德車廠私人有限公司

(414)

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

RAY HUNTER

26/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AIG.

Khanchana.

Accident date: 24/10/2019

Estimated repair cost for vehicle no: SLW9986H HONDA FREED 1.5 G A '09

CHASSIS: GB31035230

S/N	Qty	Item	U/price	Amount	
1	1	Rear Boot Lid <i>Distorted</i>		\$1,460.30	1247
2	2	Rear Boot Lid Hinge <i>Free</i>	\$51.40	\$102.80	+
3	2	Rear Boot Lid Shock Absorber <i>Free</i>	\$140.00	\$280.00	+
4	1	Rear Boot Lid Emblem Logo <i>Free</i>		\$27.40	✓
5	1	Rear Boot Lid Freed Logo <i>Free</i>		\$43.10	✓
6	1	Rear Boot Lid Center Moulding <i>Cracked</i>		\$287.30	✓
7	1	Rear Boot Lid Number Plate Lamp <i>Free</i>		\$34.60	+
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$189.50	✓
9	1	Rear Boot Lid Inner Rubber <i>At</i>		\$120.00	✓
10	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$206.80	✓
11	10	Rear Boot Lid Inner Trim Board Clip <i>Free</i>	\$6.50	\$65.00	30
12	1	Rear Boot Lid Wiper Arm <i>At</i>		\$50.00	✓
13	1	Rear Boot Lid Wiper Motor <i>Damaged</i>		\$137.20	✓
14	1	Rear Boot Lid Windscreen <i>Shattered</i>		\$825.90	✓
15	1	Rear Boot Lid Windscreen Moulding <i>Free</i>		\$85.30	✓
16	2	Rear Taillamp <i>Cracked</i>	\$458.10	\$916.20	732
17	4	Rear Taillamp Clip <i>Free</i>	\$8.00	\$32.00	✓
18	2	Rear Taillamp Panel <i>Free</i>	\$210.30	\$420.60	+
19	1	Rear Bumper <i>Deformed</i>		\$490.30	✓
20	10	Rear Bumper Clip <i>Free</i>	\$6.50	\$65.00	30
21	2	Rear Bumper Side Retainer <i>Free</i>	\$16.00	\$32.00	✓
22	2	Rear Bumper Mud Shield <i>Free</i>	\$36.00	\$72.00	+
23	4	Rear Bumper Mud Shield Clip <i>Free</i>	\$6.50	\$26.00	+
24	1	Rear Bumper Towing Cover <i>Free</i>		\$22.50	+
25	1	Rear Fender <i>Free</i>		\$990.00	+
26	1	Rear Fender Air Duct <i>Free</i>		\$28.00	+
27	1	Rear Fender Glass <i>Free</i>		\$297.10	+
28	2	Rear Fender Inner Trim Board <i>Cracked</i>	\$327.00	\$654.00	✓

29	16	Rear Fender Inner Trim Board Clip	<i>new</i>	\$6.50	\$104.00 60.
30	1	Rear End Panel	<i>Dented</i>		\$520.50 ✓
31	1	Rear End Panel Inner	<i>Repis</i>		\$104.00 ✗
32	1	Rear End Panel Outer Garnish	<i>Deformed</i>		\$104.00 ✓
33	1	Rear Spare Tyre Panel	<i>Repis</i>		\$1,155.50 ✗
34	1	Rear Spare Tyre Panel Top Cover	<i>new</i>		\$62.00 ✗
35	1	Rear Exhaust	<i>2</i>		\$628.00 ✗
36	2	Rear Exhaust Mounting	<i>NP</i>	\$27.00	\$54.00 ✗
37	1	Rear Centre Exhaust	<i>new</i>		\$802.00 ✗

5904.30

472344

Subtotal:- \$11,494.90

S/N	Qty	Item / Special Nett	U/price	Amount
38	1	Rear Boot Lid Number Plate	<i>Dented</i>	\$50.00 ✓
39	1	Rear Boot Lid Reverse Camera	<i>Dented</i>	\$550.00 380.
40	1	Rear Boot Lid Video Camera	<i>new</i>	\$680.00 ✗
41	1	Rear Boot Lid Windscreen Solar Film	<i>new</i>	\$450.00 250
42	2	Rear Bumper Side Reflector	<i>new</i>	\$200.00 \$400.00 ✗
43	1	Rear Bumper Reverse Sensor	<i>Dented</i>	\$380.00 200
44	1	Rear Spare Tyre Panel & End Panel Sealant	<i>new</i>	\$450.00 60

940

Subtotal:- \$2,960.00

Labour charges

To remove & refit rear seat cushion, trim board & to provide vehicle interior grooming	\$380.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 50
To remove & refit video camera	\$380.00 50
To remove & refit rear & centre exhaust	\$380.00 X
To remove & refit rear R/H & L/H fender glass	\$200.00 X
Gum	\$100.00 X
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30
Towing fee	\$100.00 X
Tuff kote	\$200.00 60
Panel beating	\$2,400.00 1000
Spray painting	\$2,000.00 1000

Subtotal:- \$6,690.00

Total:- \$21,144.90

total: 8153.44

L/S: 6.5K

06 Days

6.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: