

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5236M**AAD1910-171***Not Authored**Recovery By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

24 OCT 2019

SHD 5236M

JTDKB3FUX03078475

TOYOTA

PRIUS

23.10.19

LONPAC

19/12/2018

PART		LIST	
1	1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80 X
2	1 REAR FENDER RH	\$	854.80 ✓
3	1 REAR FENDER LINER	\$	139.80
4	1 REAR BUMPER	\$	442.60
5	1 REAR BUMPER RE-INFORCEMENT	\$	332.70
6	1 REAR BUMPER TOWING COVER	\$	15.40
7	1 REAR BUMPER UNDER COVER (BLACK)	\$	576.30
8	1 REAR BUMPER SIDE RETAINER RH	\$	117.70
9	1 TAILLAMP LOWER RH	\$	502.00
10	1 TAILLAMP UPPER RH	\$	451.80
11	1 REAR BUMPER SIDE RH	\$	123.70
12	1 REAR TAILGATE	\$	1,147.80
13	1 COVER, FLOOR UNDER, NO.1	\$	175.10
14	1 COVER, FLOOR UNDER, NO.2	\$	241.90
15	1 COVER, REAR FLOOR	\$	229.90
16	1 COVER, DECK TRIM, REAR	\$	126.70
17	1 PANEL SUB-ASSY, REAR DOOR, RH	\$	1,281.70
18	1 LOCK ASSY, REAR DOOR W/MOTOR, RH	\$	561.90
19	1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	293.00
20	1 WEATHERSTRIP, REAR DOOR, RH	\$	180.10
21	1 RUN, REAR DOOR GLASS, RH	\$	122.50
22	1 PLATE ASSY, REAR DOOR LOCK STRIKER	\$	39.30
23	1 HUB & BEARING ASSY, REAR AXLE, RH	\$	NN 725.60 X
24	1 DISC REAR	\$	450.70 X
25	1 CARRIER SUB ASSY, REAR AXLE, RH	\$	953.60 X
26	1 CYLINDER ASSY, DISC BRAKE, REAR RH	\$	1,001.90 X
27	1 PAD KIT, DISC BRAKE, REAR	\$	188.40 X

Trans-cab Auto Services Pte Ltd**AAD1910-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5236M

28	1	COVER, DISC BRAKE DUST, REAR RH	\$	58.20
29	1	BAR, STABILIZER, REAR	\$	295.70
30	1	LINK ASSY, REAR STABILIZER, RH	\$	179.10
31	1	BUSH, STABILIZER, REAR	\$	71.20
32	1	BRACKET, REAR STABILIZER BAR, NO.1	\$	11.50
33	1	BRACKET, REAR SUSPENSION ARM, RH	\$	107.20
34	1	COVER, REAR SUSPENSION ARM, RH	\$	49.70
35	1	ARM ASSY, REAR SUSPENSION, NO.1 RH	\$	239.20
36	1	ARM ASSY, TRAILING, REAR RH	\$	370.40
37	1	ABSORBER ASSY, SHOCK, REAR RH	\$	127.00
38	1	SUPPORT ASSY, REAR SUSPENSION, RH	\$	149.30
39	1	SPRING, COIL, REAR RH	\$	199.00
40	1	INSULATOR, REAR COIL SPRING, LOWER RH	\$	13.90
41	1	INSULATOR, REAR COIL SPRING, UPPER RH	\$	19.80
42	1	ARM ASSY, REAR SUSPENSION, NO.2 RH	\$	497.50
43	1	ARM ASSY, UPPER CONTROL, REAR RH	\$	420.80
44	1	MEMBER SUB ASSY, REAR SUSPENSION	\$	2,245.20
45	1	WIRE, SKID CONTROL SENSOR, RH	\$	94.70
46	1	DUCT ASSY, QUARTER VENT, RH	\$	67.00
47	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	296.20

Per X

TOTAL	\$	17,384.30
25%	\$	4,346.08
	\$	13,038.23

Special Nett

1	1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>6050</i>
2	1	REAR RIGHT WHEEL RIM	\$	NN 1,570.55 <i>7X</i>
3	1	REAR RIGHT WHEEL RIM COVER	\$	<i>na</i> 175.80 ✓
4	1	SET PARKING AID	\$	<i>na</i> 700.00
5	1	SET REAR BUMPER CLIP	\$	<i>na</i> 66.00
6	1	REAR BUMPER PROTECTOR	\$	<i>na</i> 100.00
7	2	REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00
8	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00
9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00
10	1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i> 47.00
11	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i> 52.90

X

Trans-cab Auto Services Pte Ltd**AAD1910-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5236M

12	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	X
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	X
14	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i>	80.00	X
TOTAL			\$		3,285.75	

TOTAL PARTS \$ 16,323.98**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>4401</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>6001</i>
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	<i>1001</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5236M

To dismantle and refit rear undercarriage parts, final checking and testing.	\$	NN 380.00	7X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2cl
To Rust-Proofing Of The Affected Areas.	\$	170.00	3cl
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	nn 380.00	X
To transfer of Rear Door fittings, attachments and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	15,270.00	
Over All Total	\$	31,593.98	

(PART-BY-PART) Repair Days**20 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: