

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018992/UPA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLH3505G **Insured Vehicle No :** SLP1999K

Date of Loss: 23/10/2019 Nature of Claim: TP Claim No: 1630066153SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH3505G	Engine No:	HR12213451B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TBAE12Z0982829
Reg. Date:	31/10/2016 (Man. Year: 2016)	Odometer:	94685 km
Colour:	Red		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	920.00	372.60	547.40	59.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	600.00	250.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	1,770.00	972.60	797.40	45.05
Approved Total (Overridden) (\$)		750.00		
(S\$)	1,770.00	750.00	1,020.00	57.63
+ GST 7.00/7.00% (S\$)	123.90	52.50	71.40	57.63
Nett Amount (S\$)	1,893.90	802.50	1,091.40	57.63
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		990.50		
Global Sum Settlement (S\$)		990.00		

INSPECTION

Date of Assignment: 24/10/2019

Date Inspected: 31/10/2019 Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented / Deformed	600.00 FN	*414.00 FN
2	1		*REVERSE SENSOR WITH CONTROL UNIT	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	980.00	414.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	60.00	41.40
Total Parts (S\$)	920.00	372.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY AFFECTED AREAS	New	450.00	400.00
2	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	400.00	200.00
Gross Labour Cost (\$\$)			850.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >