

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

Mee Far Clara
Lentor Plain
ore 786548

Not Authorised

1/1 Sep @ 580dp

Recovery After Paint

6 days

Date : 29/10/2019

TITY	PARTICULARS	AMOUNT (\$)
	RE: NISSAN SYLPHY / SJN 9809 H	
	Parts (a) 39.00 @ 30%	
	29.30	
	rear boot lock	R 194.30 X
	rear boot lock catch	R 95.90 X
	rear end panel	R 544.20 X
	front bumper reinforcement beam	R 374.50 X
	front bumper side retainer (right) 39.00	Di 767.00
	front door (right)	R 967.40 X
	front anti rollbar linkage	su 129.40 X
	front steering tie rod	su 195.40 X
	front steering tie rod end joint	su 173.60 X
	sub-total	3,441.70
	less 30%	1,032.51
	sub-total (a)	2,409.19
	front fender dust cover clip	net 32.00
	front fender dust cover (right) 99.60	Di 214.30
	front fender signal lamp	scr 146.30
	front fender (right) 727.60	Br 858.40
	front bumper 554.70	cm 765.40
	front bumper fog lamp	mis 316.40
	front bumper fog lamp garnish 128.40	Di 277.60
	front bumper sponge	su 316.50 X
	front bumper lower dust cover	su 322.30 X
	front top grille	su 575.10 X
	front head lamp lower bracket	Di 63.40
	front head lamp assy 722.80	cm 975.90
	front lower arm 252.17	Di 571.20
	front door frame sticker (1)	nr 96.40 X
	front door frame sticker (2)	nr 96.40 X
	front wheel bearing 210.10	nr 293.30
	rear bumper	Br 10d 576.40
	wiper washer tank 204.90	nc 306.30
	radiator side air guide 128.40	cm 249.70
	sub-total	7,053.30

balance brought forward.			7,053.30
	less 10%		705.33
	sub-total (b)		6,347.97
reverse sensor	s.nett	Pr	Sm 220.00 X
tyre	s.nett		800sm 280.00 284.50
alloy rim	s.nett		nd 680.00 ✓
front knuckle arm	s.nett		Pr 495.40 ✓
front shock absorber	s.nett		Pr 431.30 ✓
	sub-total (c)		2,106.70
Sub-total for (a) + (b) + (c)			10,863.86
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	(a) 27.30		1,600.00 600.
To check wiring system.	(b) 3746.85		50.00 20.
To apply rust proofing on affected areas.	S/N 1677.90		120.00 30.
To install reverse sensors and reverse camera.	L/C 1800.00		980.00 50.
To transfer door(s) accessories.	7252.05		80.00 X
To apply putty & spray painting on affected areas.	@ 20%		60.00 800.
To remove and install front undercarriage parts to enable repair.	5801.64		180.00 180.
To replace alloy rim and perform wheel balancing.			40.00 20.
To machine press wheel bearing.			80.00 30.
To perform 4 wheels computerise alignment.			80.00 60.
Towing Charges.			80.00 50.
		Total	14,213.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: