

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-126

DATE : 24-Oct-2019

POLICY NO. : P10008662R02

VEHICLE REG. NO. : SKF5413Y

VEHICLE MAKE : CHEVROLET CRUZE 1.6 (M)

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 980.00	\$ 980.00
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
5	Rear Bumper Tow Eye	1	\$ 30.00	\$ 30.00
6	Rear Boot Cover	1	\$ 1,280.00	\$ 1,280.00
Total Spare Parts				\$ 2,400.00
	<u>SPECIAL NETT</u>			
7	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
	<u>LABOUR</u>			
8	Spray painting Rear Bumper and Rear Boot Cover	1	\$ 500.00	\$ 500.00
9	Remove, Replace and Repair Accident Affected Area	1	\$ 500.00	\$ 500.00
10	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
11	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
12	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,210.00
Amount Before Excess				\$ 3,810.00
Add GST @ 7%				266.70
Total Amount Payable				\$ 4,076.70

Estimate prepared by: **Raymond Tan**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.