

22/03/2002

ASS. REC. BY:

REF: CS/MSG19019044/THP302

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Jowyn Tay Mei Ling of MSG Date/Time: 25/10/2019

Meimen

Estimated Cost: Bill to:

OD / U / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBH 1624C Insured: GBC 4981C

at Workshop m/s Leong Seng Motor Pte Ltd Tel: 6273 7469

of BIK 1006 Bukit Merah Lane 2 #01-08

Policy No: A29097618MKC Claim No: 609508

Sum Insured: Excess:

Make of Veh: D.O.A. 21/10/2019
(Client's Record)

"WP"

30.10.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25/10/2019 @ 05:40pm Person Contacted: Loo Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	WRSP request ask Taufik Survey on 30.10.2019
	PBH 1624C - CS/GA219018648/K22F3 22/10/2019
	GBC 4981C - X

REG. BY: Tanary

REF: MS19

ASSIGNMENT

From: _____ Date: 30.10.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 1624C

at Workshop m/s Leong Seng motor

of Blk 106 Bukit Merah Lane 2 01-08

Insured: _____


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum. _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *mf*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBH/1624C Yr Regn: 2013, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda GLH/25 C.C. 125

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 21798 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LA LJA1146C3267447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 2.75 / R18 R: 3.0 / R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 30/10/190/1420

Survey held at Leong Seng Motor

Des. of Damages: Fft / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/10	Sent Preli by Merimer
13/11	L/S \$3400, 4 days (Red \$1668.00, 32%)

RECEIVED 13 NOV 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 13/11/19 Typist

Rep. Form: _____

Lump Sum: \$3400

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: 150

Transportation: _____

\$ + RS. \$

Photos

Others 11

TOTAL

161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019		25 Oct 2019 16:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MANJYO TRADING PTE LTD, Co. Reg. No.: 201736691N		
Main Claimant:	CERTIS CISCO AUXILLARY POLICE FORCE PTE LTD, Co. Reg. No.: 20090082K		
Vehicle Reg. No.:	FBH1624C	Date of Loss:	21/10/2019 11:00 - :59 [9 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 609508	Policy/Cover Note No.:	A29097618MKC (Comprehensive) Coverage: 20/09/2019 - 19/09/2020
Vehicle Reg. No. (Insured):	GBC4981C	Policy No. (Claimant):	
		Excess:	
Repairster:	Leong Seng Motor Pte Ltd (HQ) BLK 1006 Bukit Merah Lane 2, 2 Alexandra Village #01-08, 159762 Alexandra - Tel: 62737469		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/10/2019]		
Driver/Custodian (Insured):	BALAMURUGAN S/O NARAYASAMY (), NRIC: S7324143Z, Tel: +6590233275 Email:		
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: 6273 7469.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 31 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBC4981C	Accident Date	: 21/10/2019
TP Vehicle No	: FBH1624C	Assignment Date	: 25/10/2019
Make	: HONDA CB125	Est. Duration of Repair	: 4.00
Date of Inspection	: 30/10/2019		
Inspection At	: LEONG SENG MOTOR PTE LTD (HQ) BLK 1006 BUKIT MERAH LANE 2, 2 ALEXANDRA VILLAGE #01-08 SINGAPORE 159762		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,438.00
Revised Amount	:S\$	3,078.00
Check Items (Estimated)	:S\$	1,370.00
Total	:S\$	4,448.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2019 16:06
Date Of Accident	21/10/2019 10:30
Exact Location Of Accident	BEACH ROAD TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH1624C
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILLARY POLICE FORCE PTE LTD
Co Reg No	20090082K 200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-89006080
Alternative Phone No	OFFICE-89006080

Vehicle Particulars

Manufacturer	HONDA
Model	CB125-124CC TTP
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MOMVM000001011-02-000
Cover Note Number	

Driver

Name of Driver	TAN WEE KEONG
Passport No/FIN	G7318140U
Date Of Birth	26/01/1980
Occupation	OUTDOOR
Date Of Driving Pass	16/10/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-89006080
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	20 JALAN AFIFI
Postcode	409179
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC4981C
Vehicle Make/Model/Colour	NISSAN CABSTAR
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	BALAMRUGAN S/O NARAYASAMY
NRIC/Passport Number	S7324143Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available wherever.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) to comply with requirements under any regulations, laws or court orders.



Policyholder
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/10/2014 around 10:33 a.m., I was on duty travelling to Foster rd. At beach road junction, I stop at traffic junction behind a few vehicle, waiting to turn left. When traffic light turn green, we started to move forward. Suddenly vehicle B (GBC 4981C) hit the rear of my vehicle, the impact was very strong and it pushed my vehicle forward and hit the rear of vehicle C (BHC 8080E).

DECLARATION

I/We do hereby declare that the particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH1624C

Model : CB125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Rear fender		\$ 220.00		del ✓
2	Rear no plate holder		\$ 150.00		del ✓
3	Rear no plate lamp		\$ 80.00		cur ✓
4	Brake lamp assy		\$ 250.00		cur ✓
5	Rear signal lamp		\$ 50.00		x
6	Front fender		\$ 165.00		cut ✓
7	Front fork assy ← b1 ✓		\$ 780.00		?
8	Fork under bracket ← b1 ✓		\$ 285.00		?
9	Front wheel axle ← b1 ✓		\$ 125.00		x ?
10	Front signal lamp RH		\$ 50.00		cut ✓
11	Headlamp assy		\$ 280.00		x rm.
12	Brake lever		\$ 30.00		cut ✓
13	Mirror		\$ 75.00		cut ✓
14	Handle bar ← b1 ✓		\$ 180.00		? b1 ✓
15	Handle balancer		\$ 45.00		cut ✓
16	Brake pedal		\$ 95.00		del ✓
17	Front foot rest		\$ 65.00		cut ✓
18	Rear foot rest		\$ 50.00		cut ✓
19	Exhaust protector		\$ 165.00		del ✓
20	Exhaust pipe		\$ 680.00		del ✓
21	Rear no plate			\$ 15.00	b1 ✓
22	Rear box			\$ 180.00	cut ✓
23	Rear box base			\$ 65.00	cur ✓
24	Front crash bar			\$ 350.00	del ✓
25	Rear frame alignment repair			\$ 350.00	100
26	Respray front fender			\$ 120.00	50
27	Towing 2 way			\$ 100.00	80.
28	Labour			\$ 450.00	250.
29					1170
30	Tanpoh 92495244		3490		
31	-wp	10%	3141		
32	20/10/14 @ 220 pm		1170		
33	lump sum		4311		
34		1/55	3400		
35	Respray after repair				
36					
37	4 days				
38					
39	Tanpoh @ 1400000000				

\$ 3,820.00 \$ 1,630.00

Less 10%

\$ 382.00

\$ 3,438.00

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBH1624C

Model : CB125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Rear fender		\$ 220.00		del
2	Rear no plate holder		\$ 150.00		del
3	Rear no plate lamp		\$ 80.00		cut
4	Brake lamp assy		\$ 250.00		cut
5	Rear signal lamp		\$ 50.00		x 1/2
6	Front fender		\$ 165.00		cut
7	Front fork assy		\$ 780.00		? 1/2
8	Fork under bracket		\$ 285.00		? 1/2
9	Front wheel axle		\$ 125.00		x ? 1/2
10	Front signal lamp RH		\$ 50.00		cut
11	Headlamp assy		\$ 280.00		x 1/2
12	Brake lever		\$ 30.00		cut
13	Mirror		\$ 75.00		cut
14	Handle bar		\$ 180.00		? 1/2
15	Handle balancer		\$ 45.00		cut
16	Brake pedal		\$ 95.00		del
17	Front foot rest		\$ 65.00		cut
18	Rear foot rest		\$ 50.00		cut
19	Exhaust protector		\$ 165.00		del
20	Exhaust pipe		\$ 680.00		del
21	Rear no plate			\$ 15.00	del
22	Rear box			\$ 180.00	cut
23	Rear box base			\$ 65.00	cut
24	Front crash bar			\$ 350.00	del
25	Rear frame alignment repair			\$ 350.00	100
26	Respray front fender			\$ 120.00	50
27	Towing 2 way			\$ 100.00	80
28	Labour			\$ 450.00	250
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					

Tanpin 92495744
 -wp
 20/10/14 @ 220 pm
 1000 pm
 Resurvey after repair
 4 days
 Tanpin @ Leong Seng Motor

KKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: \$ 3,820.00 \$ 1,630.00

Less 10%

\$ 382.00
 \$ 3,438.00

9068

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019		25 Oct 2019 16:13 Edit Adj Rpt	S\$3,400.00 Edit Estimates	S\$3,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MANJYO TRADING PTE LTD , Co. Reg. No.: 201736691N								
Main Claimant:	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD , Co. Reg. No.: 20090082K								
Vehicle Reg. No.:	FBH1624C	Date of Loss:	21/10/2019 11:00 - :59 [78 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 609508	Policy/Cover Note No.:	A29097618MKC (Comprehensive) Coverage: 20/09/2019 - 19/09/2020						
Vehicle Reg. No. (Insured):	GBC4981C	Policy No. (Claimant):							
		Excess:							
Repairer:	Leong Seng Motor Pte Ltd (HQ) BLK 1006 Bukit Merah Lane 2, 2 Alexandra Village #01-08, 159762 Alexandra - Tel: 62737469								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/11/2019]								
Driver/Custodian (Insured):	BALAMURUGAN S/O NARAYASAMY (), NRIC: S7324143Z, Tel: +6590233275 Email:								
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: 6273 7469.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBH1624C (609508)

[GBC4981C]

TP

CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD

Oct 21 2019 11:00AM

[MANJYO TRADING PTE LTD]

Leong Seng Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	31/10/19 18:47	Adjuster Immediate Advice								Load HTM	
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	14/11/19 12:47	General View								Load JPG	☒
2	14/11/19 12:47	General View								Load JPG	☒
3	14/11/19 12:47	General View								Load JPG	☒
4	14/11/19 12:47	General View								Load JPG	☒
5	14/11/19 12:47	General View								Load JPG	☒
6	14/11/19 12:47	General View								Load JPG	☒
7	14/11/19 12:47	General View								Load JPG	☒
8	14/11/19 12:47	General View								Load JPG	☒
9	14/11/19 12:47	General View								Load JPG	☒
10	14/11/19 12:47	General View								Load JPG	☒
11	14/11/19 12:47	General View								Load JPG	☒
12	14/11/19 12:47	General View								Load JPG	☒
13	14/11/19 12:47	General View								Load JPG	☒
14	14/11/19 12:47	General View								Load JPG	☒
15	14/11/19 12:47	General View								Load JPG	☒
16	14/11/19 12:47	General View								Load JPG	☒
17	14/11/19 12:47	General View								Load JPG	☒
18	14/11/19 12:47	General View								Load JPG	☒
19	14/11/19 12:47	General View								Load JPG	☒
20	14/11/19 12:47	General View								Load JPG	☒
21	14/11/19 12:47	General View								Load JPG	☒
22	14/11/19 12:47	General View								Load JPG	☒
23	14/11/19 12:47	General View								Load JPG	☒
24	14/11/19 12:47	General View								Load JPG	☒
25	14/11/19 12:47	General View								Load JPG	☒
26	14/11/19 12:47	General View								Load JPG	☒
27	14/11/19 12:47	General View								Load JPG	☒
28	14/11/19 12:47	General View								Load JPG	☒
29	14/11/19 12:47	General View								Load JPG	☒
30	14/11/19 12:47	General View								Load JPG	☒
31	14/11/19 12:47	General View								Load JPG	☒
32	14/11/19 12:47	General View								Load JPG	☒
33	14/11/19 12:47	General View								Load JPG	☒
34	14/11/19 12:47	General View								Load JPG	☒
35	14/11/19 12:47	General View								Load JPG	☒
36	14/11/19 12:47	General View								Load JPG	☒
37	14/11/19 12:47	General View								Load JPG	☒
38	14/11/19 12:47	General View								Load JPG	☒
39	14/11/19 12:47	General View								Load JPG	☒
40	14/11/19 12:47	General View								Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	14/11/19 12:47	General View	 Load JPG	☒
42	14/11/19 12:47	General View	 Load JPG	☒
43	14/11/19 12:47	General View	 Load JPG	☒
44	14/11/19 12:47	General View	 Load JPG	☒
45	14/11/19 12:47	General View	 Load JPG	☒
46	14/11/19 12:47	General View	 Load JPG	☒
47	14/11/19 12:47	General View	 Load JPG	☒
48	14/11/19 12:47	General View	 Load JPG	☒
49	14/11/19 12:47	General View	 Load JPG	☒
50	14/11/19 12:47	General View	 Load JPG	☒
51	14/11/19 12:47	General View	 Load JPG	☒
52	14/11/19 12:47	General View	 Load JPG	☒
53	14/11/19 12:47	General View	 Load JPG	☒
54	14/11/19 12:47	General View	 Load JPG	☒
55	14/11/19 12:47	General View	 Load JPG	☒
56	14/11/19 12:47	General View	 Load JPG	☒
57	14/11/19 12:47	General View	 Load JPG	☒
58	14/11/19 12:47	General View	 Load JPG	☒
59	14/11/19 12:47	General View	 Load JPG	☒
60	14/11/19 12:47	General View	 Load JPG	☒
61	14/11/19 12:47	General View	 Load JPG	☒
62	14/11/19 12:47	General View	 Load JPG	☒
63	14/11/19 12:47	General View	 Load JPG	☒
64	14/11/19 12:47	General View	 Load JPG	☒
65	14/11/19 12:47	General View	 Load JPG	☒
66	14/11/19 12:47	General View	 Load JPG	☒
67	14/11/19 12:47	General View	 Load JPG	☒
68	14/11/19 12:47	General View	 Load JPG	☒
69	14/11/19 12:47	General View	 Load JPG	☒
70	14/11/19 12:47	General View	 Load JPG	☒
71	14/11/19 12:47	General View	 Load JPG	☒
72	14/11/19 12:47	General View	 Load JPG	☒
73	14/11/19 12:47	General View	 Load JPG	☒
74	14/11/19 12:47	General View	 Load JPG	☒
75	14/11/19 12:47	General View	 Load JPG	☒
76	14/11/19 12:47	General View	 Load JPG	☒
77	14/11/19 12:47	General View	 Load JPG	☒
78	14/11/19 12:47	General View	 Load JPG	☒
79	14/11/19 12:47	General View	 Load JPG	☒
80	14/11/19 12:47	General View	 Load JPG	☒
81	14/11/19 12:47	General View	 Load JPG	☒
82	14/11/19 12:47	General View	 Load JPG	☒
83	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
84	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
85	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
86	14/11/19 12:48	Reinspection Photo	Load JPG	☒
87	14/11/19 12:48	Reinspection Photo	Load JPG	☒
88	14/11/19 12:48	Reinspection Photo	Load JPG	☒
89	14/11/19 12:48	Reinspection Photo	Load JPG	☒
90	14/11/19 12:48	Reinspection Photo	Load JPG	☒
91	14/11/19 12:48	Reinspection Photo	Load JPG	☒
92	14/11/19 12:48	Reinspection Photo	Load JPG	☒
93	14/11/19 12:48	Reinspection Photo	Load JPG	☒
94	14/11/19 12:48	Reinspection Photo	Load JPG	☒
95	14/11/19 12:48	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
97	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
98	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
99	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
100	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
101	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
102	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
103	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
104	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
105	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
106	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
107	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
108	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
109	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
110	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
111	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
112	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
113	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
114	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
115	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
116	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
117	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
118	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
119	14/11/19 12:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/10/19 14:41	PRI	 Load PDF	
2	25/10/19 14:41	TP GIA	 Load PDF	
3	25/10/19 15:05	Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19019044/T1YF3E2

Date: 14/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29097618MKC
Claimant
Vehicle No : FBH1624C **Insured Vehicle No :** GBC4981C
Date of Loss: 21/10/2019 **Nature of Claim:** TP **Claim No:** 609508

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH1624C**
 Make & Model: HONDA CB125, 124cc TTP Engine No: JA11E2006936
 Reg. Date: 28/03/2013 (Man. Year: 2012) Chassis No: LALJA11U6C3267447
 Colour: White Odometer: 21798 km
 Engine Capacity: 125 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75 R18 Rear Tyre Size: 3.0 R18
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,048.00	3,751.00	297.00	7.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	560.00	460.00	45.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,068.00	4,311.00	757.00	14.94
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	5,068.00	3,400.00	1,668.00	32.91

INSPECTION

Date of Assignment: 25/10/2019
 Date Inspected: 30/10/2019 Inspected At: Leong Seng Motor Pte Ltd (HQ)
 BLK 1006 Bukit Merah Lane 2, 2
 Alexandra Village #01-08
 Singapore 159762
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Nov 2019)	
Parts:	N/A	HONDA CB125 124cc TTP (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH1624C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Deformed	220.00 FL	*220.00 FL
2	1		*REAR NO PLATE HOLDER	Deformed	150.00 FL	*150.00 FL
3	1		*REAR NO PLATE LAMP	Cracked	80.00 FL	*80.00 FL
4	1		*BRAKE LAMP ASSY	Cracked	250.00 FL	*250.00 FL
5	1		*REAR SIGNAL LAMP	Not Necessary	50.00 FL	*- FL
6	1		*FRONT FENDER	Cut	165.00 FL	*165.00 FL
7	1		*FRONT FORK ASSY	Bent	780.00 FL	*780.00 FL
8	1		*FORK UNDER BRACKET	Bent	285.00 FL	*285.00 FL
9	1		*FRONT WHEEL AXLE	Bent	125.00 FL	*125.00 FL
10	1		*FRONT SIGNAL LAMP RH	Cut	50.00 FL	*50.00 FL
11	1		*HEADLAMP ASSY	Not Necessary	280.00 FL	*- FL
12	1		*BRAKE LEVER	Cut	30.00 FL	*30.00 FL
13	1		*MIRROR	Cut	75.00 FL	*75.00 FL
14	1		*HANDLE BAR	Bent	180.00 FL	*180.00 FL
15	1		*HANDLE BALANCER	Cut	45.00 FL	*45.00 FL
16	1		*BRAKE PEDAL	Dented	95.00 FL	*95.00 FL
17	1		*FRONT FOOT REST	Cut	65.00 FL	*65.00 FL
18	1		*REAR FOOT REST	Cut	50.00 FL	*50.00 FL
19	1		*EXHAUST PROTECTOR	Dented	165.00 FL	*165.00 FL
20	1		*EXHAUST PIPE	Dented	680.00 FL	*680.00 FL
21	1		*REAR NO PLATE	Bent	15.00 FS	*15.00 FS
22	1		*REAR BOX	Cut	180.00 FS	*180.00 FS
23	1		*REAR BOX BASE	Cracked	65.00 FS	*65.00 FS
24	1		*FRONT CRASH BAR	Dented	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,430.00	4,100.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	382.00	349.00
Total Parts (\$\$)	4,048.00	3,751.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REAR FRAME ALIGNMENT REPAIR	New	350.00	180.00
2	RESPRAY FRONT FENDER	New	120.00	50.00
3	TOWING 2 WAY	New	100.00	80.00
4	LABOUR	New	450.00	250.00
Gross Labour Cost (\$\$)			1,020.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >