

勝企業

Win Auto Enterprise

Blk 1033 Eunos Ave 5A #01-31

Singapore 409703

HP No: +65 9745 8981

Fax No: +65 6842 5778

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TP Somp
Shirley

Acknowledged by Repairer

Signature:

Date:

Estimated Quotation Vehicle No: GBD6265T (Nissan NV350 Van)

Quantity	Items	Amount SGD\$ (Nett)
1 Pc	Rear Boot Lid <i>Dented</i>	\$1,816.70
2Pcs	Rear Boot Lid Shock Absorber <i>new</i>	\$295.91
2Pcs	Rear Boot Lid Hing <i>new</i>	\$154.20
1 Pc	Rear Boot Lid Lock <i>new</i>	\$287.10
2 Pcs	Rear Boot Lid Rubber <i>new</i>	\$134.30
1 Pc	Rear Boot Lid Side Lock, Right Side <i>new</i>	\$87.80
1 Pc	Rear Tail Lamp <i>new</i>	\$258.80
1 Pc	Rear Bumper <i>Dented</i>	\$669.20
1 Pc	Rear Bumper Side Lock, Right Side <i>new</i>	\$58.00
1 Set	Reverse Sensor <i>new</i>	\$280.00 <i>200 (SN)</i>
4Pcs	Rear Bumper Clips <i>new</i>	\$24.00
3Pcs	Rear Bumper Right Side Clips <i>new</i>	\$57.00 <i>20</i>
1 Set	NV350 and URN Logo	\$130.00
1Pcs	Nissan Centre Logo	\$87.90
1 Pc	8 Pax Sticker <i>new</i>	\$15.00
1 Pc	70Km/h Sticker	\$15.00
1 Pc	Rear Windscreen Inner Seal	\$87.00
1 Pc	Rear Windscreen Glue	\$68.00
1 Pc	Rear Lamp Panel <i>new</i>	\$480.00
	Total Amount	\$5,005.91

3289.40
2960.46
SN: 20

1P2 REAR TAIL PANEL Lock \$68.00 N x

Labour Charges	Amount SGD\$
Remove and Fix Rear Windscreen	\$180.00 <i>120</i>
Spray Painting Undercoating	\$280.00 <i>80</i>
To Spray Painting	\$1,400.00 <i>800</i>
Knocking & Welding	\$1,500.00 <i>800</i>
Checking of Wiring	\$80.00 <i>30</i>
Total Amount	8,513.91 \$3,440.00

1830

*total: 4890.46
1/s: 4K*

*1/s 29/10/19
06 Rep. Admin
H/S*