

Cecilia

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53222**
Date Estimated : **25/10/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Ng Chee Wan
31 Jalan Pari Dedap

Singapore 488622

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6141P	WBA2D920105E9142	03/11/2017	216i G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper including to remove and install body parts in order to carry out painting job.	850.00	0	850.00 ✓
To respray rear bumper.	934.00	0	934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (CHROM)	110.55	1.00	0	110.55 ✓
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1.00	0	1,045.45 ✓

Total Labour :	2,014.00
Total Parts :	1,156.00
Total Labour & Parts :	3,170.00
GST @7%:	221.90
Grand Total :	3,391.90

LOSS OF USE = \$60 X 3 DAYS

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601
64796624

LK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
is subject to final approval from Insurance



Acknowledged by Repairer

Signature:
(After Motorrad)
Date:

GST REG. NO : M2 - 0020081 - X

26 OCT 2019

E S T I M A T E

Estimate No. : b1 53222
Date Estimated : 25/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ng Chee Wan
31 Jalan Pari Dedap

Singapore 488622

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6141P	WBA2D920105E91423	03/11/2017	216i G TOURER	0

DESCRIPTION

Replacing rear bumper

VALUE

850 1,275.00

Spray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries

80.00

Total Labour 1: 2,570.00

DESCRIPTION

RR BUMPER LH SIDE GUIDE

? X NAI

QTY**PRIC****VALUE**

REAR BUMPER CARRIER

? X NAI

1

61.35

61.35

RR BUMPER LH INNER SIDE GUIDE

? X NAI

1

458.10

458.10

REAR BUMPER TRIM STRIP (CHROM)

? X NAI

1

67.55

67.55

REAR BUMPER PANEL PRIMED (LINES PDC)

✓ CUT

1

110.55

110.55

DECOUPING RING PDC TORQUE CONVERTER

00 X 44 NAI

1

1,045.45

1,045.45

4

5.05

20.20

Total Parts : 1,763.20



Steve (LKK)

8322 8813

w/ Prejudice 18/11/19, 11.00am

PIP

Rery Def spray

3 days

Labour 1	:	2,570.00
Parts	:	1,763.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	303.32
Grand Total	:	4,636.52

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **