

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

26 OCT 2019

E S T I M A T E

Estimate No. : b1 53222
Date Estimated : 25/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ng Chee Wan
31 Jalan Pari Dedap

Singapore 488622

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6141P	WBA2D920105E91423	03/11/2017	216i G TOURER	0

DESCRIPTION

Replacing rear bumper

VALUE

1,275.00

Spray rear bumper

1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

177.00

Sundries

80.00

Total Labour 1: **2,570.00**DESCRIPTION

RR BUMPER LH SIDE GUIDE

QTY

1

PRIC

61.35

VALUE

61.35

REAR BUMPER CARRIER

1

458.10

458.10

RR BUMPER LH INNER SIDE GUIDE

1

67.55

67.55

REAR BUMPER TRIM STRIP (CHROM)

1

110.55

110.55

REAR BUMPER PANEL PRIMED (LINES PDC

1

1,045.45

1,045.45

DECOUPING RING PDC TORQUE CONVERTER

4

5.05

20.20

Total Parts : **1,763.20**

Labour 1 : 2,570.00

Parts : 1,763.20

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 303.32

Grand Total : **4,636.52**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **