

Mphacilia

Exclusive Enterprise Pte Ltd

8 Kaki Bukit Ave 4 , #03-50 , Premier @ KB , Singapore 415875

Tel : 62459655 / 8653 6483 (Xiang) Fax : 6245 9678

Email : exclusiveenterprise50@gmail.com

Not Authorized
Make

1/s # 1400

3 day.

the after repair

3/10/19

TP INS : AXA

Veh No. : GT 421E

Veh Model : Toyota Liteace

No. List items

- 1 Front Bonnet
- 2 Front Bumper
- 3 Front Bumper Side Retainer L/R @ \$122.10
- 4 Front Bumper Beam
- 5 Front Grille
- 6 Front Logo
- 7 Headlamp RH
- 8 Headlamp Rim RH
- 9 Side Lamp RH
- 10 Front Fender RH
- 11 Front Fender Inner Cowling RH
- 12 Support Panel
- 13 Brace Panel

QTY

Amount

1	11	\$ 509.80	X
1	De	\$ 571.30	/
2	o/s but	\$ 244.20	pc
1	11	\$ 98.00	X
1	11	\$ 195.80	X
1	11	\$ 36.40	X
1	eye	\$ 107.80	/
1	cm	\$ 101.60	/
1	cm	\$ 141.00	/
1	but/sec	\$ 361.20	/
1	11	\$ 139.20	X
1	11	\$ 702.00	X
1	11	\$ 55.00	X

Sub-Total : \$3263.30

Less 25% 502

Total : \$2447.47

S/N

Front Bumper Clips

Front Fender Inner Cowling Clips

1Set	mu	\$ 50.00	40
1Set	11	\$ 50.00	X

S/N Total : \$100

Labour

Wire Check

Labour

Painting

\$ 50.00	20
\$ 800.00	300
\$ 800.00	300

Labour Total : \$1650

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1405

50%

7-702.50

S.N-40.00

L-620.00

1445.

4497.47