

15/5/2016

INS. CASE OWNER:

Kitty

CC

4 new

AXA1901

9064

H. goss

LKK:

IDAC:

Surveyor:

H. Ann

DOI:

ASSIGNMENT

24/10/19

Date / Time:

24/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGS 32895

Name of Insured:

TAN YI ZHUANG

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

24/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S9mo x4w1 / 14 4137

Policy No.:

GA 487563

Make / Model:

MITSUBISHI

Place of Accident:

MTE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGS 32895

SMA 9879X

S9w6777Z

S9m 69955



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

500n

SAN

4P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SMA 9879X - X

SGS 32895 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

19/12

Send LOI.

27/12

LOD in to self mandate.

31/12

Pending mandate approval.

10/1/2020

File pass to MK to close.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

13,000.00

(13 days)

Reduction:

13,194.97

% 50

Email

Call

FINAL SETTLEMENT

Date/Time:

8/1/2020

Confirm with:

VINCENT

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost:

S\$

13,000.00

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

1140.00

(\$ 60 x 19 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

7.50

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

14,144.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

14,144.50

Name 1:

Suan San Motor Trading

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

7500

COPY SENT
10/1/2020

REF:

ASM CAXA

ASS. REC. BY:

H-ANIV

ASSIGNMENT

hv Extinct

From:

Date:

29.10.2019

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To Inspect Vehicle No:

SMA 9859X

at Workshop m/s

Soon San Motor

of Bk 3006 vbi road 1 #01-390

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Cecilia case

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

13 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 9859X

Yr Regn:

21/04/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

119 CARENS

c.c

1685

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

153874

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

1/NAHU 815 VH.7173752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50/R17

R:

225/50/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Frt and Rear 7 (Yoko)

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/10/19

D.O.I.

24/10/19

Survey held at

Soon San motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMA 9859X

L/S \$13,000/- (Red - \$13,194.97/50%) do limit

hv Extinct

mv - 76000

* workshop require wan do

PV - 54488

p/p repair

PV - 21500

limit repair \$17500
let workshop know

* in charge person - Vincent

90047468

* 13 repair days + 2 PRS 6 days / sat + 3 sun = 21 days.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S. + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Rep. Form:

Lump Sum / B.B. / C.

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

1pce air con condenser	? photo	Dented	\$ 805.00	page 2	740.00	✓
1pce radiator	? photo	Dented	773.00		700.00	✓
1pce radiator cowl	X SVC		120.00			
1pce radiator motor	X SVC		302.00			
2pcs radiator side covers	@\$27 X SVC		54.00			
1pce tail gate	✓ BT		1,088.00		1088.00	✓
1pce tail gate top lock	✓ Jm		109.00		109.00	✓
1pce tail gate lower lock catch	X SVC		35.00			
1pce tail gate trim cover	X SVC		230.00			
1pce tail gate cc plate	Yule carry logo ✓ ncc		25.00		25.00	✓
1pce tail gate emblem	✓ ncc		76.00		40.00	✓
1pce tail gate CRDi plate	✓ ncc		39.00		30.00	✓
1pce tail gate carnes plate	✓ ncc		46.00		30.00	✓
1pce tail gate rubber	SVC X		131.00			
2pcs tail gate dampers	@\$90 SVC X		180.00			
1pce tail gate tape form windscreen	✓ ncc		45.00		45.00	✓
1pce tail gate windscreen sealant	✓ ncc		140.00	30	30.00	✓
1pce tail gate top moulding chrome	X SVC		124.00			
1pce tail gate plate assessor	X SVC		30.00			
1pce tail gate sticker	✓ ncc		20.00		20.00	✓
2pcs tail gate reflectors	@\$770 L/H only? R/H X SVC		1,540.00	-photo L/H could do	600.00	✓
2pcs tail lamps	@\$773 L/H only only? R/H SVC		1,546.00	-photo L/H could do	357.00	✓
1pce rear bumper	✓ CRA		576.00		576.00	✓
4pcs rear bumper reverse sensors	@\$162 ? photo		648.00	3 pieces done	456.00	✓
1pce rear bumper lower spoiler	✓ CRA		189.00		189.00	✓
2pcs rear bumper side garnish cover	@\$32 ✓ CRA		64.00		64.00	✓
1pce rear left mudflap	L/H only ✓ CRA		78.00		39.00	✓
1pce rear reinforcement	✓ BT		367.00		367.00	✓

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 32855.

29/10/19
H/S repair
reany refer parent
Hoek Ann
853/883
12:45 pm
without pr. Zulree
Hoek Ann @ Hek. Auto.com

	1pce bonnet	✓ BT	\$ 793.00	693.00 ✓
	1pce bonnet lock	lower ✓ Jan	168.00	138.00 ✓
	1pce bonnet insulator	X SVC	327.00	
9ps	12pcs bonnet insulator clips@ \$6	✓ nec	72.00	32.00 ✓
	1pce bonnet top lock	✓ BT	47.00	47.00 ✓
	1pce bonnet top lock catch	✓ CRA	44.00	44.00 ✓
1ps	2pcs bonnet hinges@ \$38	R/H only ✓ CRA	76.00	30.00 ✓
	2pcs headlamps@ \$1,558	? - photo cracked	3,116.00 ✓	2800 ✓
	1pce bonnet lower lock cover garnish	✓ CRA	110.00	80.00 ✓
4ps	7pcs bonnet lower cover clips@ \$6	✓ nec	42.00	16.00 ✓
	1pce support panel side garnish	? photo cracked	98.00 ✓	70.00 ✓
	1pce griller	✓ CRA	357.00	300.00 ✓
	1pce griller emblem	✓ nec	76.00	50.00 ✓
	1pce griller outer moulding chrome	✓ CRA	368.00	256.00 ✓
	1pce griller centre garnish	lower ✓ CRA	121.00	100.00 ✓
	1pce front bumper	✓ CRA	668.00	668.00 ✓
	2pcs front bumper side holders@ \$24	✓ nec	48.00	40.00 ✓
2ps	4pcs front bumper reverse sensors @ \$162	H only photo	648.00 ?	304.00 ✓
	1pce front bumper lower griller	garnish ✓ CRA	159.00	140.00 ✓
	1pce front bumper lower cover	X SVC	150.00	
	1pce front bumper engine cover	X SVC	142.00	
	2pcs fog lamp cover@ \$130	X SVC	260.00	
	2pcs fog lamps@ \$206	X SVC	412.00	
8ps	10pcs front bumper inner clips@ \$6	✓ nec	60.00	32.00 ✓
	1pce front bumper reinforcement	? photo	389.00	389.00 ✓
	1pce front bumper inner sponge	? photo	68.00	68.00 ✓
	1pce support panel	cracked	575.00 1page	525.00 ✓

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower S,pore 068811

Accident date:24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 32855.

8ps	10pcs rear bumper inner clips@\$6 ✓ acc	\$ 60.00	page 3	32.00 ✓
	2pcs rear bumper side holders@\$42 ✓ acc	84.00		84.00 ✓
	2pcs rear bumper reinforcement brackets@\$85 ? photo Bent	170.00		150.00 ✓
	2pcs rear bumper lamps@\$120 4H-CR4 RH-M15 ✓	240.00		240.00 ✓
	1pce rear bumper lower garnish ✓ CR4	179.00		179.00 ✓
	3pcs rear bumper inner brackets@\$18 ✓ M15	54.00		46.00 ✓
8ps	2pcs rear bumper tow cover@\$12 X SUC	24.00		
	1pce rear spare tyer holder X SUC (R)	221.00		
	1pce rear panel ? photo Bent ✓	453.00		453.00 ✓
	1pce rear panel lower garnish cover X SUC	71.00		
		\$20,330.00		
	Less 5% 10%	1,016.50		
		\$19,313.50		
1ps	2pcs rear & front number plate with cover Part only	200.00	35 ✓ BT	
	1tin coolant water ✓ acc	10.00	8 ✓	
	1tin power steering oil X SUC	20.00		
	To towing ✓	100.00	60 ✓	
	To rustproof front & rear Part and Riv	300.00	30 ✓	
	To dismantle/renew tail gate	140.00	100 ✓	
	To dismantle/renew air con condenser with gas	120.00	70 ✓	
	To dismantle/renew front & rear reverse sensors	200.00	40 ✓	
	To focus headlamp & wiring	100.00	25 ✓	
	To remove/refit camera rear	100.00	20 ✓	
	To remove/refit rear interior to effect repair ✓	100.00	30 ✓	
	To dismantle/renew accident portion	2,500.00	3 1800 ✓	
	To spray paint	2,000.00	1600 ✓	
	1pcs rear exhaust pipe X SUC (R)	680.00		
	Total:	\$25,883.50		

26194.47

Adrian G
Resmy 30/10/19
S/S

13 Days.

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811

Accident date:24/10/19

Date:29/10/19

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 32855.

To supplementary	
1set rear reverse sensor wiring <i>could</i>	\$180.50 ✓
Less 5% 100%	9.25
	\$171.47
To remove/refit rear windscreen	140.00 120 ✓
Total:	\$311.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

parts → 13671.00

parts less → 10%

→ 12303.90

labour → 3938

16241.90

1/5 less 20%

12993.52

Total

4/5 Amt

\$13000 #

\$26,194.97

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Monday, 9 December, 2019 8:57 AM
To: Vincent Woo
Cc: Cecilia Chong (LKK Auto)
Subject: RE: SMA 9859X FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 02.12.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Vincent ,

Good day, o.k will be process base on finalized total amount COR \$ 13.000 L /SUMP REPAIR and DOR 13 days close.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vincent Woo [mailto:soonsanmotor@gmail.com]
Sent: Monday, 9 December, 2019 8:46 AM
To: Hock Ann (LKK Auto)
Subject: Re: SMA 9859X FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 02.12.2019

Agreed thanks

Vincent Woo <soonsanmotor@gmail.com> 于 2019年12月2日周一 下午8:36写道 :

OK thanks

On Mon, 2 Dec 2019, 9:25 AM Hock Ann (LKK Auto), <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear vincent ,

Good day , Kindly attached refer SMA 9859X KIA CARENS finalized updated calculate adjustment on 02.12.2019 .

COR - \$ 13.000

DOR – 13 DAYS

Please refer adjustment updated total L/sump amount \$ 13.000 if agree total L/sump amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

29/10/19
H/S repair
rear side panel
Hock Ann
8531883
12:45 pm
without pin Inducer
Hock Ann @ Hock Auto room
10 day
* working means
you do H/S repair

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

1pce bonnet	✓ B+	\$ 793.00
1pce bonnet lock rear	lower ✓ Jm	168.00
1pce bonnet insulator	X SVC	327.00
8ps 12pcs bonnet insulator clips@ \$6	✓ acc	72.00
1pce bonnet top lock	✓ B+	47.00
1pce bonnet top lock catch	✓ CRA	44.00
1ps 2pcs bonnet hinges@ \$38	R/H only ✓ CRA	76.00
2pcs headlamps@ \$1,558	? photo	3,116.00
1pce bonnet lower lock cover garnish	✓ CRA	110.00
4ps 7pcs bonnet lower cover clips@ \$6	✓ acc	42.00
1pce support panel side garnish	? photo	98.00
1pce griller	✓ CRA	357.00
1pce griller emblem	✓ acc	76.00
1pce griller outer moulding chrome	✓ CRA	368.00
1pce griller centre garnish	lower ✓ CRA	121.00
1pce front bumper	✓ CRA	668.00
2pcs front bumper side holders@ \$24	✓ acc	48.00
2ps 4pcs front bumper reverse sensors @ \$162	H only photo	648.00 ?
1pce front bumper lower griller	garnish ✓ CRA	159.00
1pce front bumper lower cover	X SVC	150.00
1pce front bumper engine cover	X SVC	142.00
2pcs frog lamp cover@ \$130	X SVC	260.00
2pcs frog lamps@ \$206	X SVC	412.00
8ps 10pcs front bumper inner clips@ \$6	✓ acc	60.00
1pce front bumper reinforcement	? photo	389.00
1pce front bumper inner sponge	? photo	68.00
1pce support panel	X SVC (R)	575.00 1page

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

1pce	air con condenser	? photo	\$	805.00	page 2
1pce	radiator	? photo		773.00	
1pce	radiator cowl	X SVC		120.00	
1pce	radiator motor	X SVC		302.00	
2pcs	radiator side covers	@\$27 X SVC		54.00	
1pce	tail gate	✓ BT		1,088.00	
1pce	tail gate top lock	✓ Jm		109.00	
1pce	tail gate lower lock catch	X SVC		35.00	
1pce	tail gate trim cover	X SVC		230.00	
1pce	tail gate cc plate	cycle carry logo ✓ nec		25.00	
1pce	tail gate emblem	✓ nec		76.00	
1pce	tail gate CRDi plate	✓ nec		39.00	
1pce	tail gate carnes plate	✓ nec		46.00	
1pce	tail gate rubber	SVC X		131.00	
2pcs	tail gate dampers	@\$90 SVC X		180.00	
1pce	tail gate tape form windscreen	✓ nec		45.00	
1pce	tail gate windscreen sealant	✓ nec		140.00	30
1pce	tail gate top moulding chrome	X SVC		124.00	
1pce	tail gate plate assessor	X SVC		30.00	
1pce	tail gate sticker	✓ nec		20.00	
(ps) 2pcs	tail gate reflectors	@\$770 L/H only? R/H X SVC		1,540.00	photo
(ps) 2pcs	tail lamps	@\$773 L/H only only? R/H X SVC		1,546.00	photo
1pce	rear bumper	✓ CR4		576.00	
3ps 4pcs	rear bumper reverse sensors	@\$162 ? photo		648.00	
1pce	rear bumper lower spoiler	✓ CR4		189.00	
2pcs	rear bumper side garnish cover	@\$32 ✓ CR4		64.00	
(ps) 1pce	rear left mudflap	L/H only ✓ CR4		78.00	
1pce	rear reinforcement	✓ Ref		367.00	

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower S,pore 068811

Accident date:24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

LKK Auto Consultants hence

the Repairer of the following

- To resurvey before repair sprays and
- To display damaged car(s) in
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from insurer's company

Acknowledged by Repairer

Signature:

Date:

8ps 10pcs rear bumper inner clips@\$6 ✓ me	\$ 60.00	page 3
2pcs rear bumper side holders@\$42 ✓ me	84.00	
2pcs rear bumper reinforcement brackets@\$85 ? photo	170.00	
2pcs rear bumper lamps@\$120 4H-CRA RH-mis ✓	240.00	
1pce rear bumper lower garnish ✓ CRA	179.00	
3pcs rear bumper inner brackets@\$18 ✓ mis	54.00	
8ps 2pcs rear bumper tow cover@\$12 X SUC	24.00	
1pce rear spare tyer holder X SUC (R)	221.00	
1pce rear panel ? -photo	453.00	
1pce rear panel lower garnish cover X SUC	71.00	
	\$20,330.00	
Less 5% 10%	1,016.50	
	\$19,313.50	
1ps 2pcs rear & front number plate with cover front only	200.00	35
1tin coolant water ✓ me	10.00	8
1tin power steering oil X SUC	20.00	
To towing X	100.00	
To rustproof front & rear fit and Riv	300.00	30
To dismantle/renew tail gate + Riv windscreen removal	140.00	100
To dismantle/renew air con condenser with gas	120.00	70 photo
To dismantle/renew front & rear reverse sensors	200.00	40
To focus headlamp & wiring	100.00	25
To remove/refit camera rear	100.00	20
To remove/refit rear interior to effect repair ✓	100.00	30
To dismantle/renew accident portion 6.5	2,500.00	1300
To spray paint 7ps	2,000.00	1260
1pcs rear exhaust pipe X SUC (R)	680.00	
Total:	\$25,883.50	3 All rustproof front and back

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	349E
Vehicle Details	
Vehicle No.:	SMA9859X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	D4FDGH119121
Chassis No.:	KNAHU815VH7173752
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$22,737.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$18,832.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$14,124.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$40,364.00
Total Rebate Amount:	\$54,488.00

— 9416

The information contained herein is correct as at 30 Oct 2019

OK

Bakun 7 yr 6 months

Repin 9000 yr

$$9000 + 12 = 750 \text{ months}$$

$$63000 + 4500 + 9416$$

$$= 76916$$

$$MV - 76000$$

$$PV - 54488$$

$$VV - 21500$$

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



Give it your best SHOT

Need more energy for work? 5-hour ENERGY® is the power boost you need.

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Superior Condition 2013 MC Stradale.



Very Low Usage, Fully Maint By Agent, Bidded Number 168
Going With Car!
Direct Owner StarAd



PRIME MOTOR

(CHENG YONG CREDIT ENTERPRISES PTE LTD)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category ▼

Sort by Date Posted ▼

4 vehicles

Kia Carens

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	Kia Carens		Any	Any	2017	Any	Any	Any
	Kia Carens	Diesel 1.7A EX	\$87,800	\$9,830 /yr	30-Oct-2017	1,685 cc	42,000 km	MPV
Fuel Type: Diesel (Euro 5 Engine and Above) One Owner And Very Well Maintained. Fully Agent Serviced With Warranty Till October 2023. Excellent Driving Dynamics, Cabin Space And Fuel Economy Of 19.2Km/L. Bank And In House Loan Available. Trade In Welcomed. Contact Our Sales Team For Viewing.								
Posted: 26-Oct-2019 Tags: 2017 Kia Carens, 2017 kia carens, Kia Carens, kia carens, Kia, Carens, carens, Used Kia								
	Kia Carens	Diesel 1.7A EX	\$83,888	\$9,870 /yr	19-Jul-2017	1,685 cc	106,000 km	MPV
Fuel Type: Diesel (Euro 5 Engine and Above) One Of The Most Sought After Vehicle In The Market! Well Known For Its Fuel Efficient, 1 Owner And Well Maintained. Excellent Condition, Accident Free, Trade In Are Welcome, Powerful Engine And Smooth Transmission. Call Us Today To Book Appointment Befor...								
Global Carz Pte Ltd								
Posted: 17-Oct-2019 Tags: 2017 Kia Carens, 2017 kia carens, Kia Carens, kia carens, Kia, Carens, carens, Used Kia								
	Kia Carens	Diesel 1.7A SX	\$87,500	\$9,640 /yr	22-Dec-2017	1,685 cc	81,700 km	MPV
Fuel Type: Diesel (Euro 5 Engine and Above) High Loans With Lowest Interest Rates From 2.28%. Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.								
Posted: 15-Oct-2019 Tags: 2017 Kia Carens, 2017 kia carens, Kia Carens, kia carens, Kia, Carens, carens, Used Kia								
	Kia Carens	Diesel 1.7A EX	\$89,000	\$10,720 /yr	25-May-2017	1,685 cc	52,000 km	MPV
Fuel Type: Diesel (Euro 5 Engine and Above) Agent Unit! Beautiful Diesel Korean MPV For Sale! 2888 Number Plate Included! Accident And Damage Free. Servicing Records Available From C&C. Fuel Efficient And Economical. 10 Years Engine Warranty, 5 Years Warranty And 05 Years Servicing. Consignment Unit. Trad...								
Prem Roy Motoring								
Posted: 23-Sep-2019 Tags: 2017 Kia Carens, 2017 kia carens, Kia Carens, kia carens, Kia, Carens, carens, Used Kia								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type

For old advertisements, view Expired ads

Compare

1e New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: S8038349E
 Owner ID Type: Singapore NRIC
 Owner Name: HENG KOK HUI
 Registered Address: APT BLK 55 TEBAN GARDENS ROAD #29-453 SINGAPORE 600055
 Mailing Address: -
 Birth Date: 15 Nov 1980

Vehicle Particulars

Vehicle No.: SMA9859X
 Previous Vehicle No.: -
 Effective Date of Ownership: 17 Aug 2018
 Original Regn Date: 21 Apr 2017
 Registration Date: 21 Apr 2017
 Year of Manufacture: 2017
 Vehicle Type: Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: KIA
 Vehicle Model: CARENS 1.7 DCT DIESEL 5DR FWD
 Primary Colour: White
 Secondary Colour: -
 Passenger Capacity: 6
 Chassis No.: KNAHU815VH7173752
 Engine No.: D4FDGH119121
 Engine Capacity / Power Rating: 1685 cc / -
 Maximum Power Output: 104.0 kW (139 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1525 kg
 Maximum Laden Weight: 2270 kg
 Open Market Value: \$22,737.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 20 Apr 2027
 Minimum PARF Benefit: \$9,416.00
 No. of Transfers: 1
 IU Label No.: 1127514700
 COE No.: 2017040103002375E
 COE Expiry Date: 20 Apr 2027
 COE Category: B - Car above 1600cc or 97kW (130bhp)
 COE Registration Category: B - Car above 1600cc or 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: \$54,000.00 / -
 Actual QP Paid: \$54,000.00
 QP (Regn Cat): \$54,000.00
 OPC Cash Rebate Eligibility: No
 QP during COE Bidding Exercise: \$54,000.00
 Additional Registration Fee Rate: First \$20,000.00 (100%), next \$2,737.00 (140%)
 Actual ARF Paid: \$18,832.00
 Vehicle Lifespan Expiry Date: No Lifespan
 CO2 Emission: 135.00 (g/km)
 CEV/VES Rebate Utilised Amount: \$5,000.00
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 Message: To renew the COE, the Prevailing Quota Premium payable is that of Category B. This is a public service vehicle.

OK

Save as PDF

SOON SAN MOTOR TRADING

Block 3006, Ubi Road 1, #01-390, Singapore 407800
Tel : 68414555 Fax : 67473546 408700

DISCHARGE VOUCHER

My / Our Kia Carens - 1.7 (A)

Claim No. S9M024WIMC / KT Vehicle No. SMA 9859X

I / We Heng Kok Hui

NRIC No. S 8038349 E of BIK55, #29-453

Teban Gardens Road, S' 600055

hereby declares that I have received my / our motor vehicle No.

SMA 9859X from the above company in satisfactory condition

after repairs and have no further claims what-so-ever for the repairs

done which have been involved in an accident on 24/10/2019

The repairs were done to my satisfaction and what ever money due

Please pay to the repairers

Thank You.

Signature.....

Date : 18 / 11 / 2019

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Service Request Details

Claim

S9M024WI

Reference

None 

Loss Date

October 24, 2019

Report Date

Oct 25, 2019 4:31:53 PM

Request Date

October 25, 2019

Due Date

November 4, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Vincent

T: 9.13a.m

v. 1h

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMA9859X

Model

CARENS-1.7 (A)

Service Address

...

Primary Contact/Insured

TAN YI ZHUANG (ZAC)

472A FERNVALE STREET, #20-39, 791472, Singapore

YVONNE.ONGLX@GMAIL.COM

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

non-reported

5

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

DHIWAR Namrata

From: soonсанmotor@yahoo.com.sg
Sent: Friday, October 25, 2019 3:19 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Your Insurer vehicle No: SGS 3285 S

Categories: Namrata

Soon San Motor Trading
Blk 3006, Ubi Road 1, #01-390,
Singapore 408700
Tel : 68414445
Fax: 67473546

25th October 2019

AXA Insurance Singapore Pte Ltd
8, Shenton Way, #27-01,
AXA Tower, Singapore 068811

Dear Sir/Mdm,
Accident involving SMA 9859 X, SGS 3285 S, SMB 8885 U, SMM 6995 S, SGW 6777 Z and SLN 9412 U
along AYE Towards MCE on 24/10/2019

We hereby give you two days notice for your surveyor to contact and inspection on the motor vehicle No:
SMA 9859 X at the above address contact person (Thomas H /P : 97330686) direct settlement.

Your faithfully,

Sent from Android device



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27/12/2019

Survey Details:

Date of loss	24-Oct-19
Date of appointment	29-Oct-19
Date of survey	29-Oct-19
Location of survey	SOON SAN MOTOR TRADING

Vehicle Details:

Claim Type:	Third party
Vehicle number	SMA 9859X
Make and Model	KIA CARENS 1.7
Date of registration	21/4/2017
Excess	
Market Value	\$76,000
Parf Rebate	\$54,488
Nett Loss	\$21,512

Repair details:

Initial Estimate	\$ 26,194.97
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 16,121.90
Check items (estimate)	\$ -
Labour	\$ 120.00
Total	\$ 16,241.90
Lump Sum(if applicable)	\$ 13,000.00
Number of days for repair	13



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

13 REPAIR DAYS + 2 PRS + 3 SAT + 3 SUN = 21 DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	13,000.00
Loss of use	\$	1,260.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	7.50
Others	\$	-
Proposed Total	\$	14,267.50



<MANDATE IA> - S9M024WI {ACCIDENT INVOLVING SGS 3285S & SMA 9859X ON 24/10/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S28 (OI LAST 2 VEH) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE.
AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$14,267.50 (CLAIMING LOU). MANDATE IA
HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION.
THANKS - CCL 27/12/2019

Reply

9/11/2019

Vehicle Registration Detail Information

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No. :

S8038349E

Owner ID Type :

Singapore NRIC

Owner Name :

HENG KOK HUI

Registered Address :

APT BLK 55 TEBAN GARDENS ROAD #29-453 SINGAPORE 600055

Mailing Address :

-

Birth Date :

15 Nov 1990

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

BY HAND

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER

S,pore 068811

Accident date: 24/10/2019

Date:05/12/2019

Atten; Cecilia

Accident involving vehicle no: SMA 9859X & SGS 3285S along AYE Towards MCE.

We understand that you are the insurer of SGS 3285S vehicle.

I/We wish to inform you my/our vehicle SMA 9859X have been completed repairs to my/our

Satisfaction by M/S SOON SAN MOTOR TRADING we therefore propose to claims from your as follows:-

Cost of repair	\$13,000.00
Grab driver 1days \$200 x 21days	4,200.00
LTA search	7.50

Total: \$17,207.50

Please let us your reply soonest possible

Thank you

Your faithfully

SOON SAN MOTOR TRADING

Signature

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER

S,pore 068811

Accident date: 24/10/2019

Date:05/12/2019

Final bill cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

To contract lump sum repair recommend by your surveyor and ourselves for Total: \$13,000.00 nett

(Sin/Dollars: Thirteen Thousand Only)

SOON SAN MOTOR
TRADING
Signature

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19019064/Hga3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: KITTY TEO			Date : 16-01-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGS 3285S	Veh. Inspected	SMA 9859X	
Policy No.	GA489563	Coverage (\$)	0.00	
Claim No.	S9M024WI	Excess (\$)	0.00	
Assign From	KITTY TEO	Assign Date	29/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAHU815VH7173752	Colour	WHITE	
Odometer	153874	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	YOKOHAMA	5 mm	
L/H Front Tyre	225/50 R17	YOKOHAMA	5 mm	
R/H Rear Tyre	225/50 R17	YOKOHAMA	5 mm	
L/H Rear Tyre	225/50 R17	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2019	Inspection Date	29/10/2019	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REINFORCEMENT (CONSISTENT)	BENT	367.00	367.00
1	BONNET (CONSISTENT)	BENT	793.00	693.00
1	BONNET LOCK LOWER (CONSISTENT)	JAMMED	168.00	138.00
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	327.00	-
12	BONNET INSULATOR CLIPS @ \$6.00 (CONSISTENT)	NECESSARY	72.00	32.00
1	BONNET TOP LOCK (CONSISTENT)	BENT	47.00	47.00
1	BONNET TOP LOCK CATCH (CONSISTENT)	CRUSHED	44.00	44.00
2	BONNET HINGES @ \$38.00 (CONSISTENT)	O/S CRUSHED	76.00	30.00
2	HEADLAMPS @ \$1558.00 (CONSISTENT)	CRACKED	3,116.00	2,800.00
1	BONNET LOWER LOCK COVER GARNISH (CONSISTENT)	CRACKED	110.00	80.00
7	BONNET LOWER COVER CLIPS @ \$6.00 (CONSISTENT)	NECESSARY 4PCS ONLY	42.00	16.00
1	SUPPORT PANEL SIDE GARNISH (CONSISTENT)	DEFORMED	98.00	70.00
1	GRILLER (CONSISTENT)	CRACKED	357.00	300.00
1	GRILLER EMBLEM (CONSISTENT)	NECESSARY	76.00	50.00
1	GRILLER OUTER MOULDING CHROME (CONSISTENT)	CRACKED	368.00	256.00
1	GRILLER LOWER GARNISH (CONSISTENT)	CRACKED	121.00	100.00
1	FRONT BUMPER (CONSISTENT)	CRUSHED	668.00	668.00
2	FRONT BUMPER SIDE HOLDERS @ \$24.00 (CONSISTENT)	NECESSARY	48.00	40.00
4	FRONT BUMPER REVERSE SENSORS @ \$162.00 (CONSISTENT)	N/S DAMAGED 2PCS ONLY	648.00	304.00
1	FRONT BUMPER LOWER GARNISH (CONSISTENT)	CRUSHED	159.00	140.00
1	FRONT BUMPER LOWER COVER (CONSISTENT)	SERVICEABLE	150.00	-
1	FRONT BUMPER ENGINE COVER (CONSISTENT)	SERVICEABLE	142.00	-
2	FOG LAMP COVER @ \$130.00 (CONSISTENT)	SERVICEABLE	260.00	-
2	FOG LAMPS @ \$206.00 (CONSISTENT)	SERVICEABLE	412.00	-
10	FRONT BUMPER INNER CLIPS @ \$6.00 (CONSISTENT)	NECESSARY 8PCS ONLY	60.00	32.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	389.00	389.00
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	CRACKED	68.00	68.00
1	SUPPORT PANEL (CONSISTENT)	BENT	575.00	525.00
10	REAR BUMPER INNER CLIPS @ \$6.00 (CONSISTENT)	NECESSARY 8PCS ONLY	60.00	32.00
2	REAR BUMPER SIDE HOLDERS @ \$42.00 (CONSISTENT)	NECESSARY	84.00	84.00

Report Ref No. CC4/ASM19019064/Hga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER REINFORCEMENT BRACKETS @ \$85.00 (CONSISTENT)	BENT	170.00	150.00
2	REAR BUMPER LAMPS @ \$120.00 (CONSISTENT)	N/S CRACKED / O/S MISSING	240.00	240.00
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	CRACKED	179.00	179.00
3	REAR BUMPER INNER BRACKETS @ \$18.00 (CONSISTENT)	MISSING	54.00	46.00
2	REAR BUMPER TOW COVER @ \$12.00 (CONSISTENT)	SERVICEABLE	24.00	-
1	REAR SPARE TYRE HOLDER (CONSISTENT)	TO REPAIR SEE LABOUR	221.00	-
1	REAR PANEL (CONSISTENT)	DENTED	453.00	453.00
1	REAR PANEL LOWER GARNISH COVER (CONSISTENT)	SERVICEABLE	71.00	-
1	SET REAR REVERSE SENSOR WIRING (CONSISTENT) (ADDITIONAL)	CRACKED	180.50	160.00
	LESS 5% DISCOUNT		-1,025.53	-
	LESS 10% DISCOUNT		-	-1,367.10
			19,484.97	12,303.90
	<u>SPECIAL NETT ITEMS</u>			
2	REAR & FRONT NUMBER PLATE WITH COVER (SN) (CONSISTENT)	FRONT BENT	200.00	35.00
1	TIN COOLANT WATER (SN) (CONSISTENT)	NECESSARY	10.00	8.00
1	TIN POWER STEERING OIL (SN) (CONSISTENT)	SERVICEABLE	20.00	-
1	REAR EXHAUST PIPE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	680.00	-
			910.00	43.00
	<u>LABOUR</u>			
	TO TOWING.		100.00	60.00
	TO RUSTPROOF FRONT & REAR.		300.00	30.00
	TO DISMANTLE / RENEW TAIL GATE.		140.00	100.00
	TO DISMANTLE / RENEW AIR CON CONDENSER WITH GAS.		120.00	70.00
	TO DISMANTLE / RENEW FRONT & REAR REVERSE SENSORS.		200.00	40.00
	TO FOCUS HEADLAMP & WIRING.		100.00	25.00
	TO REMOVE / REFIT CAMERA REAR.		100.00	20.00

Report Ref No. CC4/ASM19019064/Hga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIT REAR INTERIOR TO EFFECT REPAIR.		100.00	30.00
	TO DISMANTLE / RENEW ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE HOLDER AND REAR EXHAUST PIPE.		2,500.00	1,800.00
	TO SPRAY PAINT.		2,000.00	1,600.00
	TO REMOVE / REFIT REAR WINDSCREEN. (ADDITIONAL)		140.00	120.00
			5,800.00	3,895.00
GRAND TOTAL			26,194.97	16,241.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CC4/ASM19019064/Hga3s2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.