

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 3285S.

29/10/19
H/S repair
rear
Hoch Ann
853/1883
12.45 pm
without pre-approval
Hoch Ann @ H/Auto.com
10 day
* workshop manual
van to H/S repair

	1pce bonnet	✓ BT	\$ 793.00
	1pce bonnet lock	rear lower ✓ Jm	168.00
	1pce bonnet insulator	X SVC	327.00
8ps	12pcs bonnet insulator clips@ \$6	✓ nec	72.00
	1pce bonnet top lock	✓ BT	47.00
	1pce bonnet top lock catch	✓ CR4	44.00
1ps	2pcs bonnet hinges@ \$38	R/H only ✓ CR4	76.00
	2pcs headlamps@ \$1,558	? -photo	3,116.00
	1pce bonnet lower lock cover garnish	✓ CR4	110.00
4ps	7pcs bonnet lower cover clips@ \$6	✓ nec	42.00
	1pce support panel side garnish	? photo	98.00
	1pce griller	✓ CR4	357.00
	1pce griller emblem	✓ nec	76.00
	1pce griller outer moulding chrome	✓ CR4	368.00
	1pce griller centre garnish	lower ✓ CR4	121.00
	1pce front bumper	✓ CR4	668.00
	2pcs front bumper side holders@ \$24	✓ nec	48.00
2ps	4pcs front bumper reverse sensors @ \$162	L/H only photo	648.00 ?
	1pce front bumper lower griller	garnish ✓ CR4	159.00
	1pce front bumper lower cover	X SVC	150.00
	1pce front bumper engine cover	X SVC	142.00
	2pcs frog lamp cover@ \$130	X SVC	260.00
	2pcs frog lamps@ \$206	X SVC	412.00
8ps	10pcs front bumper inner clips@ \$6	✓ nec	60.00
	1pce front bumper reinforcement	? photo	389.00
	1pce front bumper inner sponge	? photo	68.00
	1pce support panel	X SVC (R)	575.00 1page

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811.

Accident date: 24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 32855.

1pce air con condenser ? photo	\$ 805.00	page 2
1pce radiator ? photo	773.00	
1pce radiator cowling X SVC	120.00	
1pce radiator motor X SVC	302.00	
2pcs radiator side covers@\$27 X SVC	54.00	
1pce tail gate ✓ BT	1,088.00	
1pce tail gate top lock ✓ Jm	109.00	
1pce tail gate lower lock catch X SVC	35.00	
1pce tail gate trim cover X SVC	230.00	
1pce tail gate cc plate vyle carry logs ✓ nec	25.00	
1pce tail gate emblem ✓ nec	76.00	
1pce tail gate CRDi plate ✓ nec	39.00	
1pce tail gate carnes plate ✓ nec	46.00	
1pce tail gate rubber SVC X	131.00	
2pcs tail gate dampers@\$90 SVC X	180.00	
1pce tail gate tape form windscreen ✓ nec	45.00	
1pce tail gate windscreen sealant ✓ nec	140.00	30
1pce tail gate top moulding chrome X SVC	124.00	
1pce tail gate plate assessor X SVC	30.00	
1pce tail gate sticker ✓ nec	20.00	
(ps) 2pcs tail gate reflectors@\$770 L/H only? R/H X SVC	1,540.00	-photo
(ps) 2pcs tail lamps@\$773 L/H only only? R/H SVC	1,546.00	-photo
1pce rear bumper ✓ CRA	576.00	
3ps 4pcs rear bumper reverse sensors@\$162 ? photo	648.00	
1pce rear bumper lower spoiler ✓ CRA	189.00	
2pcs rear bumper side garnish cover@\$32 ✓ CRA	64.00	
(ps) 1pce rear left mudflap L/H only ✓ CRA	78.00	
1pce rear reinforcement ✓ B-f	367.00	

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower S,pore 068811

Accident date:24/10/2019

Date:25/10/2019

Estimate cost to repair vel: SMA 9859X (Kia Carens) claims under vel: SGS 32855

- LKK Auto Consultants** hence **the Repairer** of the following:
- To resurvey before/after spray and
 - To display damaged part(s) duly
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be taken and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

8ps	10pcs rear bumper inner clips@\$6 ✓ me	\$ 60.00	page 3
	2pcs rear bumper side holders@\$42 ✓ me	84.00	
	2pcs rear bumper reinforcement brackets@\$85 ? photo	170.00	
	2pcs rear bumper lamps@\$120 LH-CR4 RH-M15 ✓	240.00	
	1pce rear bumper lower garnish ✓ CR4	179.00	
	3pcs rear bumper inner brackets@\$18 ✓ M15	54.00	
4ps	2pcs rear bumper tow cover@\$12 X SVC	24.00	
	1pce rear spare tyer holder X SVC (R)	221.00	
	1pce rear panel ? -photo	453.00	
	1pce rear panel lower garnish cover X SVC	71.00	
		\$20,330.00	
	Less 5% 10%	1,016.50	
		\$19,313.50	
1ps	2pcs rear & front number plate with cover fit only	200.00	35
	1tin coolant water ✓ me	10.00	8
	1tin power steering oil X SVC	20.00	
	To towing X	100.00	
	To rustproof front & rear fit and Rev	300.00	30
	To dismantle/renew tail gate + Rust windscreen remove	140.00	100
	To dismantle/renew air con condenser with gas	120.00	70 B photo.
	To dismantle/renew front & rear reverse sensors	200.00	40
	To focus headlamp & wiring	100.00	25
	To remove/refit camera rear	100.00	20
	To remove/refit rear interior to effect repair ✓	100.00	30
	To dismantle/renew accident portion 6.5	2,500.00	1300
	To spray paint 7ps	2,000.00	1260
	1pcs rear exhaust pipe X SVC (R)	680.00	
	Total:	\$25,883.50	

3 All inclusive front and back to be