




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19019065/Eps3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Date : 10-12-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 452T	Veh. Inspected	GBJ 6467X	
Policy No.	GA470144/1	Coverage (\$)	0.00	
Claim No.	S9M024TO	Excess (\$)	0.00	
Assign From		Assign Date	29/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35Y80K213334	Colour	WHITE	
Odometer	10333	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/75 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/75 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/10/2019	Inspection Date	29/10/2019	
Survey held at	SYSTEMATIC AIRCONDITIONING PTE LTD 29 SENOKO WAY SINGAPORE 758059			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		