

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

	OD	3RD PARTY	DATE	REMARKS
FAX TO FAX NO		Rasul LKK	26/11/19	3
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				
PLEASE SIGNATURE BY _____				

Total Labour :	3,916.00
Total Parts :	2,949.50
Total Labour & Parts :	6,865.50
GST @7%:	480.59
Grand Total :	7,346.09

CAR RENTAL - \$385.20 (3 days)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53206**
Date Estimated : **25/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Gautam Anand
188 Depot Road The Interlace
#16-17

Singapore 109688

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJF4818G	WBAWY92070LE001	28/11/2014	X3 sDrive20	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	938.00	0	938.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00
# To make good tail end panel and knock out dented area caused by the accident.	850.00	0	850.00
# To respray tail end panel	668.00	0	668.00
# To remove and install rear boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# CLAMP	1.60	3	0	4.80
RR BUMPER CARRIER ECE	797.80	1	0	797.80
COVER MIDDLE BOTTOM	167.55	1	0	167.55
REAR BUMPER CLADDING (PDC/SCHWARZ)	211.45	1	0	211.45
REAR BUMPER PANEL PRIMED (XLINE/PDC)	1,510.10	1	0	1,510.10
UNDERRIDE GUARD PRIMED REAR (X LINE)	249.40	1	0	249.40
# EXPANDING RIVET BLACK	1.40	6	0	8.40

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53206**
Date Estimated : **25/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Gautam Anand
188 Depot RoadThe Interlace
#16-17

Singapore 109688

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJF4818G	WBAWY92070LE001	28/11/2014	X3 sDrive20	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
# To make good tail end panel and knock out dented area caused by the accident.	850.00	0	850.00
# To respray tail end panel	668.00	0	668.00
# To remove and install rear boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# CLAMP	1.60	3	0	4.80
# EXPANDING RIVET BLACK	1.40	6	0	8.40

SUPPLEMENTARY ITEMS

Total Labour :	1,748.00
Total Parts :	13.20
Total Labour & Parts :	1,761.20