

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53206**
Date Estimated : **25/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Gautam Anand
188 Depot Road The Interlace
#16-17

Singapore 109688

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJF4818G	WBAWY92070LE001	28/11/2014	X3 sDrive20	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

# To make good tail end panel and knock out dented area caused by the accident.	850.00	0	850.00 ✓
# To respray tail end panel	668.00	0	668.00 ✓
# To remove and install rear boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# CLAMP <i>me</i>	1.60	3	0	4.80
# EXPANDING RIVET BLACK <i>me</i>	1.40	6	0	8.40

SUPPLEMENTARY ITEMS

Total Labour :	1,748.00
Total Parts :	13.20
Total Labour & Parts :	1,761.20