

China-Ju CP(P)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6623H

DATE : 25.10.2019

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (RH) ?			\$ 138.10
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Side Bracket (RH) ?			\$ 33.10
	Rear Bumper Cover Clips ✓			\$ 22.00
	Rear Bumper Side Under(RH) ?			\$ 27.50
	Rear Bumper Reflector Lamp (RH) ✓			\$ 31.90
	SUB TOTAL			\$ 1,458.05
	LESS 20%			\$ 291.61
	DISCOUNTED TOTAL			\$ 1,166.44
	Labour Charge			
	Panel Beating			\$ 350.00 ³²⁰
	Spray Painting Charge	200		\$ 250.00
	Wiring Charge			\$ 50.00 ^X
	Remove/Refix Reverse Sensor	30		\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 1,936.44
<p><i>Kalir 11/11/19</i></p> <p><i>25/10/19 1230L</i></p> <p><i>2 Days</i></p> <p><i>PIP</i></p> <p><i>Before Paint photo</i></p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Part prices are subject to confirmation • Third party survey on a "Without Prejudice" basis • No illegal modification is allowed • Supplier's liability must be ascertained and is subject to final approval from the Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				