

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 17031

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1283/2019/NS
Date : 25-Oct-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Li Mingyue
Address : 18B Cranberra Drive
#10-47
Singapore 768100
Telephone : HP +65 81385685
Type of Claim : Own Damage Claims
Policy No. : 1900115876
Vehicle No : **SMM 6219 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-19
Engine No : CHZ C27277
Chassis No : WAUZZZ8V1K1024352
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Oct-19
Place of Accident : Whampoa Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMM 6219 A

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated</u>	
			<u>Charges</u>	
1	To remove and reinstall rhs front suspension assy. Inspect subframe for damages and renew if necessary.	S/N \$	2,400.00	✓
2	To renew rhs rim and carry out wheel alignment.	S/N \$	280.00	✓
3	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES			: \$ 2,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 6219 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	TRACK CONTROL ARM - RH ?	\$ 336.00	?
2	STABILIZER BAR <i>Not in</i>	\$ 372.00	X
3	WHEEL BEARING HOUSING - RH ?	\$ 532.00	?
4	WHEEL HOUSING - FRONT ?	\$ 442.00	?
5	GUIDE JOINT - RH ?	\$ 117.00	?
6	COUPLING ROD ?	\$ 88.00	?
7	DRIVE SHAFT - RH <i>Not in</i>	\$ 2,208.00	X
8	GAS SHOCK ABSORBER ?	\$ 251.00	?
9	STRUT STORAGE SUSPENSION ?	\$ 114.00	?
10	UPPER STRUT BEARING ?	\$ 43.00	?
11	TRACK ROD ?	\$ 86.00	?
12	TIE ROD END - RH <i>Not in</i>	\$ 118.00	X
13	ALUMINIUM ASSEMBLY CARRIER <i>Not in</i>	\$ 940.00	X
14	BONDED RUBBER BUSHES SET <i>Not in</i>	\$ 91.00	X
15	FRONT ALUMINIUM RIM - RH <i>Not in</i>	\$ 666.00	X
16	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,704.00	
TOTAL LABOUR CHARGES		\$ 2,872.00	
GRAND TOTAL		\$ 9,576.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim,
Surveyed Date : 29/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant