

21/10/2019

ASS. REC. BY:

REF:

CS/CT119019124/KT8352

Special Instruction:

Surveyor: Amush

ASSIGNMENT (Office)

From (Person): Tan Kah Leongof CT1Date/Time: 30/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA61PInsured: CB7H1E

given.

at Workshop in/s Hc AutoTel: 94570678 Joe / 64570678of 160 Sin Ming Drive #05-09Policy No: DMB4SN15285319044Claim No: SNM19D205085C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30/10Person Contacted: JoeVehicle IN / OUT

Date/Time

Action/Instruction

Johny (✓)SMA61P-XCB7H1E-X23/11/19 8 Had email13/12/20 Re-finalised LS \$7900 & confirmed. (led: 9794-30, 55%)

ASS. FILE BY:

REF:

CTI

ASSIGNMENT

From:

Date: 30/10

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 61 P

at Workshop m/s HC Auto

of 160 Sin Ming Drive #05-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 882k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMA 61 P

Yr Regn:

04 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru

XV

Wagon

c.c

1995

Colour:

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

30206

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF1G77KLSJG 029915

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/10/19

D.O.I.

30/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

RECEIVED 17 FEB 2020

Date/Time, File Pass to?



Prel. Report

14/2 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / LBR (%)

Tp

79001

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 30 October 2019 9:22 AM
To: Elaine Toh; assignments
Subject: RE: OUR REF: SNM19D205085-CB7411E- TKL- PRE-REPAIR SURVEY --- YOUR REF: CB 7411 E --- ACCIDENT INVOLVING SMA 61 P AND CB 7411 E ON 29 OCTOBER 2019 ALONG ECP NEAR TO TRAFFIC PARK AT ABOUT 0815 HOURS

WITHOUT PREJUDICE

Dear Elaine,

We refer to your email dated 30.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]
Sent: Wednesday, October 30, 2019 8:21 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205085-CB7411E- TKL- PRE-REPAIR SURVEY --- YOUR REF: CB 7411 E --- ACCIDENT INVOLVING SMA 61 P AND CB 7411 E ON 29 OCTOBER 2019 ALONG ECP NEAR TO TRAFFIC PARK AT ABOUT 0815 HOURS
Importance: High

Veli lu- Kenneth

Our Ref: SMA 61 P (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of 29 October 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **KENNETH KONG** as the Single Joint Expert for this matter.

Venue: H C Auto Pte Ltd
160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722
Contact: Mr. Joe @ 9457-0678 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,
Elaine Toh (Secretary)
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.

Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SMA 61 P – By fax: 64578287 only

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

Sent: Tuesday, 29 October, 2019 4:48 PM

To: Elaine Toh

Subject: RE: OUR REF: SNM19D205085-CB7411E- TKL- PRE-REPAIR SURVEY --- YOUR REF: CB 7411 E --- ACCIDENT INVOLVING SMA 61 P AND CB 7411 E ON 29 OCTOBER 2019 ALONG ECP NEAR TO TRAFFIC PARK AT ABOUT 0815 HOURS

Without Prejudice

Dear Elaine,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, October 29, 2019 4:27 PM

To: Elaine Toh <Elainetoh@visionlawllc.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D205085-CB7411E- TKL- PRE-REPAIR SURVEY --- YOUR REF: CB 7411 E --- ACCIDENT INVOLVING SMA 61 P AND CB 7411 E ON 29 OCTOBER 2019 ALONG ECP NEAR TO TRAFFIC PARK AT ABOUT 0815 HOURS

Dear Kah Leong,

Please conduct PRS for SMA61P.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Tuesday, October 29, 2019 12:03 PM

To: Claims Dept of CTI

Cc: Chong Boon Sen; Ong Chin Kiat; Chee So Chow; Elaine Cheong; Alfred Toh; Tan Kah Leong; Irene Tay; Angie Foo

Subject: PRE-REPAIR SURVEY --- YOUR REF: CB 7411 E --- ACCIDENT INVOLVING SMA 61 P AND CB 7411 E ON 29 OCTOBER 2019 ALONG ECP NEAR TO TRAFFIC PARK AT ABOUT 0815 HOURS

Importance: High

Our Ref: SMA 61 P (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **EYU SIEW HWA** to notify you of a road traffic accident on 29 October 2019 at about 0815 hours along ECP near to Traffic Park involving our client's motor vehicle registration number SMA 61 P and motor vehicle registration number CB 7411 E driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh (Secretary)
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SMA 61 P – By fax: 64578287 only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------|
| Date Of Report | 30/10/2019 11:56 |
| Date Of Accident | 29/10/2019 08:15 |
| Exact Location Of Accident | ECP NEAR TO TRAFFIC PARK |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMA61P |
| Insured/Policyholder | |
| Name Of Registered Owner | EYU SIEW HWA |
| NRIC No | S1486292G |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97224893 |
| Alternative Phone No | OTHERS-97224893 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | SUBARU |
| Model | XV 2.0 |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 1800041126-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | EYU SIEW HWA |
| NRIC No | S1486292G |
| Date Of Birth | 23/07/1961 |
| Occupation | INDOOR |
| Date Of Driving Pass | 23/10/1978 |
| Driving Experience | 41 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97224893 |
| Fax Number | |
| Contact Number | OTHERS-97224893 |
| Email Address | NOEMAIL |

| | |
|---|------------------------------|
| Address | BLK 28 SIMEI STREET 1 #11-09 |
| Postcode | 529948 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|-------------|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| POLICE STATION NAME [OTHER] | THOMSON NPP |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN / POLICE REPORT NO: T/20191029/2056

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------|
| Vehicle Registration Number | CB7411E |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | BUS |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|---|------------------------------|
| Name | EYU SIEW HWA |
| Approximate Age | 58 |
| Injuries Sustain | |
| Injured person in which vehicle? | SMA61P |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | BLK 28 SIMEI STREET 1 #11-09 |
| Postcode | 529948 |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

30 OCT 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

30 OCT 2019


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attached police report no: T20191029/2056.

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 30 OCT 2019

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 30 OCT 2019

[Signature]
 Reporting Centre Personnel's Signature
 Name: Jenny Lim
 NRIC/FIN No.: 2



**SINGAPORE
POLICE FORCE**



T/20191029/2056

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 3

Report No. T/20191029/2056

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|------------------|--------------------------|
| Date/Time Report Made: 29/10/2019 12:43 | Vide Report No.: | Station Diary No.: 22 |
|--|------------------|--------------------------|

Informant's Particulars

| | | | | | |
|--|--|--|---|--|--|
| Name of Informant: EYU SIEW HWA | | | Address: BLK 28 SIMEI STREET 1 #11-09 SINGAPORE 529948 | | |
| ID Type / ID No.: NRIC NO / S1486292G | | | Contact No.: Home/Office: | | |

General Information of the Accident

| | | | | |
|--|------------------|------------------------------------|--|-------------------------------------|
| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 29/10/2019 08:15 | Type of Location: Straight Road |
| Location: Along Road 1 EAST COAST EXPRESSWAY Near to Traffic Park | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | | Traffic Volume: Heavy |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|-------------------|--------|----------------------------|-------|-------------------|-----------------|
| CB7411E | Bus/Coach/Minibus | | | | Slightly Damaged | 0 |
| SMA61P | Car | SUBARU | XV 2.0I-S EYESIGHT AWD CVT | Blue | Seriously Damaged | 0 |

Details of Vehicle Insurance

| Vehicle No. | Insurance Company | Insurance No. | Effective | Expiry Date |
|-------------|--------------------------------------|---------------|------------|-------------|
| SMA61P | AIG ASIA PACIFIC INSURANCE PTE. LTD. | 1800041126-01 | 17/04/2019 | 16/04/2020 |



**SINGAPORE
POLICE FORCE**



T/20191029/2056

2 of 3

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20191029/2056

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|-----------------------------|--|-----------------------------------|
| Details of Person Involved | | | |
| Any Pedestrian Involved: No | | | |
| No. of Pedestrians Injured: NIL | | Use of Pedestrian Crossing: NA | |
| Driver | | | |
| Name | Unknown Driver | ID No. | NIL |
| Related Vehicle | CB7411E (Bus/Coach/Minibus) | Contact No. | NIL |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Driver | | | |
| Name | EYU SIEW HWA | ID No. | S1486292G |
| Related Vehicle | SMA61P (Car) | Contact No. | 97224893 |
| Hospital/Clinic | TWIN CITY MEDICAL CENTRE | Class of Driving Licence & Expiry Date | Class: 3 Date of Expiry: NIL |
| Date Treatment | 29/10/2019 | Date Discharge | NIL |
| No. of Days granted Medical Leave | 03 | Degree of Injury | Slight |

Brief Details.

On 29/10/2019 at about 0815hrs, I was driving my vehicle (SMA61P) along second left lane of ECP near to traffic park.

Suddenly, a front vehicle cut into my lane abruptly from 3rd left lane towards my lane. As such, I did a sudden brake to slow down. Subsequently, I felt an impact on the rear of my vehicle. I then made a check and discovered that a bus (CB7411E) collided onto the rear of my vehicle. Both of us then took pictures and left the area. I do not have in-car CCTV in my vehicle.

On the same date, I felt pain on my neck, lower back and legs as such, I went to see the doctor. I was then given a 3 days MC. I am lodging this report for insurance and medical claims.



**SINGAPORE
POLICE FORCE**



T/20191029/2056

3 of 3

Report No. T/20191029/2056

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

| | |
|---|--------------------------------|
| Signature Of Officer Recording The Report: E / Sgt 3 PANG XIU KANG | Signature Of Informant: |
| Signature Of Interpreter: Not applicable | Date/Time: 29/10/2019 12:43 |
| Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151 | Classification Of Case: |
| Authentication Stamp NP168 | SN 070 |
| SIGNATURE | |

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 29 / 10 / 2019

ESTIMATE COSTS OF REPAIR

Mr Eyu Siew Hwa

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*NOT WORKING
Repairing Bumper*

Dear Sir / Madam ,

Vehicle no. : SMA 61 P - Subaru XV 2.0

Accident date : 29 / 10 / 2019

| Quantity | Descriptions | Amount (S\$) |
|----------|--|----------------|
| 1 | 1 pc rear windscreen glass <i>Shattered</i> | |
| 2 | 1 pc rear windscreen glass molding <i>new ?</i> | |
| 3 | 1 pc boot lid <i>By</i> | |
| 4 | 1 pc boot lid inner lock <i>RX</i> | |
| 5 | 2 pcs boot lid side garnish 1 @ <i>Sub X</i> | |
| 6 | 1 pc boot lid 'Subaru' logo <i>new</i> | |
| 7 | 1 pc boot lid 'Subaru' emblem <i>new</i> | |
| 8 | 1 pc boot lid 'XV' emblem <i>new</i> | |
| 9 | 1 pc boot lid 'AWD' emblem <i>new</i> | |
| 10 | 1 pc boot lid 'EYE SIGHT' emblem <i>new</i> | |
| 11 | 1 pc boot lid inner trim <i>new</i> | |
| 12 | 2 pcs boot lid absorber 1 @ <i>Sub X</i> | |
| 13 | 1 pc boot lid wiper arm <i>Sub X</i> | |
| 14 | 1 pc boot lid wiper motor <i>?</i> | |
| 15 | 1 pc boot lid wiper blade <i>Sub X</i> | |
| 16 | 2 pcs boot lid lamp 1 @ <i>new car</i> | |
| 17 | 2 pcs boot lid hinge 1 @ <i>RX</i> | |
| 18 | 1 pc rear weather strip <i>?</i> | |
| 19 | 2 pcs tail lamp 1 @ <i>new car</i> | |
| 20 | 2 pcs tail lamp panel 1 @ <i>?</i> | |
| 21 | 2 pcs tail lamp lower bracket 1 @ <i>new car</i> | |
| 22 | 2 pcs tail lamp lower clip 1 @ <i>new car</i> | |
| 23 | 1 pc rear bumper fascia <i>new</i> | |
| 24 | 1 pc rear bumper reinforcement <i>By</i> | |
| | Balance C/FD | |

S -

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMA 61 P)

\$ -

| | | | |
|----|-------|------------------------------------|----------------|
| 25 | 1 pc | rear bumper center step garnish | Sur - |
| 26 | 1 pc | rear bumper beam | ? |
| 27 | 2 pcs | rear bumper bracket | 1 @ ? |
| 28 | 2 pcs | rear bumper reflector | 1 @ Sur x |
| 29 | 2 pcs | rear bumper side retainer | 1 @ N/S D17 Lt |
| 30 | 2 pcs | rear bumper lower cover | 1 @ might ? |
| 31 | 1 pc | rear bumper tow cover | Sur - |
| 32 | 1 pc | n/s rear fender | ? |
| 33 | 2 pcs | rear fender inner garnish | 1 @ Sur - |
| 34 | 1 pc | n/s rear fender wheel arch garnish | Sur x |
| 35 | 2 pcs | rear no plate lamp | 1 @ ? |
| 36 | 1 pc | wiper motor | ? |
| 37 | 1 pc | rear end panel | ? |
| 38 | 1 pc | rear end panel inner garnish | ? |
| 39 | 1 pc | rear spare tyre board | Sur x |
| 40 | 1 pc | rear spare tyre panel | R x |

Less 20 %

\$ -
\$ -
\$ -

| | | | | |
|----|-------|---------------------|---------|----|
| 41 | 1 pc | rear camera | Sur - ✓ | sn |
| 42 | 1 pc | rear no. plate | Sur x | sn |
| 43 | 1 set | rear reverse sensor | Sur - | sn |
| 44 | 1 pc | rear end panel seal | ? | sn |

\$ -

| | | |
|--|----|----------|
| Labour charges | \$ | 2,000.00 |
| To putty and spray painting | \$ | 1,800.00 |
| Re-seal anti rust | \$ | 200.00 |
| To check wiring | \$ | 120.00 |
| Remove and refix rear windscreen glass | \$ | 160.00 |
| Remove and refix rear reverse sensor | \$ | 120.00 |
| Remove and refix cushion seat , garnish , carpet , etc | \$ | 180.00 |
| | \$ | 4,580.00 |
| Plus : 7% GST | \$ | 320.60 |
| Grand total | \$ | 4,900.60 |

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

*Not Authored
C/Sm & 7900.
Penny After Rain*

Date : 29 / 10 / 2019

ESTIMATE COSTS OF REPAIR

Mr Eyu Siew Hwa

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

9 days

Dear Sir / Madam ,

Vehicle no. : SMA 61 P - Subaru XV 2.0

Accident date : 29 / 10 / 2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

| Quantity | Descriptions | Amount (S\$) |
|----------|--|----------------|
| 1 | 1 pc rear windscreen glass | 1,095.40 |
| 2 | 1 pc rear windscreen glass molding | \$ 165.00 |
| 3 | 1 pc boot lid <i>1102.</i> | \$ 1,276.40 |
| 4 | 1 pc boot lid inner lock | \$ 276.40 |
| 5 | 2 pcs boot lid side garnish 1 @ 72.50 | \$ 145.00 |
| 6 | 1 pc boot lid 'Subaru' logo | \$ 68.40 |
| 7 | 1 pc boot lid 'Subaru' emblem | \$ 85.80 |
| 8 | 1 pc boot lid 'XV' emblem | \$ 32.90 |
| 9 | 1 pc boot lid 'AWD' emblem | \$ 85.42 |
| 10 | 1 pc boot lid 'EYE SIGHT' emblem | \$ 96.80 |
| 11 | 1 pc boot lid inner trim | \$ 393.30 |
| 12 | 2 pcs boot lid absorber 1 @ 180.80 | \$ 361.60 |
| 13 | 1 pc boot lid wiper arm | \$ 79.80 |
| 14 | 1 pc boot lid wiper motor | \$ 404.00 |
| 15 | 1 pc boot lid wiper blade | \$ 26.00 |
| 16 | 2 pcs boot lid lamp 1 @ 308.80 <i>NLS cm</i> | \$ 617.60 |
| 17 | 2 pcs boot lid hinge 1 @ 44.00 | \$ 88.00 |
| 18 | 1 pc rear weather strip | \$ 116.00 |
| 19 | 2 pcs tail lamp 1 @ 582.40 <i>512.</i> | \$ 1,164.80 |
| 20 | 2 pcs tail lamp panel 1 @ 150.10 | \$ 300.20 |
| 21 | 2 pcs tail lamp lower bracket 1 @ 10.50 | \$ 21.00 |
| 22 | 2 pcs tail lamp lower clip 1 @ 3.50 | \$ 7.00 |
| 23 | 1 pc rear bumper fascia <i>601.50</i> | \$ 894.00 |
| 24 | 1 pc rear bumper reinforcement <i>223.</i> | \$ 380.00 |
| | Balance C/FD | \$ 8,180.82 |

Acknowledged by Repairer

Signature:

Date:

Sho...

1,095.40

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMA 61 P)

\$ 8,180.82

| | | |
|----|-------|--------------------------------------|
| 25 | 1 pc | rear bumper center step garnish |
| 26 | 1 pc | rear bumper beam |
| 27 | 2 pcs | rear bumper bracket 1 @ 42.40 |
| 28 | 2 pcs | rear bumper reflector 1 @ 91.00 |
| 29 | 2 pcs | rear bumper side retainer 1 @ 26.00 |
| 30 | 1 pc | rear bumper lower cover 1 @ 223.50 |
| 31 | 1 pc | rear bumper tow cover |
| 32 | 1 pc | n/s rear fender 1160 |
| 33 | 1 pc | rear fender inner garnish 1 @ 327.40 |
| 34 | 1 pc | n/s rear fender wheel arch garnish |
| 35 | 2 pcs | rear no plate lamp 1 @ 74.00 |
| 36 | 1 pc | rear end panel |
| 37 | 1 pc | rear end panel inner garnish |
| 38 | 1 pc | rear spare tyre board |
| 39 | 1 pc | rear spare tyre panel |

| | | | |
|-----|-----|-----------|---|
| \$ | Bu | 280.00 | ✓ |
| \$ | n | 240.40 | X |
| \$ | n | 84.80 | X |
| \$ | sn | 182.00 | X |
| n/s | n/s | 52.00 | ✓ |
| \$ | mit | 447.00 | ✓ |
| \$ | mit | 16.50 | ✓ |
| \$ | Bu | 1,360.50 | ✓ |
| n/s | sn | 654.80 | ✓ |
| \$ | sn | 168.00 | X |
| n/s | sn | 148.00 | X |
| \$ | Bu | 385.00 | ✓ |
| n/s | sn | 181.80 | ✓ |
| \$ | sn | 665.80 | X |
| \$ | n | 896.00 | X |
| \$ | | 13,943.42 | |
| \$ | | 2,788.68 | |
| \$ | | 11,154.74 | |

Less 20 %

| | | |
|----|-------|---------------------|
| 40 | 1 pc | rear camera |
| 41 | 1 pc | rear no. plate |
| 42 | 1 set | rear reverse sensor |
| 43 | 1 pc | rear end panel seal |

| | | | | |
|----|-----|-----------|----|-------|
| \$ | mit | 485.00 | sn | ✓ |
| \$ | sn | 100.00 | sn | X |
| \$ | sn | 350.00 | sn | 200sn |
| \$ | sn | 250.00 | sn | 300sn |
| \$ | | 12,339.74 | | |

| |
|--|
| Labour charges |
| To putty and spray painting |
| Re-seal anti rust |
| To check wiring |
| Remove and refix rear windscreen glass |
| Remove and refix rear reverse sensor |
| Remove and refix cushion seat , garnish , carpet , etc |

| | | |
|----|-----------|-------|
| \$ | 2,000.00 | 1200d |
| \$ | 1,800.00 | 1000d |
| \$ | 200.00 | 90d |
| \$ | 120.00 | 20d |
| \$ | 160.00 | 120d |
| \$ | 120.00 | 50d |
| \$ | 180.00 | 100d |
| \$ | 16,919.74 | |
| \$ | 1,184.38 | |
| \$ | 18,104.12 | |

Plus : 7% GST
Grand total

17619.42

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 31 / 10 / 2019

RE : Supplementary

Mr Eyu Siew Hwa

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SMA 61 P - Subaru XV 2.0

Accident date : 29 / 10 / 2019

| Quantity | Descriptions | Amount (S\$) | |
|------------------|----------------------------------|----------------------|---|
| 1 1 pc | no. plate garnish | \$ <i>way</i> 250.00 | ✓ |
| 2 1 pc | in car camera (rear) | <i>repair</i> 485.00 | X |
| 3 <i>1</i> 2 pcs | tail gate side garnish 1 @ 32.50 | <i>1567</i> \$ 65.00 | ✓ |
| 4 <i>1</i> 2 pcs | tail lamp side clips 1 @ 4.50 | <i>1567</i> \$ 9.00 | ✓ |
| | | \$ 809.00 | |
| | Less 20 % | \$ 161.80 | |
| | | \$ 647.20 | |

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 30 / 10 / 2019

RE : Supplementary

Mr Eyu Siew Hwa

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SMA 61 P - Subaru XV 2.0

Accident date : 29 / 10 / 2019

| Quantity | Descriptions | Amount (S\$) |
|----------|--|--------------------------------|
| 1 2 pcs | boot lid inner trim side garnish 1 @ 32.80 | <i>21.56</i> \$ 65.60 <i>4</i> |
| | | \$ 65.60 |
| | Less 20 % | \$ 13.12 |
| | | \$ 52.48 |

17794.34

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 29 Oct 2019 | | 30 Oct 2019 14:59 Edit Adj Rpt | S\$7,900.00 Edit Estimates | S\$7,900.00 View Rpt | | Pending for Survey Report Cancel Case |




































| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|--|--------------------------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | [Created by insurer] | | | | | | |
| Insured: -, Co. Reg. No.: - | | | | | | | | | |
| Main Claimant: EYU SIEW HWA , ID: S1486292G | | | | | | | | | |
| Vehicle Reg. No.: SMA61P | | Date of Loss: 29/10/2019 08:00 - :59 [18 Months and 12 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / SNM19D205085C02 | | Policy/Cover Note No.: DMB1SN15285319044 | | | | | | | |
| Vehicle Reg. No. (Insured): CB7411E | | Policy No. (Claimant): 1800041126-01 | | | | | | | |
| | | Excess: S\$0.00 | | | | | | | |
| Repairer: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City, 575722 Sin Ming - Tel: 64570678 | | | | | | | | | |
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193] | | | | | | | | | |
| Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/11/2019] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | View All Compose Case Mail | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS <input type="checkbox"/> | | | View All Search Tasks Create New Task Complete | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SMA61P (SNM19D205085C02)
[CB7411E]
TP
EYU SIEW HWA
Oct 29 2019 8:00AM
[-]
H C Auto Pte Ltd

Upload Documents | Upload Photos | Compose New Letter











View View in Browser ▼

| Photos/Images | | | 3 per page ▼ | ✓ |
|---------------|-----------------|-----------------------------------|--|-------|
| No. | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 2 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 3 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 4 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 5 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 6 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 7 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 8 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 9 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 10 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 11 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 12 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 13 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 14 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 15 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 16 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 17 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 18 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 19 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 20 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 21 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 22 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 23 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 24 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 25 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 26 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 27 | 14/02/20 16:21 | General View |  Load JPG | ✓ |
| 28 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 29 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 30 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 31 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 32 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 33 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 34 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |
| 35 | 14/02/20 16:28 | Reinspection Photo |  Load JPG | ✓ |

| Photos/Images | | | 3 per page ▼ | ✓ |
|---------------|-----------------|-----------------------------------|--------------|-------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 36 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 37 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 38 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 39 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 40 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 41 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 42 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 43 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 44 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 45 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 46 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 47 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 48 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 49 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 50 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 51 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 52 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 53 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 54 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 55 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 56 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 57 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 58 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 59 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 60 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 61 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 62 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 63 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 64 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 65 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| 66 | 14/02/20 16:28 | Reinspection Photo | Load JPG | ✓ |
| Documentation | | | 1 per page ▼ | ✓ |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 17/02/20 15:57 | SUPPLEMENTARY | Load PDF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page ▼ | ✓ |
|--------------------|----------------|--|--------------|-------|
| No | Finalized On | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail | Print |
| 1 | 06/12/19 19:11 | Accident Statement | Load HTM | |
| 2 | 06/12/19 19:17 | Accident Statement | Load HTM | |
| 3 | 06/12/19 19:17 | Accident Statement | Load HTM | |
| 4 | 06/12/19 19:18 | Accident Statement | Load HTM | |
| Photos/Images | | | 3 per page ▼ | ✓ |
| No | Finalized On | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail | Print |
| 1 | 30/10/19 12:03 | Accident Photo | Load JPG | ✓ |
| 2 | 30/10/19 12:03 | Accident Photo | Load JPG | ✓ |

| Assessment Reports | | | 1 per page ▼ | ✓ |
|--------------------|----------------|--|--|-------|
| No | Finalized On | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail | Print |
| 3 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 4 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 5 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 6 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 7 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 8 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 9 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 10 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 11 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |
| 12 | 30/10/19 12:03 | Accident Photo |  Load JPG | ✓ |

| Documentation | | | 1 per page ▼ | ✓ |
|---------------|----------------|--|--|-------|
| No | Finalized On | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail | Print |
| 1 | 30/10/19 12:03 | Sketch Plan Sketch Plan |  Load TIF | |
| 2 | 30/10/19 12:04 | Police Report |  Load TIF | |
| 3 | 30/10/19 12:04 | Certificate of Insurance |  Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119019124/KTF3S2
Date: 17/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN15285319044
Claimant Vehicle No: SMA61P Insured Vehicle No: CB7411E
Date of Loss: 29/10/2019 Nature of Claim: TP Claim No: SNM19D205085C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA61P
Make & Model: SUBARU XV, 2.0 (A) Engine No: FB20YC58266
Reg. Date: 17/04/2018 (Man. Year: 2017) Chassis No: JF1GT7KL5JG029915
Colour: Metallic Dark Blue Odometer: 30206 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 13,039.42 | 7,341.74 | 5,697.68 | 43.70 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,580.00 | 2,580.00 | 2,000.00 | 43.67 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 17,619.42 | 9,921.74 | 7,697.68 | 43.69 |
| Approved Total (Overridden) (S\$) | | 7,900.00 | | |
| (S\$) | 17,619.42 | 7,900.00 | 9,719.42 | 55.16 |
| + GST 7.00/7.00% (S\$) | 1,233.36 | 553.00 | 680.36 | 55.16 |
| Nett Amount (S\$) | 18,852.78 | 8,453.00 | 10,399.78 | 55.16 |

INSPECTION

Date of Assignment: 30/10/2019
Date Inspected: 30/10/2019 Inspected At: H C Auto Pte Ltd (HQ)
160 Sin Ming Drive, #05-09 Sin Ming Auto City
Singapore 575722
Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 17 Feb 2020) |
| Parts: | M1-SUV | SUBARU XV 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMA61P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------------------------|-------------|--------------|
| 1 | 1 | | *REAR WINDSCREEN GLASS | Shattered | 1,095.40 FL | *1,095.40 FL |
| 2 | 1 | | *REAR WINDSCREEN GLASS MOULDING | No such part | 165.00 FL | *- FL |
| 3 | 1 | | *BOOT LID | Bent | 1,276.40 FL | *1,102.00 FL |
| 4 | 1 | | *BOOT LID INNER LOCK | Repair | 276.40 FL | *- FL |
| 5 | 2 | | *BOOT LID SIDE GARNISH | Serviceable | 145.00 FL | *- FL |
| 6 | 1 | | *BOOT LID SUBARU LOGO | Necessary | 68.40 FL | *68.40 FL |
| 7 | 1 | | *BOOT LID SUBARU EMBLEM | Necessary | 85.80 FL | *85.80 FL |
| 8 | 1 | | *BOOT LID XV EMBLEM | Necessary | 32.90 FL | *32.90 FL |
| 9 | 1 | | *BOOT LID AWD EMBLEM | Necessary | 85.42 FL | *85.42 FL |
| 10 | 1 | | *BOOT LID EYE SIGHT EMBLEM | Necessary | 96.80 FL | *96.80 FL |
| 11 | 1 | | *BOOT LID INNER TRIM | Buckled | 393.30 FL | *393.30 FL |
| 12 | 2 | | *BOOT LID ABSORBER | Serviceable | 361.60 FL | *- FL |
| 13 | 1 | | *BOOT LID WIPER ARM | Serviceable | 79.80 FL | *- FL |
| 14 | 1 | | *BOOT LID WIPER MOTOR | Jammed | 404.00 FL | *404.00 FL |
| 15 | 1 | | *BOOT LID WIPER BLADE | Serviceable | 26.00 FL | *- FL |
| 16 | 1 | | *BOOT LID LAMP | N/s Cracked | 617.60 FL | *308.80 FL |
| 17 | 2 | | *BOOT LID HINGE | Repair | 88.00 FL | *- FL |
| 18 | 1 | | *REAR WEATHER STRIP | Dented | 116.00 FL | *116.00 FL |
| 19 | 1 | | *TAIL LAMP | N/s Cracked | 1,164.80 FL | *512.00 FL |
| 20 | 1 | | *TAIL LAMP PANEL | N/s Bent | 300.20 FL | *150.10 FL |
| 21 | 1 | | *TAIL LAMP LOWER BRACKET | N/s Distorted | 21.00 FL | *10.50 FL |
| 22 | 1 | | *TAIL LAMP LOWER CLIP | N/s Necessary | 7.00 FL | *3.50 FL |
| 23 | 1 | | *REAR BUMPER FASCIA | Cracked | 894.00 FL | *601.50 FL |
| 24 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 380.00 FL | *223.00 FL |
| 25 | 1 | | *REAR BUMPER CENTER STEP GARNISH | Buckled | 280.00 FL | *280.00 FL |
| 26 | 1 | | *REAR BUMPER BEAM | Repair | 240.40 FL | *- FL |
| 27 | 2 | | *REAR BUMPER BRACKET | Repair | 84.80 FL | *- FL |
| 28 | 2 | | *REAR BUMPER REFLECTOR | Serviceable | 182.00 FL | *- FL |
| 29 | 1 | | *REAR BUMPER SIDE RETAINER | N/s Distorted | 52.00 FL | *26.00 FL |
| 30 | 2 | | *REAR BUMPER LOWER COVER | Missing 1pc Only | 447.00 FL | *223.50 FL |
| 31 | 1 | | *REAR BUMPER TOW COVER | Missing | 16.50 FL | *16.50 FL |
| 32 | 1 | | *N/S REAR FENDER | Buckled | 1,360.50 FL | *1,160.00 FL |
| 33 | 1 | | *REAR FENDER INNER GARNISH | N/s Cut | 654.80 FL | *327.40 FL |
| 34 | 1 | | *N/S REAR FENDER WHEEL ARCH GARNISH | Serviceable | 168.00 FL | *- FL |
| 35 | 1 | | *REAR NO PLATE LAMP | N/s Cracked / O/s Serviceable | 148.00 FL | *74.00 FL |
| 36 | 1 | | *REAR END PANEL | Bent | 385.00 FL | *385.00 FL |
| 37 | 1 | | *REAR END PANEL INNER GARNISH | Mtg Cracked | 181.80 FL | *181.80 FL |
| 38 | 1 | | *REAR SPARE TYRE BOARD | Serviceable | 665.80 FL | *- FL |
| 39 | 1 | | *REAR SPARE TYRE PANEL | Repair | 896.00 FL | *- FL |
| 40 | 1 | | *REAR CAMERA | Missing | 485.00 FS | *485.00 FS |
| 41 | 1 | | *REAR NO. PLATE | Serviceable | 100.00 FS | *- FS |
| 42 | 1 | | *SET REAR REVERSE SENSOR | Torn | 350.00 FS | *200.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|------------|------------|
| 43 | 1 | | *REAR END PANEL SEAL | Necessary | 250.00 FS | *30.00 FS |
| 44 | 1 | | *NO. PLATE GARNISH | Warped | 250.00 FL | *250.00 FL |
| 45 | 1 | | *IN CAR CAMERA (REAR) | Repeated | 485.00 FL | *- FL |
| 46 | 1 | | *TAIL GATE SIDE GARNISH | N/s Cut | 65.00 FL | *32.50 FL |
| 47 | 1 | | *TAIL LAMP SIDE CLIPS | N/s Necessary | 9.00 FL | *4.50 FL |
| 48 | 1 | | *BOOT LID INNER TRIM SIDE GARNISH | N/s Cut | 65.60 FL | *32.80 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (S\$) | 16,003.02 | 8,998.42 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 2,963.60 | 1,656.68 |
| Total Parts (S\$) | 13,039.42 | 7,341.74 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES. | New | 2,000.00 | 1,200.00 |
| 2 | TO PUTTY AND SPRAY PAINTING. | New | 1,800.00 | 1,000.00 |
| 3 | RE-SEAL ANTI RUST. | New | 200.00 | 90.00 |
| 4 | TO CHECK WIRING. | New | 120.00 | 20.00 |
| 5 | REMOVE AND REFIX REAR WINDSCREEN GLASS. | New | 160.00 | 120.00 |
| 6 | REMOVE AND REFIX REAR REVERSE SENSOR. | New | 120.00 | 50.00 |
| 7 | REMOVE AND REFIX CUSHION SEAT, GARNISH, CARPET, ETC. | New | 180.00 | 100.00 |
| Gross Labour Cost (S\$) | | | 4,580.00 | 2,580.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >