

REPAIR ESTIMATE*

VEHICLE NO : SH 8963B

DATE 29/10/2019

MAKE :

LKK - Calvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			S 553.00
	Rear Bumper Clip 10 pcs <i>X 22</i>			S 22.00
	SUB TOTAL			S 575.00
	LESS 20%			S 115.00
	DISCOUNTED TOTAL			S 460.00
	Rear Bumper Rubber Mat <i>X 22</i>			S 50.00
	Labour Charge			S 50.00
	Panel Beating			S 350.00
	Spray Painting Charge			S 250.00
	Wiring Charge			S 50.00
	Remove/Refix Reverse Sensor			S 80.00
	TOTAL LABOUR			S 730.00
	ESTIMATE TOTAL			S 1,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

200

100
S 350.00
S 250.00
S 50.00
S 80.00

Nett

1/Calvin LKK

29/10/19

1300h

2 days

2/3

After Repair photo

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.