

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 21 Oct 2020

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : GBD3403G | Accident Date | : 23/10/2019 |
| TP Vehicle No | : SKC230G | Assignment Date | : 30/10/2019 |
| Make | : HONDA ACCORD | Est. Duration of Repair | : 5 |
| Date of Inspection | : 30/10/2019 | | |
| Inspection At | : TK MOTOR WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6 #02-56, AUTOBAY @ KAKI BT SINGAPORE 417883 | | |

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,086.20 |
| Revised Amount | :S\$ | 6,404.51 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 6,404.51 |
| Lump Sum Repair | :S\$ | 5,100.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SURVEY ON WP