

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO : 53049097L

DATE: 26/11/2019

THAN QING SHUI JOHNSON
BLK 113D MCNAIR RD #25-246
SINGAPORE 325113

DEAR SIR

ACCIDENT DATE: 23/10/2019

ESTIMATE COST OF REPAIRS BILL TO TOYOTA LEXUS GS450H AUTO CAR NO: SKC230G

1 PC FRONT L/H FENDER <i>Dented</i>	S\$	988.20	988.20 ✓
1 PC FRONT L/H FENDER MOULDING <i>3 new</i>		161.10	161.10 x
5 PC FRONT L/H FENDER MOULDING CLIP <i>3 new</i>		19.50	19.50 x
1 PC FRONT BUMPER <i>torn</i>		684.90	684.90 ✓
1 PC FRONT BUMPER L/H SIDE RETAINER <i>new</i>		35.60	35.60 ✓
8 PC FRONT BUMPER CLIP <i>3 new</i>		30.40	30.40 ✓
2 PC FRONT BUMPER SIDE CLIP <i>3 new</i>		25.60	25.60 ✓
1 PC FRONT L/H HID HEADLAMP <i>3 new</i>		2,875.40	2,875.40 ✓ 1715
1 PC FRONT L/H SIDE MIRROR <i>3 new</i>		1,214.20	1,214.20 ✓
1 PC FRONT L/H DOOR <i>3 new</i>		1,176.90	1,176.90 x
1 PC FRONT L/H DOOR LOWER MOULDING <i>3 new</i>		212.20	212.20 x
1 PC REAR L/H DOOR LOWER MOULDING <i>3 new</i>		212.20	212.20 x
1 PC Front L/H Wheel Rim		50.00	50.00 30
TO CHECK WRING		1100	1100 900
TO SPRAY PAINTING		600.00	600.00 500
TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.			
TOTAL S\$			<u>9,086.20</u> 1230

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 6404.51

L/S: 5.1K.

0.5 Days