

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5402E**AAD1910-191***Not Notarized
11 Sep @ 2800h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

29 OCT 2019

SHC 5402E

VF1ABL15AUC279583

RENAULT

LATITUDE

24.10.19

AIG

4/11/2014

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>B1</i>	561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>Del/601</i>	411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>S_L</i>	98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>S_L</i>	82.10	X
5	1	BUMPER RETAINER RH REAR	\$	<i>S_L</i>	59.80	X
6	1	BUMPER REFLECTOR RH	\$	<i>S_L</i>	16.60	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>S_L</i>	80.80	X
8	1	BUMPER RETAINER LH REAR	\$	<i>Dir</i>	54.20	✓
9	1	BUMPER REFLECTOR LH	\$	<i>S_L</i>	16.60	X
10	1	BUMPER BEAM REAR	\$	<i>B1</i>	547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i>	114.50	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i>	100.90	✓
13	1	BUMPER BLOCK LH REAR	\$	<i>S_L</i>	75.70	X
14	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i>	745.80	✓
15	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>S_L</i>	404.56	✓
16	1	TAILLAMP RH	\$	<i>S_L</i>	313.10	✓
17	1	TAILLAMP PANEL RH	\$	<i>N</i>	401.40	✓
18	1	TAILLAMP LH	\$	<i>CHA</i>	401.40	✓
19	1	TAILLAMP PANEL LH	\$	<i>N</i>	401.40	X
20	1	BOOT REAR	\$	<i>N</i>	1,677.20	✓
21	1	BOOT FINISHER	\$	<i>S_L</i>	344.70	✓
22	1	BOOT WHEATERSTRIP	\$	<i>S_L</i>	178.20	✓
23	1	BOOT REFLECTOR LAMP LH	\$	<i>S_L</i>	277.70	✓
24	1	BOOT REFLECTOR LAMP RH	\$	<i>S_L</i>	277.70	X
25	1	BOOT BADGE 'RENAULT'	\$	<i>N_L</i>	82.40	✓
26	1	BOOT BADGE	\$	<i>N_L</i>	95.80	✓
27	1	BOOT STRUT LH	\$	<i>S_L</i>	145.10	✓
28	1	BOOT STRUT RH	\$	<i>S_L</i>	145.10	✓
29	1	BOOT HINGE LH	\$	<i>N</i>	254.20	✓

Trans-cab Auto Services Pte Ltd**AAD1910-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5402E

30	1	BOOT HINGE RH	\$	253.80	}	X	
31	2	BOOT RUBBER PLUG	\$	139.90			
32	2	BOOT BUFFER	\$	26.80			
33	1	BOOT LOCK LINKAGE	\$	20.60			
34	1	BOOT LOCK LINKAGE HOLDER	\$	99.50			
35	1	BOOT INNER TRIM BOARD	\$	611.00			
36	1	BOOT SWITCH	\$	113.00			
37	1	BOOT LOCK	\$	246.60			
38	1	BOOT LOCK CATCH	\$	41.70			
39	1	FENDER PANEL REAR LH	\$	1,933.20			
40	1	WHEELARCH REAR LH	\$	275.40	}		
41	1	FENDER PANEL INNER TRIM REAR LH	\$	671.45			
42	1	FUEL FLAP	\$	244.70			
43	1	AIR VENT	\$	59.40			
TOTAL			\$	13,103.51			
10%			\$	1,310.35			
			\$	11,793.16			

Special Nett

1	1SET	PARKING AID	\$	700.00	400.00	
2	1SET	REAR BUMPER CLIP	\$	66.00	—	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X	
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X	
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	—	
10	1	BOOT STICKER "Trans-cab"	\$	30.00	}	X
11	1	BOOT STICKER "6555-3333"	\$	30.00		
12	2	REAR WINDSCREEN SEALANT	\$	80.00		
13	1	WINDSCREEN MOULDING	\$	100.00		
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00		
15	1	BOOT INNER TRIM CLIP	\$	45.00	}	
16	1SET	BOOT FINISHER CLIP	\$	24.20		
17	1	TAILLAMP CLIP LH	\$	5.00	—	
18	1	TAILLAMP CLIP RH	\$	5.00	X	
19	1	Rear Bumper Protector	\$	100.00	40.00	
20	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	X	

Trans-cab Auto Services Pte Ltd**AAD1910-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5402E

21	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
22	1	REAR LEFT TYRE	\$	SL	300.00	X
23	1	REAR TYRE RIM COVER	\$	SL	50.00	X
24	1	REAR LEFT TYRE RIM	\$	SL	380.00	X
TOTAL			\$		2,259.20	

TOTAL PARTS	\$	14,052.36
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	Soi
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	5001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	L	170.00	X
To check steering geometry and computer wheel alignment	\$	L	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	L	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5402E

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *4401*

To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 14,510.00****Over All Total \$ 28,562.36****LUMP SUM (REPAIR DAY)**~~20 DAYS~~
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: