

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019163/EKA3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SG1725Z **Insured Vehicle No :** SJW2878G

Date of Loss: 21/10/2019 **Nature of Claim:** TP **Claim No:** 2331900712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG1725Z	Engine No:	50340782344086
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Chassis No:	WMAA22ZZ8F7002898
Reg. Date:	01/09/2016 (Man. Year: 2015)	Odometer:	208726 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,295.10	3,201.75	4,093.35	56.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,941.00	1,241.00	700.00	36.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,236.10	4,442.75	4,793.35	51.90
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	9,236.10	3,800.00	5,436.10	58.86
+ Loss of Use (3.0 x S\$250.00/day) (\$\$)		750.00		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		4,557.00		

INSPECTION

Date of Assignment: 29/10/2019

Date Inspected: 29/10/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	Broken	974.70 F	*974.70 FL
2	1		*HEADLAMP ,RH (MAN BUS)	Broken	1,603.60 F	*1,603.60 FL
3	1		*FLASHER AUX HEADLAMP ,RH (MAN BUS)	Broken	904.40 F	*904.40 FL
4	1		*RETAINER :MALE & FEMALE ,REAR LID ,MAN BUS	Bent	74.80 F	*74.80 FL
5	1		*FLAP ,FRONT :FOR MAN A22 BUS	Repair	1,868.80 F	*- FL
6	1		*BUMPER FRONT :CENTRE ,FOR MAN A22 BUS	Repair	1,868.80 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,295.10	3,557.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	355.75

Total Parts (\$\$)	7,295.10	3,201.75
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,325.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	616.00	446.00
Gross Labour Cost (\$\$)			1,941.00	1,241.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >