



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685592
Estimator Telephone Number 66662623
Accident Reporting Number 66662672

Date Generated : 29/10/2019

User ID : GohUK2

Section A - Accident Details	
Registration Number	SG1725Z
Case Reference Number	BUS/10/19/7032
Registration Date	1/9/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Hou Kai
Type of Accident	Side Swipe
Accident Date and Time	21/10/2019 4 30 PM
Accident Reported Date and Time	24/10/2019 10 02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1725Z - BUS RIGHT HEADLIGHT COVER CRACKED AND SCRATCHES ON THE BOTTOM OF THE FRONT RIGHT BUMPER SNW2878G (TP) - INSURED WITH AIG
Prepared Date and Time	29/10/2019 10 46 AM
Chassis Number	WMAA22Z28F7002898
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$2,561.40	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,561.40	\$0.00
Lump Sum Total	\$2,560.00	\$0.00
Number of Repair Days	4 0	
Prepared / Adjusted By	Kok Khoo Geh	
ARC / Surveyor Sign Off Date	29/10/2019 10 56 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve (LKK) ML ML
29/10/19, 2 00pm

3 dy
L/S
ML AL sy



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655922
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/10/2019

User ID : GohNG2

Part 1 - Labour Works									
Job Scope									
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS									
Total Labour									
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope									
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS									
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope									
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	Unit Price	Amount	Unit Price	Amount	Remarks
8010152	Body	F01001-CW266	COVER HEADLAMP-FRT RH.FOR MAN A22 BUS	1.00	\$674.70	10.00	\$677.23	Replace	✓ UR
8010306	VE	81 25101-8540	HEADLAMP RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	✓ UR
8010307	VE	81 25320-6112	FLASHER AUX HEADLAMP RH (MAN BUS)	1.00	\$804.40	10.00	\$813.96	Replace	✓ UR
8009375	VM		RETAINER MALE & FEMALE REAR LID MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	✓ RT
8010154	Body	F01001-CW263	FLAP FRONT FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	x R
8010151	Body	F01001-CE265	BUMPER FRONT CENTR E.FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	x R
Total						\$7,296.10		\$3,201.78	
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	Unit Price	Amount	Unit Price	Amount	Remarks
Total									

3291.75
- 20% L/S
2561.40
P+L = 1241
3802.40
= 3800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG1725Z
Case Reference Number	BUS/10/19/7032
Registration Date	1/9/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Hou Kai
Type of Accident	Side Swipe
Accident Date and Time	21/10/2019 4:30 PM
Accident Reported Date and Time	24/10/2019 10:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104053
Special Instruction to ARC, if any	SG1725Z - BUS RIGHT HEADLIGHT COVER CRACKED AND SCRATCHES ON THE BOTTOM OF THE FRONT RIGHT BUMPER. SJW2878G (TP) - INSURED WITH AIG
Prepared Date and Time	29/10/2019 10:46 AM
Chassis Number	WMAA22ZZ8F7002898
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$616.00	\$446.00
Total Spare Part Cost	\$2,561.40	\$2,561.40
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,502.40	\$3,802.40
Lump Sum Total	\$4,500.00	\$3,800.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoo Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	29/10/2019 10:56 AM	29/10/2019 2:26 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$795.00
Total Labour	\$1,325.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$446.00
Total Spray Painting & Panel Beating	\$616.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010152	Body	F01001-CW266	COVER, HEADLAMP, FRT, RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace
6009375	VM		RETAINER, MALE & FEMALE, REAR LID, MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	Replace
6010154	Body	F01001-CW263	FLAP, FRONT, FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
6010151	Body	F01001-CE265	BUMPER, FRONT, CENT RE, FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
Total					\$7,295.10		\$3,201.75		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									